

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

EQ INSURANCE COMPANY LTD

5 MAXWELL ROAD #17-00 TOWER BLOCK

MND COMPLEX SINGAPORE 069110 INV No. AC2201700

INV Date 28/03/2022

Reference CS/EQI22001776/Evf3n2

Code **EQI**

PROFESSIONAL SERVICE FEE

Vehicle No. SJE 19C

Insured Veh. GBK 8356P

Claim No. DM22HO00276/MT

Policy No.

Accident Date 22/02/2022

Inspection Date 08/03/2022

Description	Total
Survey Inspection	160.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	160.00
GST (7%)	11.20
Grand Total	171.20

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

	Affiliated to Federation Internationale Des Experts En Automobile						
	EQ INSURANCE C	OMPANY LTD	F	Ref:	CS/EQI22001776/Evf3n2		
	5 MAXWELL ROAI #17-00 TOWER BL MND COMPLEXSI		Γ	Date:	28/03/2022		
			C	Code:	EQI		
1.		Policy Particulars	- THIRD PARTY	CLAIM			
	Insured Veh.	GBK 8356P	Veh. Inspected		SJE 19C		
	Policy No.		Coverage (\$)		0.00		
	Claim No.	DM22HO00276/MT	Excess (\$)		0.00		
	Assign From	MELODY TEOH	Assign Date		24/02/2022		
2.		Vehicle Partic	ulars & Conditio	n			
	Make & Model	MERCEDES BENZ CLA180	c.c		1595		
	Engine No.	HIDDEN	Year of Reg.		2015		
	Chassis No.	WDD1173422N246847	Colour		BLACK		
	Odometer	48942 KM	Steering		IN ORDER		
	Brakes	IN ORDER	Modification		SPORTS RIM		
	General	GOOD					
3.	3. Conditions of Tyres						
		Size	Make		Balance		
	R/H Front Tyre	225/40 R18	BRIDGESTONE		5 mm		
	L/H Front Tyre	225/40 R18	BRIDGESTONE		5 mm		
	R/H Rear Tyre	225/40 R18	BRIDGESTONE		5 mm		
	L/H Rear Tyre	225/40 R18	BRIDGESTONE		5 mm		
4.	Description of Damages						
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.						
	DAMAGES SEE DI	ETAILS.					
5.		General	Information				
	Accident Date	22/02/2022	Inspection Date		08/03/2022		
	Survey held at	CYCLE & CARRIAGE INDUSTR	IES PL				
		188 PANDAN LOOP SINGAPORE 128378 (MERCEDES-BENZ)					
5a.		Re	emarks				
		ON WAS CONDUCTED ON A"WIT CE TO YOUR INSTRUCTIONS, W					
5b.	,	·	Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days						
					 		



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJE 19C

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER (SN)	CRUSHED	1,431.91	1,431.91
1	FRONT BUMPER COMPANY SIGN (SN)	NOT NECESSARY	63.99	-
1	SPACER RING (SN)	NECESSARY	6.97	6.97
1	RH/FRONT BUMPER LOWER GRILLE (SN)	NOT NECESSARY	49.10	-
1	RH/HEADLAMP (SN)	NOT NECESSARY	2,646.06	-
1	CTR/BASIC MOUNTING FOR BUMPER (SN)(ADDITONAL)	BROKEN	182.08	182.08
1	FRONT IMPACT ABSORBER (SN)(ADDITONAL)	BROKEN	166.31	166.31
1	FRONT DISTANCE SENSOR (SN)(ADDITONAL)	BROKEN	191.59	191.59
			4,738.01	1,978.86
	<u>LABOUR</u>			
	DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.		1,920.00	960.00
	RESPRAY FRONT BUMPER & RH/FRONT FENDER.		1,800.00	800.00
	USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD.		380.00	380.00
	TO REMOVE,REPLACE HEADLAMP WITH FOCUS.		120.00	120.00
			4,220.00	2,260.00
	GRAND TOTAL		8,958.01	4,238.86

RECOMMENDED COST OF REPAIRS			4,238.86
-----------------------------	--	--	----------

Report Ref No. CS/EQI22001776/Evf3n2

CHEN TSUE YEE

Automotive Assessor

X.2.

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate 5. Intribution provided must be as truthful and accurate as possible. Any white misteries entailed of withouting of material facts may allow insurance companies to reputing policy liability.
 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
 5. Any false reporting may be referred to the Police for investigation.
 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving

- and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 22/02/2022 16:31 (SGT) Date of Accident 22/02/2022 12:00 (SGT) Exact Location of Accident Singapore Additional Location Information STAR VISTA Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SJE19C

Manufacturer

INSURED/POLICYHOLDER

Is company? Name Of Registered Owner LEE WENDY H. NRIC No S8727252D Email Address WENDY.TINGX@GMAIL.COM Mobile Phone No (Phone) +65-91916140 Alternative Phone No +65-91916140

VEHICLE PARTICULARS

Mercedes Model Cla180 Variant Exact purpose for which vehicle was being used at time of accident Are you claiming under your own insurance policy for repair to No - Claiming third party your vehicle? Vehicle Category Private car Transmission CC 1595

INSURANCE COMPANY

Name of Insurance Company AIG Asia Pacific Insurance Pte. Ltd. Type of Coverage Comprehensive Fleet Policy Policy Number 2100426457-06 Cover Note Number

DRIVER

Name of Driver LEE WENDY H. NRIC No S8727252D

Date Of Birth Occupation Date Of Driving Pass Driving experience Gender Mobile Number Alt. Phone Number Email Address Address Address Address If No, Relationship of the Driver with the Insured Does Driver Own Other Vehicles? Vehicle Registration Number of Other Vehicle Owned by Driver	05/09/1987 Indoor 15/09/2006 15 YEARS AND 5 MONTHS Female (Phone) +65-91916140 +65-91916140 WENDY.TINGX@GMAIL.COM 1 WEST COAST WALK #01-02 - 127158 Yes - No
GENERAL INFORMATION OF THE ACCIDENT	
Type of Accident Weather Conditions Road Surface	Hit and run / Vandalism / Damaged whilst parked Clear Dry
OTHER INFORMATION	
Was any foreign vehicle involved in the accident? Number of vehicles involved in the accident Was anybody injured in the Accident? Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No 2 No - Yes 2 No
PASSENGER 1 Name Gender	ROLAND CAMPBELL Male
DETAILS OF POLICE ACTION	
Was the accident reported to the police? Was notice of intended Prosecution given? If yes, against whom?	No No -
CIRCUMSTANCES OF ACCIDENT	
REFER TO SKETCH PLAN.	
ATTACHMENT(S)	
Are accident photos available for attachment? Was there any video captured by Car Camera? Was there any audio recorded?	Yes No No
DETAILS OF OTHER	R VEHICLE PROPERTY 1
Vehicle Registration Number Vehicle Manufacturer Vehicle Model Vehicle Variant Vehicle Colour	GBK8356P - - - -

Commercial vehicle

Vehicle Category

Name of Driver	LOKE YUN LING
NRIC No	T0003746F
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	_



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJE 19C

INSPECTION
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJE 19C

RE-INSPECTION















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315







ESTIMATE FOR SJE19C

Cycle & Carriage Industries Pte Limited Authorised Dealer Company No. 196400367W GST Reg No. MR-8500111-X

EQ INSURANCE COMPANY LIMITED

MOTOR CLAIM DEPARTMENT 5 MAXWELL ROAD #17-00 TOWER BLOCK, MND COMPLEX SINGAPORE 069110 62239433

WIP No	55177
Reg No/Reg Date	SJE19C / 27/08/2015
Date In/Mileage	08/03/2022/- 48942
Chassis No	WDD1173422N246847
Engine No	27091030721540
Make/Model	MB/CLA 180 (C117) "URBAN"
Colour/Trim	021 191 Cosmos Blac/ 041 151-Leather Twi

Vehicle & Document Information

Account No	Terms	Date/Time Print	ed	CSE	Operator	
WE000058	Credit	10/03/2022/	14:50	K0	301 / Kerlyn Ong	
		Description	of Goods /	Services		Qty Unit Price Disc% Amount
X CTR/ BAS X FRONT IN X FRONT DI	SIC MOUNTIN MPACT ABSOR STANCE SEN	G FOR BUMPER BER SOR	2 BR	V ()	FFICIAL	$\begin{array}{c ccccccccccccccccccccccccccccccccccc$



SUPPLEMENTARY

Confirmed & accepted by

Nett 539.98 539.98

7% GST on

37.80

Total Payable

577.78

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

> Pandan Loop Service Center 188 Pandan Loop Singapore 128378 Tel: 6777 8388 Fax: 6779 5383 www.mercedes-benz.com.sg

