



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS3/LPC22000286/Eqf3e2-1 Date: 08/03/2022 Code: LPC2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	XD 3792Y	Veh. Inspected	GBF 4806K	
Policy No.		Coverage (\$)	0.00	
Claim No.	21/22/22/VC00/025341	Excess (\$)	0.00	
Assign From	GERALD POH	Assign Date	24/02/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA HIACE	c.c	2755	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JTFHT02P400210368	Colour	SILVER	
Odometer	133755 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	FAIR			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	195 R15C	DUNLOP	4 mm	
L/H Front Tyre	195 R15C	DUNLOP	4 mm	
R/H Rear Tyre	195 R15C	DUNLOP	4 mm	
L/H Rear Tyre	195 R15C	DUNLOP	4 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	07/01/2022	Inspection Date	18/01/2022	
Survey held at	7 SOON LEE STREET #01-39 iSPACE S627608			
Repairer	LYS ENGINEERING			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	