

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22001778/AQY3E2**Date:** 07/10/2022**REFERENCE**

Insured/Claimant: SHANKAR S/O NAGANAMBALAGARAN RAMASAMY Policy No: 7210032966
Date of Loss: 19/02/2022 Nature of Claim: OD Claim No: 3360065795SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMY9247K**
Make & Model: AUDI A6, 2.0 TFSI MU S-LINE (C6) (A) Engine No: DKY015277
Reg. Date: 30/03/2021 (Man. Year: 2021) Chassis No: WAUZZZF23MN054487
Colour: Grey Odometer: 17289 km
Engine Capacity: 1984 cc
Market Value/New Car Price: S\$215,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55R18 Rear Tyre Size: 225/55R18
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	116,461.20	72,874.00	43,587.20	37.43
Miscellaneous Items	0.00	0.00	0.00	
Labour	40,904.00	22,809.00	18,095.00	44.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	157,365.20	95,683.00	61,682.20	39.20
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	156,565.20	94,883.00	61,682.20	39.40
+ GST 7.00/7.00% (S\$)	10,959.56	6,641.81	4,317.75	39.40
Nett Amount (S\$)	167,524.76	101,524.81	65,999.95	39.40

INSPECTION

Date of Assignment: 24/02/2022
Date Inspected: 23/02/2022 Inspected At: 24 Benoi Sector Singapore 629857
Estimated Period of Repair: 25.0 days Repairer: Premium Automobiles Pte Ltd

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	3,012.00 FS	*2,409.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	659.00 FS	*- FS
3	1		*FRONT BUMPER CLOSING ELEMENT-CENTER	Torn	248.00 FS	*198.40 FS
4	2		*FRONT BUMPER ADAPTER-LH/RH	Distorted	88.00 FS	*70.24 FS
5	1		*FRONT BUMPER REINFORCEMENT-LH/RH	O/s Damaged	250.00 FS	*99.60 FS
6	1		*FRONT BUMPER GRILLE-LOWER CENTER	Deformed	171.00 FS	*136.40 FS
7	1		*FRONT BUMPER CLOSING ELEMENT-LOWER	Missing	235.00 FS	*187.60 FS
8	1		*FRONT BUMPER SPOILER	Cracked	282.00 FS	*225.20 FS
9	1		*FRONT BUMPER AIR GUIDE GRILLE-RH	Missing	485.00 FS	*387.60 FS
10	1		*FRONT BUMPER AIR GUIDE INNER-RH	Missing	33.00 FS	*25.84 FS
11	1		*FRONT BUMPER AIR GUIDE OUTER-RH	Missing	24.00 FS	*18.48 FS
12	1		*RADIATOR GRILLE	Cracked	2,460.00 FS	*1,968.00 FS
13	1		*RADIATOR GRILLE CENTER COVER	Not Necessary	61.00 FS	*- FS
14	1		*RADIATOR GRILLE COVER CAP	Not Necessary	55.00 FS	*- FS
15	1		*RADIATOR GRILLE BRACKET	Not Necessary	104.00 FS	*- FS
16	1		*RADIATOR GRILLE SECURING PLATE	Not Necessary	93.00 FS	*- FS
17	1		*FRONT CAMERA	Not Necessary	1,003.00 FS	*- FS
18	1		*FRONT BUMPER FOAM FILLER PIECE	Cracked	252.00 FS	*201.60 FS
19	1		*FRONT BUMPER REINFORCEMENT BEAM	Bent	1,076.00 FS	*860.80 FS
20	2		*FRONT BUMPER REINFORCEMENT BEAM SUPPORT-LH/RH	Necessary	67.00 FS	*53.60 FS
21	1		*FRONT BUMPER REINFORCEMENT BEAM SUPPORT BRACKET-RH	Damaged	61.00 FS	*48.32 FS
22	1		*FRONT BUMPER GUIDE SECTION-RH	Damaged	50.00 FS	*39.52 FS
23	1		*FRONT BUMPER TOP COVER	Deformed	140.00 FS	*112.00 FS
24	1		*FRONT BUMPER TOP COVER FOAM FILLER PIECE-RH	Missing	42.00 FS	*33.60 FS
25	1		*AIR COND STICKER	Necessary	34.00 FS	*26.96 FS
26	1		*OIL COMPLY STICKER	Necessary	34.00 FS	*27.20 FS
27	1		*PEDESTRIAN PROTECTION WARNING SIGN STICKER	Not Necessary	34.00 FS	*- FS
28	1		*HORN-RH	Damaged	154.00 FS	*123.20 FS
29	1		*HORN SUPPORT-RH	Bent	53.00 FS	*41.76 FS
30	1		*FRONT PARKING AID SENSOR (2 Pcs)	Damaged (1 Pc only)	488.00 FS	*195.20 FS
31	1		*FRONT PARKING AID SENSOR SIDE	Damaged	244.00 FS	*232.96 FS
32	1		*FRONT PARKING AID SENSOR SEAL RING (6 Pcs)	Necessary	15.00 FS	*12.00 FS
33	1		*FRONT BUMPER WARNING SET	Not Necessary	642.00 FS	*- FS
34	1		*BONNET	Distorted	5,846.00 FS	*4,676.80 FS
35	2		*BONNET HINGE-LH/RH	Bent	382.00 FS	*305.60 FS
36	1		*BONNET ATTACHMENT PARTS	Not Necessary	243.00 FS	*- FS
37	1		*BONNET ABSORBER (2PCS)	Damaged (1 Pc only)	256.00 FS	*204.80 FS
38	2		*BONNET IMPACT PROTECTION-LH/RH	Necessary	44.00 FS	*34.32 FS
39	1		*BONNET IMPACT PROTECTION-CENTER	Necessary	50.00 FS	*39.36 FS
40	1		*BONNET FLAP SOUND ABSORBER	Crumpled	353.00 FS	*282.40 FS
41	1		*BONNET STRIKER-RH	Bent	123.00 FS	*98.00 FS
42	1		*BONNET HINGE COVER-RH	Damaged	6.00 FS	*4.40 FS
43	1		*FRONT FENDER UPPER INNER COVER-RH	Distorted	36.00 FS	*28.48 FS
44	1		*HEADLIGHT COVER	Missing	49.00 FS	*38.64 FS
45	1		*BONNET SEAL-RH	Necessary	33.00 FS	*26.32 FS
46	1		*PLENUM CHAMBER COVER	Deformed	222.00 FS	*177.20 FS
47	1		*FRONT FENDER UPPER OUTER COVER-RH	Missing	40.00 FS	*31.44 FS
48	1		*BONNET LOCK MICRO-SWITCH	Damaged	239.00 FS	*190.80 FS
49	1		*BONNET BOWDEN CABLE-CENTER	Damaged	64.00 FS	*50.56 FS
50	1		*BONNET RELEASE ELEMENT	Damaged	65.00 FS	*51.44 FS
51	1		*BONNET RELEASE LEVER	Not Necessary	15.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	1		*BONNET LOCK CABLE	Not Necessary	82.00 FS	*- FS
53	1		*BONNET RELEASE CABLE COVER	Damaged	11.00 FS	*8.56 FS
54	1		*BONNET BRACKET	Not Necessary	51.00 FS	*- FS
55	1		*BONNET LOCK CABLE GRIP	Not Necessary	71.00 FS	*- FS
56	1		*FRONT FENDER-RH	Distorted	1,649.00 FS	*1,319.20 FS
57	1		*FRONT FENDER BRACE-RH	Distorted	137.00 FS	*109.60 FS
58	1		*FRONT FENDER BRACKET-RH UPPER	Distorted	49.00 FS	*38.64 FS
59	1		*FRONT FENDER CLOSING ELEMENT-RH	Distorted	60.00 FS	*47.28 FS
60	1		*FRONT FENDER ATTACHMENT PARTS	Damaged	44.00 FS	*35.20 FS
61	1		*FRONT WHEEL HOUSING LINER	Torn	299.00 FS	*238.80 FS
62	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Necessary	74.00 FS	*59.20 FS
63	1		*FRONT WHEEL SPOILER-RH	Distorted	185.00 FS	*147.60 FS
64	1		*FRONT WHEEL SPOILER STONE CHIP GUARD-RH	Necessary	57.00 FS	*45.28 FS
65	1		*FRONT WHEEL SPOILER TRIM BRACKET-RH	Damaged	45.00 FS	*35.36 FS
66	1		*HEADLIGHT MOUNTING-RH	Smashed	132.00 FS	*105.20 FS
67	1		*HEADLIGHT MATRIX BEAM-RH	Smashed	9,172.00 FS	*7,337.60 FS
68	1		*HEADLIGHT HOSE-RH	Not Necessary	33.00 FS	*- FS
69	1		*HEADLIGHT COVER CAP-RH	Not Necessary	65.00 FS	*- FS
70	2		*SPACER	Damaged	90.00 FS	*71.04 FS
71	1		*LIFT CYLINDER-RH	Smashed	217.00 FS	*173.60 FS
72	1		*LIFT CYLINDER BRACKET-RH	Smashed	7.00 FS	*5.44 FS
73	1		*LIFT CYLINDER ELBOW FITTING UPPER	Cracked	33.00 FS	*26.08 FS
74	1		*LIFT CYLINDER HOSE	Torn	204.00 FS	*162.80 FS
75	1		*LIFT CYLINDER-PIECE	Necessary	17.00 FS	*13.44 FS
76	1		*LIFT CYLINDER ELBOW FITTING LOWER	Necessary	29.00 FS	*22.48 FS
77	2		*LIFT CYLINDER COUPLING ELEMENT-STRAIGHT	Not Necessary	26.00 FS	*- FS
78	1		*LIFT CYLINDER CONNECTING PIECE-STRAIGHT	Not Necessary	16.00 FS	*- FS
79	1		*WATER RESERVOIR PUMP	Cracked	171.00 FS	*136.80 FS
80	1		*WASH WATER RESERVOIR	Deformed	208.00 FS	*166.40 FS
81	1		*WATER RESERVOIR WINDSCREEN WASHER SYSTEM PUMP	Not Necessary	137.00 FS	*- FS
82	1		*WATER RESERVOIR FUEL FILLER NECK	Deformed	202.00 FS	*161.60 FS
83	1		*WATER RESERVOIR STRAINER	Necessary	29.00 FS	*22.88 FS
84	1		*WATER RESERVOIR END CAP	Missing	20.00 FS	*15.44 FS
85	1		*LOCK CARRIER	Cracked	1,368.00 FS	*1,094.40 FS
86	1		*LOCK CARRIER SUPPORT-RH	Damaged	38.88 FS	*38.88 FS
87	1		*A/C CONDENSER	Warped	683.00 FS	*546.00 FS
88	1		*OUTSIDE TEMPERATURE SENSOR BRACKET	Necessary	26.00 FS	*20.40 FS
89	1		*EXTERNAL TEMPERATURE SENSOR	Not Necessary	64.00 FS	*- FS
90	1		*CHARGE AIR COOLER	Not Necessary	654.00 FS	*- FS
91	1		*CHARGE AIR COOLER PRESSURE HOSE-RH	Not Necessary	341.00 FS	*- FS
92	1		*RADIATOR	Leaking	1,010.00 FS	*808.00 FS
93	6		*RADIATOR COOLANT	Necessary	282.00 FS	*225.60 FS
94	1		*RADIATOR AIR GUIDE-RH	Torn	44.00 FS	*34.72 FS
95	1		*RADIATOR AIR GUIDE-UPPER	Cracked	34.00 FS	*27.04 FS
96	1		*RADIATOR AIR GUIDE-LOWER	Not Necessary	38.00 FS	*- FS
97	1		*INTAKE AIR DUCT LOWER	Cracked	51.00 FS	*40.08 FS
98	1		*INTAKE AIR DUCT UPPER	Cracked	92.00 FS	*73.52 FS
99	1		*AIR FILTER BOX	Cut	328.00 FS	*262.40 FS
100	1		*AIR MASS METER	Not Necessary	627.00 FS	*- FS
101	1		*INTAKE HOSE	Not Necessary	174.00 FS	*- FS
102	1		*FRONT FENDER TOP SUPPORT-RH UPPER	Buckled	291.00 FS	*232.80 FS
103	1		*FRONT FENDER TOP SUPPORT CLOSING ELEMENT-RH UPPER	Buckled	83.00 FS	*65.84 FS
104	1		*NOISE INSULATION PLATE-RH	Buckled	28.00 FS	*22.32 FS
105	1		*FRONT DOOR-RH	Repair	4,489.00 FS	*- FS
106	1		*FRONT DOOR OUTER SEAL-RH	Not Necessary	191.00 FS	*- FS
107	1		*FRONT DOOR ATTACHMENT PARTS	Not Necessary	379.00 FS	*- FS
108	1		*FRONT DOOR CATCH-RH	Not Necessary	0.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
109	1		*TYRE PRESSURE DATA PLATE	Not Necessary	34.00 FS	*- FS
110	1		*WINDSCREEN WATER DEFLECTOR STRIP-LH/RH	O/s Deformed	132.00 FS	*52.80 FS
111	1		*FRONT DOOR WINDOW SLOT SEAL TRIM STRIP-LH/RH OUTER	O/s Cut	448.00 FS	*178.80 FS
112	2		*FRONT DOOR WINDOW GUIDE TRIM STRIP-LH/RH	Not Necessary	574.00 FS	*- FS
113	1		*STEERING WHEEL AIRBAG UNIT	Activated	5,046.00 FS	*4,036.80 FS
114	1		*PASSENGER SIDE AIRBAG UNIT	Activated	4,341.00 FS	*3,472.80 FS
115	2		*HEAD AIRBAG UNIT-LH/RH	Activated	3,872.00 FS	*3,097.60 FS
116	1		*AIRBAG CONTROL UNIT	Activated	3,219.00 FS	*2,575.20 FS
117	2		*AIRBAG LOCK CARRIER CRASH SENSOR-LH/RH	Activated	764.00 FS	*716.48 FS
118	1		*FUSE UNIT	Activated	590.00 FS	*472.00 FS
119	2		*SEAT BELT-LH/RH	Activated	2,454.00 FS	*1,963.20 FS
120	2		*SEAT BELT HEIGHT ADJUSTER-LH/RH	Damaged	383.00 FS	*612.80 FS
121	1		*STEERING WHEEL	Cut	2,810.00 FS	*2,248.00 FS
122	1		*SEAT BELT DASHBOARD	Torn	7,693.00 FS	*6,154.40 FS
123	1		*ROOF LINER	Crumpled	2,896.00 FS	*2,316.80 FS
124	2		*FRONT GRAB HANDLE-LH/RH	Damaged	280.16 FS	*280.16 FS
125	2		*REAR GRAB HANDLE-LH/RH	Damaged	280.16 FS	*280.16 FS
126	2		*A-PILLAR TRIM-LH/RH	Deformed	502.00 FS	*401.60 FS
127	2		*B-PILLAR TRIM UPPER-LH/RH	Not Necessary	536.00 FS	*- FS
128	2		*C-PILLAR TRIM-LH/RH	Not Necessary	524.00 FS	*- FS
129	2		*D-PILLAR TRIM-LH/RH	Not Necessary	520.00 FS	*- FS
130	1		*FRONT ALUMINIUM RIM	Cut	1,847.00 FS	*1,477.60 FS
131	1		*FRONT RUBBER VALVE (4PCS)	Necessary(1Pc Only)	15.00 FS	*11.84 FS
132	1		*FRONT SUSPENSION SUBFRAME	Not Necessary	2,096.00 FS	*- FS
133	1		*FRONT SUSPENSION SUBFRAME CONSOLE	Not Necessary	622.00 FS	*- FS
134	1		*FRONT WISHBONE LINK-RH	Not Necessary	605.00 FS	*- FS
135	1		*WISHBONE SUSPENSION GUIDE	Not Necessary	1,057.00 FS	*- FS
136	2		*WISHBONE GUIDE UPPER RH-FRONT/REAR	Not Necessary	844.00 FS	*- FS
137	1		*WISHBONE WHEEL BEARING HOUSING-RH	Not Necessary	999.00 FS	*- FS
138	1		*WISHBONE SWIVEL JOINT	Not Necessary	153.00 FS	*- FS
139	1		*WISHBONE WHEEL HUB	Not Necessary	498.00 FS	*- FS
140	1		*WISHBONE FLANGE DOUBLE BALL BEARING	Not Necessary	273.00 FS	*- FS
141	1		*SUSPENSION FORKS-RH	Not Necessary	410.00 FS	*- FS
142	2		*COUPLING ROD	Not Necessary	258.00 FS	*- FS
143	1		*FRONT ANTI-ROLL BAR	Not Necessary	393.00 FS	*- FS
144	1		*GAS SHOCK ABSORBER	Not Necessary	1,366.00 FS	*- FS
145	1		*FRONT SPEED SENSOR	Not Necessary	129.00 FS	*- FS
146	1		*DRIVE SHAFT	Not Necessary	2,999.00 FS	*- FS
147	1		*TRACK ROD	Not Necessary	157.00 FS	*- FS
148	1		*TIE ROD END-RH	Not Necessary	217.00 FS	*- FS
149	1		*ENGINE UNDERSHIELD	Torn	709.00 FS	*567.20 FS
150	1		*FRONT WINDSCREEN	Cracked	1,875.00 FS	*1,500.00 FS
151	1		*GEL FOIL FOR RAIN SENSOR	Necessary	130.00 FS	*104.00 FS
152	1		*GLASS PRIMER	Necessary	22.00 FS	*17.36 FS
153	1		*FRONT WINDSCREEN SEALANT	Necessary	200.00 FS	*200.00 FS
154	1		*FRONT NO PLATE	Necessary	60.00 FS	*60.00 FS
155	1		*ARYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
156	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
157	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
158	1		*METAL FILLER POWDER	Necessary	280.00 FS	*280.00 FS
159	1		*RHS FRONT TYRE	Punctured	410.00 FS	*410.00 FS
160	1		*SUNDRIES	Necessary	600.00 FS	*485.84 FS
161	1		*HEADLIGHT MOUNTING-LH Supplementary	Cracked	132.00 FS	*105.20 FS
162	1		*REINFORCEMENT BEAM SUPPORT-LH Supplementary	Damaged	67.00 FS	*53.44 FS
163	1		*A-PILLAR BRACKET-RH Supplementary	Repair	99.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
164	1		*FRONT FENDER-LH Supplementary	Buckled	1,649.00 FS	*1,319.20 FS
165	1		*BONNET STRIKER-LH Supplementary	Bent	123.00 FS	*98.00 FS
166	1		*BONNET LOCK-LH Supplementary	Damaged	239.00 FS	*190.80 FS
167	1		*WATER RESERVOIR SEAL Supplementary	Necessary	66.00 FS	*52.40 FS
168	1		*MATRIX LED HEADLIGHT-LH Supplementary	Cut	9,172.00 FS	*7,337.60 FS
169	1		*RADIATOR AIR GUIDE-LH Supplementary	Torn	44.00 FS	*34.72 FS
170	1		*RADIATOR SUPPORT-LH Supplementary	Torn	25.00 FS	*20.00 FS
171	1		*POTENTIAL DISTRIBUTOR Supplementary	Cracked	471.00 FS	*376.40 FS
172	1		*WIRE BUTT CONNECTOR SET Supplementary	Necessary	228.00 FS	*182.40 FS
173	1		*HEADLIGHT WIRE CONNECTOR Supplementary	Cracked	18.00 FS	*13.84 FS
174	2		*SET SINGLE WIRE-1.2 Supplementary	Snapped	95.00 FS	*75.84 FS
175	2		*SET SINGLE WIRE Supplementary	Snapped	95.00 FS	*75.84 FS
176	1		*WIRE CONNECTOR-3 PIN YELLOW Supplementary	Damaged	26.00 FS	*20.08 FS
177	2		*SET SINGLE WIRE-2.8 Supplementary	Snapped	79.00 FS	*62.88 FS
178	2		*SET SINGLE WIRE-1.5 Supplementary	Snapped	95.00 FS	*37.92 FS
179	1		*WIRE CONNECTOR-3 PIN YELLOW Supplementary	Damaged	26.00 FS	*20.80 FS
180	1		*DOOR WIRING CONNECTOR-27 PIN Supplementary	Cracked	37.00 FS	*29.60 FS
181	1		*SET OF ADHENSIVE TAPES (2PCS)Supplementary	Necessary	128.00 FS	*102.24 FS
182	1		*SET ATTACHMENT PARTS FOR MEMBER TRIM (2PCS)Supplementary	Necessary	272.00 FS	*217.60 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 116,461.20 72,874.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	250.00
3	TO REMOVE AND RENEW AIRCON CONDENSER,CHARGE AIR COOLER AND RADIATOR.CHECK ELECTRICAL FANS AND CONTROL UNIT	New	1,700.00	1,700.00
4	TO CARRY OUT PRESSURISE,VACUUM AND REGAS FOR R1234	New	1,200.00	1,200.00
5	TO REMOVE AND RENEW RHS FRONT WHEEL SUSPENSION ASSY WITH SUBFRAME	New	2,800.00	0.00
6	TO CARRY OUT FIRST MEASUREMENT ON CAR O-LINER	New	800.00	800.00
7	TO SETUP THE VEHICLE CAR O-LINER TO FACILITATE THE REPAIR	New	2,400.00	2,400.00
8	TO REMOVE AND TRANSFER RHS FRONT DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	400.00	280.00
9	TO DISMANTLE LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY TO FACILITATE RESPRAYING OF LHS FRONT DOOR	New	280.00	0.00
10	TO REMOVE CENTER CONSOLE, INSTRUMENT PANELS AND CLUSTERS. RENEW DASHBOARD, BOTH FRONTAL AIRBAGS, SLIP RING. TRANSFER OLD FITTINGS. RENEW SEAL BELT AND CONTROL UNIT, PILLAR TRIMS, ROOF LINING AND BOTH CURTAIN AIR BAGS	New	3,600.00	3,600.00
11	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, BONNET, RHS FRONT DOOR AND RHS HEADLIGHT. TO CUT OUT AND WELD RHS FRONT FENDER TOP SUPPORT. TO REPAIR RHS FRONT WHEEL HOUSING TOP MOUNTING AND BOTH UPPER A-PILLAR. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	11,400.00	4,500.00
12	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER, BONNET, HINGES, RHS FRONT FENDER TOP SUPPORT, BOTH FRONT DOOR AND BOTH UPPER A-PILLAR	New	8,000.00	3,185.00
13	TO TOW BACK THE VEHICLE FROM THE ACCIDENT SCENE	New	280.00	0.00
14	TO DISMANTLE AND RENEW FRONT WINDSCREEN	New	480.00	480.00
15	TO APPLY FRONT WINDSCREEN SOLAR FILM	New	400.00	400.00
16	TO CARRY OUT WATER SEEPAGE TEST AFTER WINDSCREEN REPLACEMENT	New	200.00	150.00
17	TO RENEW RHS FRONT RIM WITH TYRE. TO CARRY OUT PRE/POST WHEEL ALIGNMENT	New	520.00	520.00
18	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK	New	384.00	384.00
19	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	250.00
20	Supplementary TO RENEW LHS FRONT FENDER	New	1,200.00	500.00
21	Supplementary TO CUT OUT AND WELD RHS A-PILLAR BRACKET	New	1,200.00	250.00
22	Supplementary TO RESPRAY LHS FRONT FENDER AND RHS A-PILLAR BRACKET	New	1,600.00	700.00
23	Supplementary TO RENEW POTENTIAL DISTRIBUTOR AND FRONTAL WIRING CONNECTOR.TO INSPECT.CHECK AND REPAIR WIRING HARNESS	New	780.00	780.00
Gross Labour Cost (\$)			40,904.00	22,809.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >