

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20010112/TGA3Q2-1
Date: 28/02/2022

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100391249
Claimant Vehicle No : SHD3072G **Insured Vehicle No :** SKQ1317K
Date of Loss: 20/09/2020 Nature of Claim: TP Claim No: 0770431433SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHD3072G**
Make & Model: HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A) Engine No: D4FDGU651412
Reg. Date: 16/06/2016 (Man. Year: 2016) Chassis No: KMHLB41UMGU091446
Colour: Blue Odometer: 314665 km
Engine Capacity: 1685 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
Front Left Side: West Lake 6 mm Rear Left Side: West Lake 6 mm
Front Right Side: West Lake 6 mm Rear Right Side: West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,575.36	1,952.16	623.20	24.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,110.00	880.00	230.00	20.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,685.36	2,832.16	853.20	23.15
Approved Total (Overridden) (S\$)		2,250.00		
(S\$)	3,685.36	2,250.00	1,435.36	38.95
+ GST 7.00/7.00% (S\$)	257.98	157.50	100.48	38.95
Nett Amount (S\$)	3,943.34	2,407.50	1,535.84	38.95
+ Car Rental (3.0 x S\$114.95/day) (S\$)		344.85		
(S\$)		2,752.35		
Liab Amount (50.00%) (S\$)		1,376.18		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,378.18		

INSPECTION

Date of Assignment: 21/09/2020
Date Inspected: 21/09/2020 Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang)
59 Loyang Drive
Singapore 508969
Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*HEADLAMP LH	Cut	1,388.00 FL	*1,388.00 FL	
2	1		*FRONT BUMPER SIDE BRACKET LH	Not Necessary	22.40 FL	*- FL	
3	1		*FRT FENDER LH	Repair	663.00 FL	*- FL	
4	1		*FRONT BUMPER ASSY	Deformed	1,052.20 FL	*1,052.20 FL	
5	1		*FRT BUMPER GRILLE LH	Not Necessary	93.60 FL	*- FL	
					Sub Total (S\$)	3,219.20	2,440.20
					- List Item Discount on L Items 20.00/20.00% (S\$)	643.84	488.04
					Total Parts (S\$)	2,575.36	1,952.16

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	540.00	420.00
2	SPRAY PAINTING CHARGE	New	450.00	400.00
3	CHECK WIRING	New	60.00	30.00
4	TUFF KOTE	New	60.00	30.00
Gross Labour Cost (\$\$)			1,110.00	880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >