

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22001792/APA3Q2**Date:** 08/12/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100179686
Claimant Vehicle No :	SMN5362U	Insured Vehicle No :	SJU4797D
Date of Loss:	12/01/2022	Nature of Claim:	TP
		Claim No:	9792061745SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMN5362U		
Make & Model:	HYUNDAI AD AVANTE, 1.6 GLS S (A)	Engine No:	G4FGKU152167
Reg. Date:	16/08/2019 (Man. Year: 2019)	Chassis No:	KMHD841CMKU915856
Colour:	Red	Odometer:	67732 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/55 R15	Rear Tyre Size:	195/55 R15
Front Left Side:	ATREZZO 6 mm	Rear Left Side:	ATREZZO 6 mm
Front Right Side:	ATREZZO 6 mm	Rear Right Side:	ATREZZO 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,186.72	886.00	2,300.72	72.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,530.00	740.00	1,790.00	70.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,716.72	1,626.00	4,090.72	71.56
Approved Total (Overridden) (S\$)		1,300.00		
(S\$)	5,716.72	1,300.00	4,416.72	77.26
+ GST 7.00/7.00% (S\$)	400.17	91.00	309.17	77.26
Nett Amount (S\$)	6,116.89	1,391.00	4,725.89	77.26
+ Loss of Use (3.0 x S\$60.00/day) (S\$)		180.00		
+ Doc/Search Fee (S\$)		29.00		
Nett Liability (S\$)		1,600.00		

INSPECTION

Date of Assignment:	23/02/2022	MG Solution Pte Ltd (HQ)
Date Inspected:	23/02/2022 Inspected At:	23 Kaki Bukit Avenue 4 #02-03B, VICOM
		Inspection Centre
		Singapore 415933
Estimated Period of Repair:	2.0 days	

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	630.00 FL	*485.00 FL
2	1		*REAR BUMPER LOWER LID	Not Necessary	420.00 FL	*- FL
3	2		*REAR BUMPER RETAINER	Necessary	124.80 FL	*35.00 FL
4	1		*REAR FENDER	Not Necessary	1,533.60 FL	*- FL
5	1		*SET REAR BUMPER CLIP	Necessary	20.00 FS	*20.00 FS
6	1		*SPORT RIM	Cut	1,000.00 FS	*450.00 FS
					Sub Total (\$\$)	3,728.40
					- List Item Discount on L Items 20.00/20.00% (\$\$)	541.68
					Total Parts (\$\$)	3,186.72

F=Franchise part. S=SpcNett. L=ListItemDisc.

990.00

104.00

886.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	1,000.00	200.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,000.00	400.00
3	TO APPLY RUST PROOFING AND TUFF COAT	New	250.00	30.00
4	WIRING CHECK	New	60.00	30.00
5	CONDUCT WATER LEAKAGE TEST	New	80.00	0.00
6	FOUR WHEEL ALIGNMENT	New	100.00	80.00
7	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	40.00	0.00
Gross Labour Cost (S\$)			2,530.00	740.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >