

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22001794/ANY3M4**Date:** 05/08/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNA00049442101

Claimant Vehicle No : SME8754A **Insured Vehicle No :** GBC9583K

Date of Loss: 22/02/2022 Nature of Claim: TP Claim No: SNM22D201341/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SME8754A**

Make & Model: TOYOTA LEXUS, 2.0 RX300 5DR SUV (AT) (2WD) EXECUTIVE (A) Engine No: 8ARW919907

Reg. Date: 22/10/2018 (Man. Year: 2018) Chassis No: JTJBAMCAX02060080

Colour: White Odometer: 56305 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55 R20 Rear Tyre Size: 235/55 R20

Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	22,318.90	13,113.90	9,205.00	41.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,025.00	2,110.00	4,915.00	69.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	29,343.90	15,223.90	14,120.00	48.12
+ GST 7.00/7.00% (S\$)	2,054.07	1,065.67	988.40	48.12
Nett Amount (S\$)	31,397.97	16,289.57	15,108.40	48.12

INSPECTION

Date of Assignment: 24/02/2022

Date Inspected: 24/02/2022 Inspected At: Sk Automobile Pte Ltd
8 Kaki Bukit Ave 4, #08-46 Premier @ Kaki Bukit
Singapore 415875

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 05 Aug 2022)

Parts: 143 TOYOTA LEXUS 2.0 RX300 5DR SUV (AT) (2WD) EXECUTIVE (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SME8754A)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Distorted	3,263.00 FL	*3,263.00 FL
2	1		*SET REAR TAILGATE WINDSCREEN MOLDING	Necessary	65.00 FL	*65.00 FL
3	1		*REAR TAILGATE LOGO EMBLEM	Cut	1,164.00 FL	*1,164.00 FL
4	1		*REAR TAILGATE LEXUS EMBLEM	Necessary	70.00 FL	*70.00 FL
5	1		*REAR TAILGATE RX300 EMBLEM	Necessary	80.00 FL	*80.00 FL
6	2		*REAR TAILGATE REFLECTOR LAMP LH/RH	Cracked	2,260.00 FL	*2,260.00 FL
7	1		*REAR TAILGATE OUTER GARNISH WITH CHROME MOLDING	Cracked	1,968.00 FL	*1,968.00 FL
8	2		*REAR TAILGATE NUMBER PLATE LAMP LH/RH	Not Necessary	566.00 FL	*- FL
9	1		*REAR TAILGATE OUTER LOCK HANDLE SWITCH	Not Necessary	188.00 FL	*- FL
10	1		*REAR TAILGATE REVERSE CAMERA (ORIGINAL)	Not Necessary	1,665.00 FL	*- FL
11	2		*REAR TAILGATE AUTO DAMPER LH/RH	Not Necessary	732.00 FL	*- FL
12	1		*REAR TAILGATE INNER TRIM BOARD	Not Necessary	602.00 FL	*- FL
13	1		*REAR TAILGATE MECHANISM LOCK WITH MOTOR	Damaged	1,006.00 FL	*1,006.00 FL
14	1		*REAR TAILGATE MECHANISM LOCK GARNISH	Cracked	57.00 FL	*57.00 FL
15	1		*REAR TAILGATE WEATHER STRIP	Not Necessary	458.00 FL	*- FL
16	2		*REAR TAILLAMP LH/RH	Not Necessary	2,092.00 FL	*- FL
17	2		*REAR TAILLAMP GARNISH LH/RH	Not Necessary	164.00 FL	*- FL
18	2		*REAR TAILLAMP LOWER BRACKET LH/RH	Not Necessary	180.00 FL	*- FL
19	2		*REAR FENDER ARCH GARNISH LH/RH	Not Necessary	230.00 FL	*- FL
20	1		*REAR BUMPER	Deformed	995.00 FL	*995.00 FL
21	2		*REAR BUMPER REVERSE SENSOR (4PCS)	Damaged (2Pieces Only)	1,952.00 FL	*976.00 FL
22	4		*REAR BUMPER REVERSE SENSOR HOLDER	Not Working	80.00 FL	*80.00 FL
23	1		*SET REAR BUMPER REVERSE SENSOR WIRE HARNESS	Not Necessary	118.00 FL	*- FL
24	1		*REAR BUMPER LOWER DIFFUSER	Deformed	361.00 FL	*361.00 FL
25	8		*REAR BUMPER LOWER DIFFUSER CLIPS	Necessary	64.00 FL	*30.00 FL
26	2		*REAR BUMPER LOWER DIFFUSER SIDE GARNISH LH/RH	Deformed	324.00 FL	*324.00 FL
27	2		*REAR BUMPER EXHAUST END CHROME PIPE LH/RH	Bent	650.00 FL	*650.00 FL
28	2		*REAR BUMPER SIDE RETAINER LH/RH	Necessary	302.00 FL	*302.00 FL
29	2		*REAR BUMPER LOWER CENTER BRACKET	Not Necessary	88.00 FL	*- FL
30	2		*REAR BUMPER LOWER SIDE BRACKET LH/RH	Not Necessary	404.00 FL	*- FL
31	1		*REAR BUMPER LOWER SIDE BRACKET LH	Not Necessary	202.00 FL	*- FL
32	1		*REAR BUMPER INNER SPONGE	Cracked	114.00 FL	*114.00 FL
33	1		*REAR BUMPER REINFORCEMENT	Bent	541.00 FL	*541.00 FL
34	1		*REAR END PANEL	Repair	926.00 FL	*- FL
35	1		*REAR END PANEL TAILGATE ANTENNA SENSOR	Not Necessary	75.00 FL	*- FL
36	1		*SET REAR TAILGATE WINDSCREEN SEALANT WITH PRIMER	Necessary	100.00 FS	*60.00 FS
37	1		*SET REAR TAILGATE OUTER GARNISH WITH CHROME MOLDING CLIPS	Necessary	60.00 FS	*30.00 FS
38	1		*SET REAR TAILGATE NUMBER PLATE WITH CASING	Bent	85.00 FS	*60.00 FS
39	1		*SET REAR TAILGATE INNER TRIM BOARD CLIPS	Not Necessary	80.00 FS	*- FS
40	2		*SET REAR FENDER ARCH GARNISH CLIPS LH/RH	Not Necessary	80.00 FS	*- FS
41	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
42	1		*REAR END PANEL SEALANT	Not Necessary	120.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*SET REAR END PANEL INNER TOP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
44	1		*REAR TAILGATE INNER HANDLE	Deformed	65.00 FL	*65.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	24,726.00	14,551.00
- List Item Discount on L Items 10.00/10.00% (\$)	2,407.10	1,437.10
Total Parts (\$)	22,318.90	13,113.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	New	1,800.00	600.00
2	TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA	New	1,800.00	800.00
3	TO APPLY ANTI-RUST & TUFF KOTE	New	140.00	60.00
4	TO PERFORM LIGHTING & WIRING CHECK	New	125.00	30.00
5	TO CALIBRATE CHASSIS & CAR BODY BACK TO MANUFACTURING SPECIFICATION	New	550.00	0.00
6	TO DISMANTLE & REINSTALL REAR WINDSCREEN PERFORM	New	150.00	120.00
7	TO PERFORM TRANSFER REAR TAILGATE MECHANISM & REALIGN BACK TO MANUFACTURING SPECIFICATION	New	380.00	0.00
8	TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR WITH DISTANCE SETTING	New	120.00	60.00
9	TO DISMANTLE & REPLACED REAR EXHAUST SILENCER BOX WITH REALIGN EXHAUST MID PIPE & RUBBER MOUNTING	New	180.00	0.00
10	TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR	New	480.00	60.00
11	PERFORM ADAR SYSTEM INTEGRATION FOR SPECIFIC CALIBRATION ROUTINES PERFORMED RADAR SENSOR BACK TO IDENTIFICATION STANDARD	New	800.00	380.00
12	TO PERFORM DIAGNOSTIC CHECK & RESET MEMORY FAULT CODE TO IDENTIFICATION STANDARD	New	380.00	0.00
13	TO PERFORM CONDUCT WATER LEAKAGE TEST OF ACCIDENT PORTION	New	120.00	0.00
Gross Labour Cost (\$\$)			7,025.00	2,110.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >