



AUTOBACS

SK Automobile Pte Ltd

A Subsidiary Of Autobacs Seven Co Ltd. Japan

8 Kaki Bukit Ave 4 #08-40/45/46 Premier@Kaki Bukit S(415875)

Tel : 6702 1555 Fax : 6702 1444 (Co Reg. No. 201500047H)

Email : wendykhoo@skauto.com.sg

TO	: CHINA TAIPING (GBC9583K)	DATE	: 23-Feb-22
ATTENTION	: MOTOR CLAIMS DEPARTMENT	JOB TYPE	: T/P CLAIMS
OWNER PARTICULAR			
OWNER ID	: SXXXX054J	<i>Hui Rong</i>	
VEHICLE DETAILS			
VEHICLE NO.	: SME8754A		
MODEL / MAKE	: LEXUS RX300		
CHASSIS NO.	: JTJBAMCAX02060080		
ACCIDENT DETAIL			
DATE	: 22-Feb-22		
TIME	: 17:37HRS	CONTACT PERSON	: MR. WINSON 91866680

QUOTATION SUMMARY

PAGE 01

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR TAILGATE <i>Distorted</i>	1	\$ 3,263.00	\$ 3,263.00
2	REAR TAILGATE WINDSCREEN MOLDING SET <i>new</i>	1	\$ 65.00	\$ 65.00
3	REAR TAILGATE LOGO EMBLEM <i>ut</i>	1	\$ 1,164.00	\$ 1,164.00
4	REAR TAILGATE LEXUS EMBLEM <i>3 new</i>	1	\$ 70.00	\$ 70.00
5	REAR TAILGATE RX300 EMBLEM <i>new</i>	1	\$ 80.00	\$ 80.00
6	REAR TAILGATE REFLECTOR LAMP LH/RH <i>new could</i>	2	\$ 1,130.00	\$ 2,260.00
7	REAR TAILGATE OUTER GARNISH WITH CHROME MOLDING <i>could</i>	1	\$ 1,968.00	\$ 1,968.00
8	REAR TAILGATE NUMBER PLATE LAMP LH/RH <i>new</i>	2	\$ 283.00	\$ 566.00
9	REAR TAILGATE OUTER LOCK HANDLE SWITCH <i>new</i>	1	\$ 188.00	\$ 188.00
10	REAR TAILGATE REVERSE CAMERA (ORIGINAL) <i>new</i>	1	\$ 1,665.00	\$ 1,665.00
11	REAR TAILGATE AUTO DAMPER LH/RH <i>new</i>	2	\$ 366.00	\$ 732.00
12	REAR TAILGATE INNER TRIM BOARD <i>new</i>	1	\$ 602.00	\$ 602.00
13	REAR TAILGATE MECHANISM LOCK WITH MOTOR <i>new</i>	1	\$ 1,006.00	\$ 1,006.00
14	REAR TAILGATE MECHANISM LOCK GARNISH <i>could</i>	1	\$ 57.00	\$ 57.00
15	REAR TAILGATE WEATHER STRIP <i>new</i>	1	\$ 458.00	\$ 458.00
16	REAR TAILLAMP LH/RH <i>new</i>	2	\$ 1,046.00	\$ 2,092.00
17	REAR TAILLAMP GARNISH LH/RH <i>new</i>	2	\$ 82.00	\$ 164.00
18	REAR TAILLAMP LOWER BRACKET LH/RH <i>new</i>	2	\$ 90.00	\$ 180.00
19	REAR FENDER ARCH GARNISH LH/RH <i>new</i>	2	\$ 115.00	\$ 230.00
20	REAR BUMPER <i>Deland</i>	1	\$ 995.00	\$ 995.00
21	REAR BUMPER REVERSE SENSOR <i>2 pieces damaged</i>	4	\$ 488.00	\$ 1,952.00
22	REAR BUMPER REVERSE SENSOR HOLDER <i>new</i>	4	\$ 20.00	\$ 80.00
23	REAR BUMPER REVERSE SENSOR WIRE HARNESS SET <i>new</i>	1	\$ 118.00	\$ 118.00
24	REAR BUMPER LOWER DIFFUSER <i>Deland</i>	1	\$ 361.00	\$ 361.00

2260.00

976

QUOTATION SUMMARY

PAGE 02

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
25	REAR BUMPER LOWER DIFFUSER CLIPS <i>new</i>	8	\$ 8.00	\$ 64.00 <i>30</i>
26	REAR BUMPER LOWER DIFFUSER SIDE GARNISH LH/RH <i>old</i>	2	\$ 162.00	\$ 324.00 <i>✓</i>
27	REAR BUMPER EXHAUST END CHROME PIPE LH/RH <i>New part</i>	2	\$ 325.00	\$ <u>650</u> <i>650.00</i> <i>✓</i>
28	REAR BUMPER SIDE RETAINER LH/RH <i>new</i>	2	\$ 151.00	\$ 302.00 <i>✓</i>
29	REAR BUMPER LOWER CENTER BRACKET <i>new</i>	2	\$ 44.00	\$ 88.00 <i>✓</i>
30	REAR BUMPER LOWER SIDE BRACKET LH/RH <i>3 M</i>	2	\$ 202.00	\$ 404.00 <i>✓</i>
31	REAR BUMPER LOWER SIDE BRACKET LH	1	\$ 202.00	\$ 202.00 <i>✓</i>
32	REAR BUMPER INNER SPONGE <i>could</i>	1	\$ 114.00	\$ 114.00 <i>✓</i>
33	REAR BUMPER REINFORCEMENT <i>Bent</i>	1	\$ 541.00	\$ 541.00 <i>✓</i>
34	REAR END PANEL <i>new</i>	1	\$ 926.00	\$ 926.00 <i>✓</i>
35	REAR END PANEL TAILGATE ANTENNA SENSOR <i>new</i>	1	\$ 75.00	\$ 75.00 <i>✓</i>
TOTAL PRICE				\$ 24,006.00
LESS -10%				\$ (2,400.60)
SUB TOTAL PRICE				\$ <u>21,605.40</u>

36. REAR TAILGATE INNER HANDLE # 65 *new*

TOTAL PRICE

\$ 24,006.00

LESS -10%

\$ (2,400.60)

SUB TOTAL PRICE

\$ 21,605.40

14306

12875.40

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR TAILGATE WINDSCREEN SEALANT WITH PRIMER SET <i>new</i>	1	\$ 100.00	\$ 100.00 <i>60</i>
2	REAR TAILGATE OUTER GARNISH WITH CHROME MOLDING CLIPS SET <i>new</i>	1	\$ 60.00	\$ 60.00 <i>30</i>
3	REAR TAILGATE NUMBER PLATE WITH CASING SET <i>Bent</i>	1	\$ 85.00	\$ 85.00 <i>60</i>
4	REAR TAILGATE INNER TRIM BOARD CLIPS SET <i>new</i>	1	\$ 80.00	\$ 80.00 <i>✓</i>
5	REAR FENDER ARCH GARNISH CLIPS SET LH/RH <i>new</i>	2	\$ 40.00	\$ 80.00 <i>✓</i>
6	REAR BUMPER CLIPS SET <i>new</i>	1	\$ 80.00	\$ 80.00 <i>30</i>
7	REAR END PANEL SEALANT <i>new</i>	1	\$ 120.00	\$ 120.00 <i>✓</i>
8	REAR END PANEL INNER TOP GARNISH CLIPS SET <i>new</i>	1	\$ 50.00	\$ 50.00 <i>✓</i>

TOTAL

180

\$ 655.00

APPROVED DETAILS

NO. OF REPAIR DAYS

:

DAYS

REPAIR UNDER

:

PART BY PART OR LUMP SUM

DATE / TIME OF SURVEY

:

SURVEYED BY / FROM

:

CONTACT NUMBER

:

EMAIL ADDRESS

DATE / TIME OF RE-SURVEY

EXCESS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Cj
 P/P L/S 24/02/22
 06 Days
 total: 15165.40.

QUOTATION SUMMARY

PAGE 03

CLAIMS DETAIL : LABOUR CHARGES AND SPRAY PAINTING

TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	\$ 1,800.00	\$300.00 @	600.
TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA	\$ 1,800.00	\$300.00 @	800
TO APPLY ANTI-RUST & TUFF KOTE	\$ 140.00	60.	
TO PERFORM LIGHTING & WIRING CHECK	\$ 125.00	30	
TO CALIBRATE CHASSIS & CAR BODY BACK TO MANUFACTURING SPECIFICATION	\$ 550.00	X	
TO DISMANTLE & REINSTALL REAR WINDSCREEN PERFORM	\$ 150.00	120.	
TO PERFORM TRANSFER REAR TAILGATE MECHANISM & REALIGN BACK TO MANUFACTURING SPECIFICATION	\$ 380.00	X.	
TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR WITH DISTANCE SETTING	\$ 120.00	60	
TO DISMANTLE & REPLACED REAR EXHAUST SILENCER BOX WITH REALIGN EXHAUST MID PIPE & RUBBER MOUNTING	\$ 180.00	X	
TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR	\$ 480.00	60	
PERFORM ADAR SYSTEM INTEGRATION FOR SPECIFIC CALIBRATION ROUTINES PERFORMED RADAR SENSOR BACK TO IDENTIFICATION STANDARD	\$ 800.00	380.	
TO PERFORM DIAGNOSTIC CHECK & RESET MEMORY FAULT CODE TO IDENTIFICATION STANDARD	\$ 380.00	X	
TO PERFORM CONDUCT WATER LEAKAGE TEST OF ACCIDENT PORTION	\$ 120.00	X	

TOTAL

\$ 7,025.00

2110

ESTIMATE REPORT

TOTAL PARTS COST	:	\$ 22,260.40
TOTAL LABOUR COST	:	\$ 7,025.00
TOTAL REPAIR COST	:	<u>\$ 29,285.40</u>



Repair Shop:
Phone Number:
Address:

Report Number: MAXIA20220305
Creation Date: 2022-03-05



12/2017-08/2019 Lexus Vehicle Diagnostic Report

License Plate: SME8754A

Manufacturer: Lexus

Year: 12/2017-08/2019

Model: RX300

Sub Model:

Engine: 8AR-FTS

Path: Lexus>Automatic selection>RX300>Europe/Others>AGL2#>8AR-FTS>Others>12/2017-08/2019>Radar cruise>Auto scan

Client:

Phone Number:

VIN: JTJBAMCAX02060080

Mileage: 56306 km

Color:

Status:

Overview

Modules Scanned:38

Modules with Faults:4

Total number of codes :8

System status report

System	DTC	Status
1. Engine	0	Pass No fault
2. Transmission	0	Pass No fault
3. ABS/VSC/TRC/EPB	0	Pass No fault
4. SRS airbag	0	Pass No fault
5. Combination meter	0	Pass No fault
6. Tire pressure monitor	0	Pass No fault
7. Main body	1	Fault
8. Driver door motor	0	Pass No fault
9. Sliding roof	0	Pass No fault
10. Left mirror	0	Pass No fault
11. Passenger seat	0	Pass No fault
12. Driver seat	0	Pass No fault
13. Right rear door motor	0	Pass No fault



Repair Shop:
Phone Number:
Address:

Report Number: MAXIA20220305
Creation Date: 2022-03-05



14. Left rear door motor	0	Pass No fault
15. Passenger door motor	0	Pass No fault
16. Back door	4	Fault
17. Right mirror	0	Pass No fault
18. Rain and/or humidity sensor	0	Pass No fault
19. Blind spot monitor (BSM) slave	0	Pass No fault
20. Blind spot monitor (BSM) master	0	Pass No fault
21. Navigation system	0	Pass No fault
22. Starting control	0	Pass No fault
23. Power source control	0	Pass No fault
24. Entry&Start	0	Pass No fault
25. Adaptive front-lighting system (AFS)	0	Pass No fault
26. Wiper	0	Pass No fault
27. Stop and start	0	Pass No fault
28. IPA/ICS/Clearance sonar	2	Fault
29. Radar cruise I	0	Pass No fault
30. Head-Up display	0	Pass No fault
31. Tilt & telescopic steering	0	Pass No fault
32. Sliding sunshade	0	Pass No fault
33. 4WD	0	Pass No fault
34. Master switch	0	Pass No fault
35. EMPS	0	Pass No fault



Repair Shop:
Phone Number:
Address:

Report Number: MAXIA20220305
Creation Date: 2022-03-05



36. Panoramic view monitor	1	Fault
37. Air conditioner	0	Pass No fault
38. Central gateway	0	Pass No fault

DTC Details

1. Main body(1 DTC)

Codes	Description	Status
U0230	Lost communication with rear gate module	History

2. Back door(4 DTCs)

Codes	Description	Status
B2250	Power back door(PBD)/PTL closer operation	History
B2251	Power back door(PBD)/PTL closer switch	History
B2220	Rear door motor circuit	History
B2202	Lost communication with emblem sensor	History

3. IPA/ICS/Clearance sonar(2 DTCs)

Codes	Description	Status
C1AED	Rear sensor communication circuit	Current
C1AED	Rear sensor communication circuit	History

4. Panoramic view monitor(1 DTC)

Codes	Description	Status
U0265	Lost communication with image processing sensor A	History

Disclaimer

The second half of the statement should be reworded to indicate, for you safety the faults should be analyzed and repaired by a professional automotive



Repair Shop:
Phone Number:
Address:

Report Number: MAXIA20220305
Creation Date: 2022-03-05



technician.



Repair Shop:
Phone Number:
Address:

Report Number: MAXIA20220305
Creation Date: 2022-03-05



12/2017-08/2019 Lexus Vehicle Diagnostic Report

License Plate: SME8754A

Manufacturer: Lexus

Year: 12/2017-08/2019

Model: RX300

Sub Model:

Engine: 8AR-FTS

Path: Lexus>Automatic selection>RX300>Europe/Others>AGL2#>8AR-FTS>Others>12/2017-08/2019>Radar cruise>Auto scan

Client:

Phone Number:

VIN: JTJBAMCAX02060080

Mileage: 56306 km

Color:

Status:

Overview

Modules Scanned:38

Modules with Faults:0

Total number of codes :0

System status report

System	DTC	Status
1. Engine	0	Pass No fault
2. Transmission	0	Pass No fault
3. ABS/VSC/TRC/EPB	0	Pass No fault
4. SRS airbag	0	Pass No fault
5. Combination meter	0	Pass No fault
6. Tire pressure monitor	0	Pass No fault
7. Main body	0	Pass No fault
8. Driver door motor	0	Pass No fault
9. Sliding roof	0	Pass No fault
10. Left mirror	0	Pass No fault
11. Passenger seat	0	Pass No fault
12. Driver seat	0	Pass No fault
13. Right rear door motor	0	Pass No fault



Repair Shop:
Phone Number:
Address:

Report Number: MAXIA20220305
Creation Date: 2022-03-05



14. Left rear door motor	0	Pass No fault
15. Passenger door motor	0	Pass No fault
16. Back door	0	Pass No fault
17. Right mirror	0	Pass No fault
18. Rain and/or humidity sensor	0	Pass No fault
19. Blind spot monitor (BSM) slave	0	Pass No fault
20. Blind spot monitor (BSM) master	0	Pass No fault
21. Navigation system	0	Pass No fault
22. Starting control	0	Pass No fault
23. Power source control	0	Pass No fault
24. Entry&Start	0	Pass No fault
25. Adaptive front-lighting system (AFS)	0	Pass No fault
26. Wiper	0	Pass No fault
27. Stop and start	0	Pass No fault
28. IPA/ICS/Clearance sonar	0	Pass No fault
29. Radar cruise 1	0	Pass No fault
30. Head-Up display	0	Pass No fault
31. Tilt & telescopic steering	0	Pass No fault
32. Sliding sunshade	0	Pass No fault
33. 4WD	0	Pass No fault
34. Master switch	0	Pass No fault
35. EMPS	0	Pass No fault



Repair Shop:
Phone Number:
Address:

Report Number: MAXIA20220305
Creation Date: 2022-03-05



36. Panoramic view monitor	0	Pass No fault
37. Air conditioner	0	Pass No fault
38. Central gateway	0	Pass No fault

Disclaimer

The second half of the statement should be reworded to indicate, for your safety the faults should be analyzed and repaired by a professional automotive technician.