4/6/22, 1:24 PM Adjuster Report

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI22001801/ETY3N2

06/04/2022 Date:

**REFERENCE** 

Reg. Date:

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No: DMPCSNW00212112101

**Claimant Vehicle** No:

SLG2712L

Insured Vehicle SMD3391B

No:

Date of Loss: 22/02/2022 Nature of Claim: TP Claim

SNM22D201344/C02/TANKL

DAD482578

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

**SLG2712L** Reg No:

Make & Model: SKODA KAROQ, 1.5 TSI STYLE (A) Engine No:

31/10/2019 (Man. Year: 2019) Chassis No: TMBKR7NU2K5035499

Colour: Blue Odometer: 68241 km

**Engine Capacity:** 1498 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: Pre-accident Condition: Yes Nο

**CONDITION OF TYRES** 

Front Tyre Size: 225/80R18 Rear Tyre Size: 225/80R18 Front Left Side: Rear Left Side: Dunlop 5 mm Dunlop 5 mm Front Right Side: Dunlop 5 mm Rear Right Side: Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,636.41	654.05	2,982.36	82.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,280.00	1,320.00	1,960.00	59.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,916.41	1,974.05	4,942.36	71.46
+ GST 7.00/7.00% (S\$)	484.15	138.18	345.97	71.46
Nett Amount (S\$)	7,400.56	2,112.23	5,288.33	71.46

**INSPECTION** 

Date Inspected:

Date of Assignment: 24/02/2022

Volkswagen Group Singapore Pte Ltd

247 ALEXANDRA ROAD

Singapore 159934

Estimated Period of Repair: 2.0 days

DENISE TAY KWEE CHENG Adjuster: **CHEN TSUE YEE** Manager:

Inspected At:

03/03/2022

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

4/6/22, 1:24 PM Adjuster Report

### **REPAIR DETAILS**

### Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 06 Apr 2022)

Parts: 144 SKODA KAROQ 1.5 TSI STYLE (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SLG2712L)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SENSOR BRACKET	Not Necessary	56.59 FS	*- FS
2	1		*SENSOR BRACKET	Not Necessary	56.59 FS	*- FS
3	1		*SENSOR BRACKET	Not Necessary	40.43 FS	*- FS
4	1		*SENSOR BRACKET	Not Necessary	40.43 FS	*- FS
5	1		*SENSOR PRIMED	Not Necessary	189.82 FS	*- FS
6	1		*SEAL RING SATIN BLACK	Not Necessary	1.46 FS	*- FS
7	1		*BONDING AGENT FOR PLASTIC	Not Necessary	68.71 FS	*- FS
8	1		*2K-PLASTIC ADHESIVE	Not Necessary	85.80 FS	*- FS
9	1		*COVER FOR REAR BUMPER LOWER (SILVER)	Cut	654.05 FS	*654.05 FS
10	1		*REINFORCEMENT	Not Necessary	529.95 FS	*- FS
11	1		*ATTACHMENT BUMPER CTR BRACKET	Not Necessary	69.03 FS	*-FS
12	1		*GUIDE PIEC LHR BUMPER BRACKET (UPPER)	Not Necessary	96.02 FS	*- FS
13	1		*GUIDE PIEC RHR BUMPER BRACKET (UPPER)	Not Necessary	96.02 FS	*- FS
14	1		*GUIDE PIEC LHR BUMPER BRACKET (SIDE)	Not Necessary	83.17 FS	*- FS
15	1		*GUIDE PIEC RHR BUMPER BRACKET (SIDE)	Not Necessary	83.17 FS	*- FS
16	1		*COVER FOR REAR BUMPER UPPER (BLACK)	Not Necessary	1,485.17 FS	*-FS
F=Fra	nchise	part. S=SpcN	lett.	Total Parts (S\$)	3,636.41	654.05

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

Particulars	Lab.Type	Repairer's	Amount
<u>our Items</u>			
LABOUR	New	2,520.00	840.00
B&P CHECK SHORT CIRCUIT/HARNESS REPAIR	New	280.00	0.00
B&P DIAGNOSIS AND PROGRAMMING	New	480.00	480.00
	Gross Labour Cost (S\$)	3,280.00	1,320.00
Report was unsub	pmitted during this print-out.		
	our Items  LABOUR  B&P CHECK SHORT CIRCUIT/HARNESS REPAIR  B&P DIAGNOSIS AND PROGRAMMING	OUR Items  LABOUR  B&P CHECK SHORT CIRCUIT/HARNESS REPAIR  New  B&P DIAGNOSIS AND PROGRAMMING  New	DOUT Items           LABOUR         New         2,520.00           B&P CHECK SHORT CIRCUIT/HARNESS REPAIR         New         280.00           B&P DIAGNOSIS AND PROGRAMMING         New         480.00           Gross Labour Cost (S\$)         3,280.00

< END OF ESTIMATES >