



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMQ 3356K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT DOOR LH	TO REPAIR SEE LABOUR	907.60	-
1	REAR DOOR LH	BENT	843.20	843.20
1	ROCKER PANEL GARNISH LH (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 20% DISCOUNT		-350.16	-168.64
			1,400.64	674.56
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT DOOR BLACK FRAME STICKER LH (SN)	NOT NECESSARY	50.00	-
1	REAR DOOR BLACK FRAME STICKER LH (SN)	NECESSARY	50.00	50.00
			100.00	50.00
	<u>LABOUR</u>			
	LABOUR CHARGES TO REMOVE, REPLACE, REFIX & READJUST ACCIDENT AREAS & ETC. INCLUSIVE OF THE REPAIR OF FRONT DOOR LH AND ROCKER PANEL GARNISH LH.		700.00	400.00
	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT ACCIDENT AREAS & ETC.		800.00	550.00
	LABOUR CHARGES TO REMOVE & REINSTALLED FRONT & REAR DOOR INNER MECHANISM & ETC. BACK TO ORIGINAL OPERATIONS.		240.00	60.00
	TO CHECK WIRING & CENTRAL LOCKING SYSTEM & ETC.		80.00	20.00
			1,820.00	1,030.00
	GRAND TOTAL		3,320.64	1,754.56
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,400.00

Report Ref No. CS/FCI22001803/Kqf3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.