



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSE SINGAPORE 068877			Ref: CS/FCI22001803/Kqf3e2	
			Date: 11/05/2022	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBC 1990X	Veh. Inspected	SMQ 3356K
	Policy No.		Coverage (\$)	0.00
	Claim No.	D22000512MFCV	Excess (\$)	0.00
	Assign From	AINI BINTE	Assign Date	24/02/2022
2. Vehicle Particulars & Condition				
	Make & Model	HONDA SHUTTLE (A)	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	GP72002614	Colour	METALLIC PEARL WHITE
	Odometer	215868 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	185/60 R15	KAPSEN	8 mm
	L/H Front Tyre	185/60 R15	KAPSEN	8 mm
	R/H Rear Tyre	185/60 R15	INTERTRAC	8 mm
	L/H Rear Tyre	185/60 R15	INTERTRAC	8 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	20/02/2022	Inspection Date	25/02/2022
	Survey held at	10 Ang Mo Kio Industrial Park 2A #01-05		
	Repairer	OPTIMA WERKZ PTE LTD		
5a. Remarks				
	A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	