

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22001806/KTY3N2**Date:** 21/03/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00003982201

Claimant Vehicle No : SMU6264B **Insured Vehicle No :** GBK9015S

Date of Loss: 13/02/2022 Nature of Claim: TP Claim No: SNM22D201340/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMU6264B**

Make & Model: MERCEDES-BENZ C180, 1.8 Blue Efficiency (A) Engine No: 27491030033377

Reg. Date: 20/03/2013 (Man. Year: 2012) Chassis No: WDD2040312A812780

Colour: Metallic Grey Odometer: 67272 km

Engine Capacity: 1595 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45R17 Rear Tyre Size: 225/45R17

Front Left Side: Michelin 7 mm Rear Left Side: Michelin 7 mm

Front Right Side: Michelin 7 mm Rear Right Side: Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,299.38	1,483.74	2,815.64	65.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,240.00	435.00	1,805.00	80.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	6,539.38	1,918.74	4,620.64	70.66
Approved Total (Overridden) (\$\$)		1,500.00		
(\$\$)	6,539.38	1,500.00	5,039.38	77.06
+ GST 7.00/7.00% (\$\$)	457.76	105.00	352.76	77.06
Nett Amount (\$\$)	6,997.14	1,605.00	5,392.14	77.06

INSPECTION

Date of Assignment: 24/02/2022

Date Inspected: 25/02/2022 Inspected At: Accord Auto Services Pte Ltd (HQ)
10 Ang Mo Kio Ind Park 2A #03-11, AMK Auto Point
Singapore 568047

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 20 Mar 2022)

Parts: 143 MERCEDES-BENZ C180 1.8 Blue Efficiency (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMU6264B)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled/Cracked	1,530.00 FL	*1,450.00 FL
2	1		*REAR BUMPER SIDE RETAINER LH LONG	Necessary	58.60 FL	*58.60 FL
3	1		*REAR BUMPER SIDE RETAINER LH SHORT	Necessary	90.00 FL	*90.00 FL
4	1		*REAR LAMP LH	Serviceable	603.00 FL	*- FL
5	1		*REAR LAMP LOWER BRACKET LH	Serviceable	75.60 FL	*- FL
6	1		*REAR FENDER LH	Repair	2,124.00 FL	*- FL
7	1		*REAR FENDER SHIELD	Serviceable	207.00 FL	*- FL
8	1		*SET REAR BUMPER CLIPS	Necessary	45.00 FS	*45.00 FS
9	1		*SET REAR LH FENDER INNER SHIELD CLIPS	Not Necessary	35.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,768.20	1,643.60
- List Item Discount on L Items 10.00/10.00% (\$\$)	468.82	159.86
Total Parts (\$\$)	4,299.38	1,483.74

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SPRAY PAINT ON ALL AFFECTED AREA	New	1,000.00	220.00
2	LABOUR REMOVE/REFIX ACCIDENT DAMAGE PARTS TO KNOCK,JACK,CUT WELD AND REALIGN ACCIDENT AFFECTED AREA	New	1,000.00	200.00
3	TO CHECK WIRING SYSTEM & LIGHT	New	120.00	15.00
4	TO APPLY ANTI RUST TREATMENT	New	120.00	0.00
Gross Labour Cost (S\$)			2,240.00	435.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >