

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22001808/UQY3N2**Date:** 12/05/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00128982101	
Claimant Vehicle No :	SMU3905E	Insured Vehicle No :	GBH9936A	
Date of Loss:	15/02/2022	Nature of Claim:	TP	Claim No: SNM22D201142/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMU3905E		Engine No:	PE21483796
Make & Model:	MAZDA CX-5, 2.0 (A)		Chassis No:	JM6KF2W7AL0500828
Reg. Date:	12/08/2020 (Man. Year: 2020)		Odometer:	27004 km
Colour:	Black			
Engine Capacity:	1998 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/65R17	Rear Tyre Size:	225/65R17
Front Left Side:	Yokohama 7 mm	Rear Left Side:	Yokohama 7 mm
Front Right Side:	Yokohama 7 mm	Rear Right Side:	Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	767.90	737.90	30.00	3.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,420.00	1,590.00	2,830.00	64.03
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,187.90	2,327.90	2,860.00	55.13
+ GST 7.00/7.00% (S\$)	363.15	162.95	200.20	55.13
Nett Amount (S\$)	5,551.05	2,490.85	3,060.20	55.13

INSPECTION

Date of Assignment:	24/02/2022		
Date Inspected:	03/03/2022	Inspected At:	Trans Eurokars Pte Ltd (Ubi) 5 Ubi Close Singapore 408605
Estimated Period of Repair:	3.0 days		

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 May 2022)
Parts:	M1-SUV	MAZDA CX-5 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMU3905E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER RH	Badly Dented	380.10 F	*380.10 F
2	1		*STAY FENDER RH	Bent	51.30 F	*51.30 F
3	1		*MUD GUARD RH FRT	Distorted	98.20 F	*98.20 F
4	10		*FASTENER	Necessary	30.00 F	*30.00 F
5	1		*WHEEL ARCH FRONT RH	Distorted	158.30 F	*158.30 F
6	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
F=Franchise part. S=SpcNett.						
					Total Parts (\$\$)	767.90
						737.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	New	250.00	120.00
2	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	New	300.00	180.00
3	TO REPLACE FRONT FENDER RH. TO REPAIR BONNET AND ALL AREAS AFFECTED BY THE ACCIDENTS.	New	1,980.00	660.00
4	TO RESPRAY FRONT FENDER RH, BONNET AND ALL AREAS AFFECTED BY THE ACCIDENTS.	New	1,890.00	630.00
Gross Labour Cost (\$)			4,420.00	1,590.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >