

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22001809/UVY3N2**Date:** 18/05/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNA00155002100

**Claimant Vehicle No :** SNC1458A **Insured Vehicle No :** XE6860J

Date of Loss: 05/01/2022 Nature of Claim: TP Claim No: SNM22D200261/C02/TOHHS

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SNC1458A**

Make & Model: MAZDA 3, 1.5 4DR M-HYBRID CLASSIC (A) Engine No: P520757433

Reg. Date: 29/09/2021 (Man. Year: 2021) Chassis No: JM6BP2SAAM1108696

Colour: White Odometer: 10595 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 205/60R16 Rear Tyre Size: 205/60R16

Front Left Side: Yokohama 8 mm Rear Left Side: Yokohama 8 mm

Front Right Side: Yokohama 8 mm Rear Right Side: Yokohama 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	7,012.10	2,232.10	4,780.00	68.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,280.00	3,400.00	5,880.00	63.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>16,292.10</b>	<b>5,632.10</b>	<b>10,660.00</b>	<b>65.43</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,140.45</b>	<b>394.25</b>	<b>746.20</b>	<b>65.43</b>
<b>Nett Amount (S\$)</b>	<b>17,432.55</b>	<b>6,026.35</b>	<b>11,406.20</b>	<b>65.43</b>

**INSPECTION**

Date of Assignment: 24/02/2022

Date Inspected: 07/03/2022 Inspected At: Trans Eurokars Pte Ltd (Ubi)  
5 Ubi Close  
Singapore 408605

Estimated Period of Repair: 4.0 days

**Adjuster:** MARCUS CHUA**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 16 May 2022)

**Parts:** 143      MAZDA 3 1.5 4DR M-HYBRID CLASSIC (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's      (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SNC1458A)

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	997.40 F	*997.40 F
2	1		*RETAINER LH REAR	Necessary	33.20 F	*33.20 F
3	1		*BRACKET CENTER REAR BUMPER	Not Necessary	5.40 F	*- F
4	1		*SPLASH SHIELD LH REAR	Not Necessary	83.50 F	*- F
5	8		*FASTENER	Necessary	24.00 F	*24.00 F
6	2		*NUT CLIP	Necessary	3.80 F	*3.80 F
7	4		*GROMMET, SCREW	Necessary	10.80 F	*10.80 F
8	3		*TAPE,PROTECTOR	Necessary	14.10 F	*14.10 F
9	1		*PLATE SET LH REAR BUMPER	Not Necessary	95.40 F	*- F
10	2		*BRACKET RETAINER S.S ULTRASONIC	Necessary	46.80 F	*46.80 F
11	1		*RETAINER S.S ULTRASONIC	Necessary	25.10 F	*25.10 F
12	1		*RETAINER S.S ULTRASONIC	Necessary	25.10 F	*25.10 F
13	1		*REAR FENDER LH	Repair	1,565.30 F	*- F
14	1		*REAR ABSORBER LH	Not Necessary	322.20 F	*- F
15	1		*RUBBER MOUNTING TOP ABSORBER LH	Not Necessary	111.10 F	*- F
16	1		*AXLE,TORSION-REAR	Not Necessary	2,122.80 F	*- F
17	1		*HUN WHEEL BEARING LH REAR	Not Necessary	437.60 F	*- F
18	1		*WHEEL,DISC-ALUMI 16X6.5	Cut	1,031.80 F	*1,031.80 F
19	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
20	1		*VALVE,AIR	Not Necessary	6.70 F	*- F

F=Franchise part. S=SpcNett.

**Total Parts (\$\$)**      **7,012.10**      **2,232.10**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REPLACE REAR BUMPER, REAR FENDER LH AND REPAIR ALL AREAS AFFECTED BY THE ACCIDENTS.	New	3,300.00	1,320.00
2	TO RESPRAY REAR BUMPER, REAR FENDER LH AND ALL AREAS AFFECTED BY THE ACCIDENTS.	New	2,520.00	1,260.00
3	TO TRANSFER REVERSE SENSORS.	New	660.00	150.00
4	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING.	New	180.00	0.00
5	TO REPLACE AXLE AND SUSPENSION MECHANISM.	New	660.00	0.00
6	TO REMOVE & REFIT THE WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.	New	560.00	0.00
7	TO SUPPLY SEALER ON THE WINDSCREEN GLASS.	New	120.00	0.00
8	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.	New	560.00	280.00
9	TO MOUNT SPORT RIM AND CONDUCT WHEEL BALANCING.	New	120.00	90.00
10	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	New	200.00	120.00
11	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	New	250.00	180.00
12	TO CARRY-OUT BODY CAVITY PRESERVATION (INCLUDING NEW PARTS AND CAOUTCHOUC)	New	150.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>9,280.00</b>	<b>3,400.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >