

COMFORTDELGRO ENGINEERING PTE LTD
#205 Braddell Road
Blk C Ext 1 3rd Level
Singapore 579701



VICOM LTD
385 Sin Ming Drive Singapore 575718

Mainline (65) 6458 4555
Facsimile (65) 6458 1040

www.vicom.com.sg
Company Registration No. 198100320K

SURVEY REPORT

Thuan

GENERAL INFORMATION

VAC Ref. No.	: 571109	Claim No.	: 305504665
Accident Date	: 10/02/2022	Claim Type	: THIRD PARTY
Assignment Date	: 11/02/2022	Policy No.	:
Survey Date	: 11/02/2022	Finalised Dt.:	:
Survey Report Date	: 18/02/2022		

VEHICLE PARTICULARS

Vehicle No.	: SH9839X	Chassis No.	: KMHC851CVKU164717
Registration Date	: 17/07/2019	Engine No.	: OBSCURED
Make	: HYUNDAI	Engine Cap.	: 1580 CC
Model	: IONIQ (G2)	Transmission	: AUTO
		Colour	: BLUE

CONDITION OF VEHICLE DURING SURVEY (VISUAL and STATIC TEST ONLY)

Foot Brake	: SERVICEABLE	Steering	: SERVICEABLE
Hand Brake	: SERVICEABLE	Modification	: NONE
Mileage	:		

<u>TYRES</u>	<u>SIZE</u>	<u>MAKE</u>	<u>BALANCE (mm)</u>
FRONT RH	195/60R16	WESTLAKE	6
FRONT LH	195/60R16	WESTLAKE	6
REAR RH	195/60R16	WESTLAKE	6
REAR LH	195/60R16	WESTLAKE	6

SURVEY CONDUCTED AT

59 Loyang Drive
Singapore 508969

REMARKS

- [1] Workshop Estimate : S\$ 7,574.72
[2] Our Adjustment : S\$ 5,022.72
[3] Repair Period : 4 days
[4] We have not authorised repairs. This survey was carried out on without prejudice basis.

VICOM LTD

SURVEY REPORT

Annex A: Adjustment on Spare Parts

#	Qty	Vehicle Parts Description	Condition	Workshop Estimate (S\$)	VAC Adjustment (S\$)
1	1	Rear Bumper	Deformed	459.40	459.40
2	1	Rear Bumper Centre Moulding	Deformed	451.25	451.25
3	1	Rear Bumper Reinforcement	Reuse	394.80	0.00
4	2	Rear Bumper Stay Rh/Lh	Reuse	276.20	0.00
5	1	Rear Bumper Lower Moulding	Reuse	155.00	0.00
6	1	Rear Bumper Under Cover	Deformed	225.00	225.00 xsv
7	10	Rear Bumper Clips	Necessary	22.00	22.00
8	1	Boot Lid	Dented	2480.40	2480.40
9	1	Boot Lid Lock Upper	Reuse	224.00	0.00
10	1	Boot Lid H Emblem	Waived	38.00	0.00
11	1	Boot Lid Ionid Emblem	Necessary	31.80	31.80
12	1	Boot Lid Hybrid Emblem	Necessary	24.30	24.30
13	1	Rear End Panel	Repair	532.00	0.00
14	1	Rear End Panel Garnish	Reuse	346.80	0.00
15	1	Rear Bumper Fog Lamp	Reuse	201.00	0.00
16	2	Rear Bumper Number Plate Lamp Rh/Lh	Reuse	170.60	0.00
17	1	Rear Bumper Hook Cover	Reuse	94.60	0.00
18	2	Rear Reflector Rh/Lh	Reuse	82.90	0.00
19	1	Rear Antenna Smart Key	Snapped	40.50	40.50
20	2	Rear Bumper Bracket Rh/Lh	Reuse	111.60	0.00
			Subtotal	6362.15	3734.65
				1272.43	746.93
Less 20 %					
			TOTAL	5089.72	2987.72
					2987.72
SPECIAL NETT ITEM					
1	1	Boot Lid Comfort & Tel No. Sticker	Necessary	60.00	60.00
2	1	Boot Lid App Sticker	Necessary	40.00	40.00
3	1	Rear Bumper Rubber Mat	Necessary	50.00	50.00
4	1	Rear Number Plate C/W Trim Cover	Cracked	55.00	55.00
5	1	Reverse Sensor	Malfunction	180.00	180.00
			TOTAL	385.00	385.00
				5474.72	3372.72
TOTAL FOR SPARE PARTS					

SURVEY REPORT

Annex B: Adjustment on Labour and Spray Painting

#	Job Description	Workshop Estimate (S\$)	VAC Adjustment (S\$)
1	Labour charges	950.00	700.00
2	Spray painting charges	850.00	750.00
3	Remove/ refix rear windscreen glass	120.00	120.00
4	Wiring charges	60.00	20.00
5	Tuff kote	60.00	20.00
6	Remove/ refix reverse sensor	60.00	20 40.00
TOTAL FOR LABOUR AND SPRAY PAINTING		2100.00	1650.00

Summary

Description	Workshop Estimate (S\$)	VAC Adjustment (S\$)
TOTAL FOR SPARE PARTS	5474.72	3372.72
TOTAL FOR LABOUR AND SPRAY PAINTING	2100.00	1650.00
TOTAL REPAIR COST	7574.72	5022.72

4822.72

VICOM LTD**SURVEY REPORT****Annex C: Conclusion****ASSESSOR'S REPORT**

At the place of inspection, we saw this vehicle sustained rear damage.

The damages seen during our survey were at rear bumper, rear end panel, boot lid and surrounding areas. A fuller detailed description of the damages is in Annex A of this survey report.

ASSESSOR'S RECOMMENDATION

Comfortdelgro Engineering Pte Ltd (Loyang) estimated a repair cost of S\$7,574.72. We adjusted it to S\$5,022.72 on a part-by-part basis.

Accordingly, we recommend repairs to this vehicle be carried out on a part-by-part basis at S\$5,022.72.

The repairs would require a period of 4 working days.



Kamarudin Abdul Kadir
for VICOM Ltd