

FINAL COST OF REPAIR

(To be completed for only one type of item)

To: <div style="text-align: center;"> HD TPT CENTRE EAST, TPTHUBEAST SELETAR NODE HD TPT RESOURCE, TPTHUBEAST RESOURCE SUP IC, TPTHUBEAST <hr style="width: 50%; margin: 0 auto;"/> Unit </div>		From: <div style="text-align: center;"> MAO/NSCSW <hr style="width: 50%; margin: 0 auto;"/> </div>	
Description of Item:		OPS UTILITY VEH FORD EVEREST FFR 0.7T	SAF 1222: BB70/D/NS/02/22 Dtd 15/2/22
Part/Reg No:	MID34336	Original Value:	-
Quantity:	01	CE/Non CE:	-
Description of Damages and Costs of Repairs:		Date:	
		MO/MR:	8202716531/19687685
		Date:	11.02.2022
		Accident Job No:	8202716531/19687685
		Date:	11.02.2022
<u>S/N</u> <u>Incident Repair</u> <u>Man-hours</u> 1) Front Bumper centre stain with blue paint 0.10			
<u>S/N</u> <u>Materials Cost</u> <u>Unit Price</u> <u>Qty</u> <u>COST</u>			
Base/LEO Area Office's Assessment of Damages			
<div style="display: flex; justify-content: space-between;"> <div> Labour Charges @ \$28.63 per hour X 0.16 hrs Total Cost of Parts / Materials Used Sub-contractor Assessment Fee Towing Service Total </div> <div style="text-align: right;"> = \$4.58 = - = - = \$14.31 = - <hr style="width: 50%; margin: 0 auto;"/> \$18.89 </div> </div>			
Estimated Time for Repair:		0.66 Hr	

*Delete whichever is not applicable

FINAL COST OF REPAIR