



Your Ref: CY 22/MID34336/100222/0004

Date: 05<sup>th</sup> Apr 2022

Our Ref: CC2/MIDA22001810/Vpq2

**M/s Ministry Of Defence**  
HQ Transport Command  
Kranji Camp 3  
151 Choa Chu Kang Way  
Singapore 688248

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SH 9839X**  
**INSURED VEHICLE: MID 34336**  
**ACCIDENT DATE: 10/02/2022**

We thank you for your instruction on 16/02/2022.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SH 9839X from M/s Vicom Ltd.
- b) Singapore Accident Statement of Vehicles SH 9839X.
- c) Police Report of Vehicles SH 9839X and MID 34336.
- d) Colour damaged vehicle photographs of SH 9839X.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SH 9839X
Make & Model	: Hyundai AE IONIQ HEV 1.6 DCT
Chassis Number	: KMHC851CVKU164717
Year of Registration	: 2019
Engine Capacity	: 1580 cc

2. We recommend that the repairs of the entire damage require about 4 (Four) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 9839X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BUMPER	DEFORMED	459.40	459.40
1	REAR BUMPER CENTRE MOULDING	DEFORMED	451.25	451.25
1	REAR BUMPER REINFORCEMENT	REUSE	394.80	-
2	REAR BUMPER STAY RH/LH	REUSE	276.20	-
1	REAR BUMPER LOWER MOULDING	REUSE	155.00	-
1	REAR BUMPER UNDER COVER	SERVICEABLE	225.00	-
10	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	BOOT LID	DENTED	2,480.40	2,480.40
1	BOOT LID LOCK UPPER	REUSE	224.00	-
1	BOOT LID H EMBLEM		38.00	-
1	BOOT LID LONID EMBLEM	NECESSARY	31.80	31.80
1	BOOT LID HYBRID EMBLEM	NECESSARY	24.30	24.30
1	REAR END PANEL	TO REPAIR SEE LABOUR	532.00	-
1	REAR END PANEL GARNISH	REUSE	346.80	-
1	REAR BUMPER FOG LAMP	REUSE	201.00	-
2	REAR BUMPER NUMBER PLATE LAMP RH/LH	REUSE	170.60	-
1	REAR BUMPER HOOK COVER	REUSE	94.60	-
2	REAR REFLECTOR RH/LH	REUSE	82.90	-
1	REAR ANTENNA SMART KEY	SNAPPED	40.50	40.50
2	REAR BUMPER BRACKET RH/LH	REUSE	111.60	-
	LESS 20% DISCOUNT		-1,272.43	-701.93
			5,089.72	2,807.72
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	BOOT LID COMFORT & TEL NO. STICKER (SN)	NECESSARY	60.00	60.00
1	BOOT LID APP STICKER (SN)	NECESSARY	40.00	40.00
1	REAR BUMPER RUBBER MAT (SN)	NECESSARY	50.00	50.00
1	REAR NUMBER PLATE C/W TRIM COVER (SN)	CRACKED	55.00	55.00
1	REVERSE SENSOR (SN)	MALFUNCTION	180.00	180.00
			385.00	385.00
	<b><u>LABOUR</u></b>			
	LABOUR CHARGES. INCLUSIVE OF THE REPAIR OF REAR END PANEL .		950.00	700.00
	SPRAY PAINTING CHARGES.		850.00	750.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE/REFIX REAR WINDSCREEN GLASS .		120.00	120.00
	WIRING CHARGES.		60.00	20.00
	TUFF KOTE.		60.00	20.00
	REMOVE/REFIX REVERSE SENSOR .		60.00	20.00
			2,100.00	1,630.00
<b>GRAND TOTAL</b>			<b>7,574.72</b>	<b>4,822.72</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>4,822.72</b>

Report Ref No. CC2/MIDA22001810/Vpq2

THEVAN THOMAS KARTHIKESAVAN

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.