



**VICOM LTD**

385 Sin Ming Drive Singapore 575718

Mainline (65) 6458 4555  
Facsimile (65) 6458 1040

www.vicom.com.sg  
Company Registration No: 198100320K

## TAX INVOICE

COMFORTDELGRO ENGINEERING PTE LTD  
#205 Braddell Road  
Blk C Ext 1 3rd Level  
Singapore 579701

ATTN : MOTOR CLAIMS DEPT.

VEHICLE No. : SH9839X  
ACCIDENT DATE : 10/02/2022  
CLAIM No. : 305504665

GST REG No. : M9-0000652-A  
CUSTOMER ID : VACC0013  
INVOICE No. : LY013808  
INVOICE DATE : 21/02/2022  
PAYMENT TERM : 30 Days Credit

DESCRIPTION	QTY	UNIT PRICE (SG\$)	AMOUNT (SG\$)
Photographs	22	1.00	\$ 22.00
Transportation	1	50.00	\$ 50.00
VAC Assessment Fee	1	195.00	\$ 195.00

REMARKS	GROSS AMOUNT	\$	267.00
CTPL	GST @ 7%	\$	18.69
	INVOICE AMOUNT	\$	285.69

This is a computer generated TAX INVOICE  
No signature required

Cheque should be made payable to 'VICOM LTD'.

**Sin Ming**

385 Sin Ming Drive Singapore 575718  
Tel: (65) 6455 5358 Fax: (65) 6455 8638

**Bukit Batok**

511 Bukit Batok St 23 Singapore 659545  
Tel: (65) 6560 3312 Fax: (65) 6569 0722

**Kaki Bukit**

23 Kaki Bukit Ave 4 Singapore 415933  
Tel: (65) 6741 6697 Fax: (65) 6749 2305

COMFORTDELGRO ENGINEERING PTE LTD  
#205 Braddell Road  
Blk C Ext 1 3rd Level  
Singapore 579701



VICOM LTD  
385 Sin Ming Drive Singapore 575718

Mainline (65) 6458 4555  
Facsimile (65) 6458 1040

www.vicom.com.sg  
Company Registration No: 190100320K

# SURVEY REPORT

GENERAL INFORMATION			
VAC Ref. No.	: 571109	Claim No.	: 305504665
Accident Date	: 10/02/2022	Claim Type	: THIRD PARTY
Assignment Date	: 11/02/2022	Policy No.	:
Survey Date	: 11/02/2022	Finalised Dt.:	:
Survey Report Date	: 18/02/2022		
VEHICLE PARTICULARS			
Vehicle No.	: SH9839X	Chassis No.	: KMHC851CVKU164717
Registration Date	: 17/07/2019	Engine No.	: OBSCURED
Make	: HYUNDAI	Engine Cap.	: 1580 CC
Model	: IONIQ (G2)	Transmission	: AUTO
		Colour	: BLUE
CONDITION OF VEHICLE DURING SURVEY (VISUAL and STATIC TEST ONLY)			
Foot Brake	: SERVICEABLE	Steering	: SERVICEABLE
Hand Brake	: SERVICEABLE	Modification	: NONE
Mileage	:		
TYRES	SIZE	MAKE	BALANCE (mm)
FRONT RH	195/60R16	WESTLAKE	6
FRONT LH	195/60R16	WESTLAKE	6
REAR RH	195/60R16	WESTLAKE	6
REAR LH	195/60R16	WESTLAKE	6
SURVEY CONDUCTED AT			
59 Loyang Drive Singapore 508969			
REMARKS			
[1] Workshop Estimate : S\$ 7,574.72			
[2] Our Adjustment : S\$ 5,022.72			
[3] Repair Period : 4 days			
[4] We have not authorised repairs. This survey was carried out on without prejudice basis.			

## SURVEY REPORT

## Annex A: Adjustment on Spare Parts

#	Qty	Vehicle Parts Description	Condition	Workshop Estimate (S\$)	VAC Adjustment (S\$)
1	1	Rear Bumper	Deformed	459.40	459.40
2	1	Rear Bumper Centre Moulding	Deformed	451.25	451.25
3	1	Rear Bumper Reinforcement	Reuse	394.80	0.00
4	2	Rear Bumper Stay Rh/Lh	Reuse	276.20	0.00
5	1	Rear Bumper Lower Moulding	Reuse	155.00	0.00
6	1	Rear Bumper Under Cover	Deformed	225.00	225.00
7	10	Rear Bumper Clips	Necessary	22.00	22.00
8	1	Boot Lid	Dented	2480.40	2480.40
9	1	Boot Lid Lock Upper	Reuse	224.00	0.00
10	1	Boot Lid H Emblem	Waived	38.00	0.00
11	1	Boot Lid Ionid Emblem	Necessary	31.80	31.80
12	1	Boot Lid Hybrid Emblem	Necessary	24.30	24.30
13	1	Rear End Panel	Repair	532.00	0.00
14	1	Rear End Panel Garnish	Reuse	346.80	0.00
15	1	Rear Bumper Fog Lamp	Reuse	201.00	0.00
16	2	Rear Bumper Number Plate Lamp Rh/Lh	Reuse	170.60	0.00
17	1	Rear Bumper Hook Cover	Reuse	94.60	0.00
18	2	Rear Reflector Rh/Lh	Reuse	82.90	0.00
19	1	Rear Antenna Smart Key	Snapped	40.50	40.50
20	2	Rear Bumper Bracket Rh/Lh	Reuse	111.60	0.00
			<b>Subtotal</b>	<b>6362.15</b>	<b>3734.65</b>
Less 20 %				<b>1272.43</b>	<b>746.93</b>
			<b>TOTAL</b>	<b>5089.72</b>	<b>2987.72</b>

## SPECIAL NETT ITEM

1	1	Boot Lid Comfort & Tel No. Sticker	Necessary	60.00	60.00
2	1	Boot Lid App Sticker	Necessary	40.00	40.00
3	1	Rear Bumper Rubber Mat	Necessary	50.00	50.00
4	1	Rear Number Plate C/W Trim Cover	Cracked	55.00	55.00
5	1	Reverse Sensor	Malfunction	180.00	180.00
			<b>TOTAL</b>	<b>385.00</b>	<b>385.00</b>

**TOTAL FOR SPARE PARTS** : **5474.72** **3372.72**

## SURVEY REPORT

## Annex B: Adjustment on Labour and Spray Painting

#	Job Description	Workshop Estimate (S\$)	VAC Adjustment (S\$)
1	Labour charges	950.00	700.00
2	Spray painting charges	850.00	750.00
3	Remove/ refix rear windscreen glass	120.00	120.00
4	Wiring charges	60.00	20.00
5	Tuff kote	60.00	20.00
6	Remove/ refix reverse sensor	60.00	40.00
TOTAL FOR LABOUR AND SPRAY PAINTING		2100.00	1650.00

## Summary

Description	Workshop Estimate (S\$)	VAC Adjustment (S\$)
TOTAL FOR SPARE PARTS	5474.72	3372.72
TOTAL FOR LABOUR AND SPRAY PAINTING	2100.00	1650.00
TOTAL REPAIR COST	7574.72	5022.72

**SURVEY REPORT****Annex C: Conclusion****ASSESSOR'S REPORT**

At the place of inspection, we saw this vehicle sustained rear damage.


The damages seen during our survey were at rear bumper, rear end panel, boot lid and surrounding areas. A fuller detailed description of the damages is in Annex A of this survey report.

**ASSESSOR'S RECOMMENDATION**

Comfortdelgro Engineering Pte Ltd (Loyang) estimated a repair cost of S\$7,574.72. We adjusted it to S\$5,022.72 on a part-by-part basis.

Accordingly, we recommend repairs to this vehicle be carried out on a part-by-part basis at S\$5,022.72.

The repairs would require a period of 4 working days.



Kamarudin Abdul Kadir  
for VICOM Ltd



