



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKQ 6452U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	TAILGATE	BADLY DENTED	1,016.00	1,016.00
1	TAILGATE INNER LOCK	SHORTED / JAMMED	315.00	315.00
1	TAILGATE WEATHERSTRIP	TWISTED	175.00	175.00
1	TAILGATE REAR LOGO	NECESSARY	47.00	47.00
1	TAILGATE "C & C" LOGO	NECESSARY	45.00	45.00
1	TAILGATE "ASX" EMBLEM	NECESSARY	58.00	58.00
1	REAR BUMPER	DISTORTED	828.00	828.00
1	REAR BUMPER REFLECTOR N/S	NOT NECESSARY	20.00	-
1	REAR BUMPER BEAM	BENT	228.00	228.00
2	REAR BUMPER SIDE RETAINERS @\$23.00	NECESSARY	46.00	46.00
1	REAR END PANEL	DENTED / BENT	335.00	335.00
1	REAR END PANEL TOP GARNISH	TWISTED	116.00	116.00
1	REAR END PANEL BUZZLE SENSOR	CRACKED	98.00	98.00
1	TAILLAMP N/S	CRACKED	545.00	545.00
1	REAR FENDER INNER TRIM N/S	NOT NECESSARY	332.00	-
	LESS 10% DISCOUNT		-420.40	-385.20
			3,783.60	3,466.80
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET REAR BUMPER REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	50.00	50.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	50.00	40.00
1	REAR WINDSCREEN INNER SEAL (SN)	NECESSARY	50.00	40.00
1	SET REAR TAILGATE INNER TRIM BOARD CLIPS (SN)	NECESSARY	50.00	50.00
1	REAR LICENCE PLATE (SN)	BENT	50.00	40.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	50.00	50.00
			580.00	470.00
<b><u>LABOUR</u></b>				
	TO CHECK WIRING.		50.00	20.00
	TO DISMANTLE & REPLACED REVERSE SENSOR.		80.00	50.00

Report Ref No. CS/TP22001812/Utf3e2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO DISMANTLE & REFIX REAR WINDSCREEN.	NOT NECESSARY	120.00	120.00
	TO DISMANTLE & REFIX CUSHION UPHOLSTERY.		120.00	80.00
	TO DISMANTLE & REFIX TAILGATE MECHANISM.		100.00	60.00
	TO SPRAY RUST PROOFING.		100.00	60.00
	TO RESET & REPROGRAMME SYSTEM.		120.00	80.00
	TO DISMANTLE & REFIX REAR EXHAUST.		100.00	-
	LABOUR FOR PANEL BEATING & REPLACED PARTS.		1,080.00	800.00
	TO PUTTY & SPRAY PAINTING.		1,500.00	1,200.00
			3,370.00	2,470.00
<b>GRAND TOTAL</b>			<b>7,733.60</b>	<b>6,406.80</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>5,100.00</b>

Report Ref No. CS/TP22001812/Utf3e2

**CHUA KANG SENG**

**Licensed Appraiser**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.