

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	MS FIRST CAPITA	L INSURANCE LTD		Ref:	CS3/FCI22001815/Vtf3e2
	36 ROBINSON ROAD #16-01 CITY HOUSE SINGAPORE 068877			Date:	29/03/2022
				Code:	FCI2
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SMB 5063X	Veh. Inspected		XD 2383B
	Policy No.		Coverage (\$)		0.00
	Claim No.	D22000550MFBP	Excess (\$)		0.00
	Assign From	HARMINDER KAUR	Assign Date		25/02/2022
2.	. Vehicle Particulars & Condition				
	Make & Model	NISSAN CWB45	c.c		13074
	Engine No.	HIDDEN	Year of Reg.		2008
	Chassis No.	CWB4CLP00102	Colour		WHITE
	Odometer	230434 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		SPORTS RIM
	General	GOOD			
3.	Conditions of Tyres				
		Size	Make		Balance
	R/H Front Tyre	295/80 R22.5	FALKEN		5 mm
	L/H Front Tyre	295/80 R22.5	FALKEN		5 mm
	R/H Rear Tyre	295/80 R22.5	FALKEN		5 mm
	L/H Rear Tyre	295/80 R22.5	FALKEN		5 mm
4.	Description of Damages				
	THE VEHICLE SUS	USTAINED DAMAGES AT THE REAR PORTION.			
5.	General Information				
	Accident Date	21/02/2022	Inspect Date / T	Γime	25/02/2022 (01:51 PM)
	Survey held at	24 LOYANG CRES LOYANG IND ESTATE S 508987			
	Repairer	TAN HUP SENG AUTO REPAIR WORKSHOP			
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D)MARKET VALUE:\$49,000.00				

Report Ref No. CS3/FCI22001815/Vtf3e2

Inspected By

THEVAN THOMAS KARTHIKESAVAN

The

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser