

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	MS FIRST CAPITA	L INSURANCE LTD		Ref:	CS3/FCI22001816/Rqf3e2	
	36 ROBINSON ROAD #16-01 CITY HOUSE SINGAPORE 068877			Date:	16/03/2022	
				Code:	FCI2	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SMB 5063X	Veh. Inspected		YP 5047C	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	D22000550MFBP	Excess (\$)		0.00	
	Assign From	HARMINDER KAUR	Assign Date		25/02/2022	
2.	2. Vehicle Particulars & Condition					
	Make & Model	ISUZU FVR34SUQDC	c.c		7790	
	Engine No.	HIDDEN	Year of Reg.		2016	
	Chassis No.	JALFVR347G7001257	Colour		YELLOW	
	Odometer	-	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	FAIR				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	275/70 R22.5	FALKEN		7 mm	
	L/H Front Tyre	275/70 R22.5	FALKEN		7 mm	
	R/H Rear Tyre	275/70 R22.5 (D)	FALKEN		7/7 mm	
	L/H Rear Tyre	275/70 R22.5 (D)	FALKEN		7/7 mm	
4.	Description of Damages					
	THE VEHICLE SUSPORTION.	STAINED DAMAGES AT THE FRONT AND REAR				
5.	General Information					
	Accident Date	21/02/2022	Inspect Date /	Time	25/02/2022 ( 03:13 PM )	
	Survey held at	Sin Ming Rd opp Blk 10 URA heavy vehicle park				
	Repairer	TAN HUP SENG AUTO REPAIR WORKSHOP				
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D)MARKET VALUE:\$88,000.00					

Report Ref No. CS3/FCI22001816/Rqf3e2

Inspected By

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

Automotive Assessor

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

REGD Auto Consultant-SAE, Licensed Appraiser