

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKT 8816A

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER (CONSISTENT)	CUT	1,128.60	1,047.00
1	RH REAR BUMPER RETAINER (CONSISTENT)	CUT	38.00	38.00
1	REAR BUMPER REVERSE SENSOR (CONSISTENT)	SERVICEABLE	360.00	-
1	REAR END PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	530.40	-
1	REAR BUMPER REFLECTOR RH (CONSISTENT)	CUT	53.00	53.00
1	REAR FENDER AIR VENT (CONSISTENT)	REUSE	87.00	-
	LESS 20% DISCOUNT		-	-227.60
			2,197.00	910.40
	SPECIAL NETT ITEMS			
1	REAR BUMPER CLIP (SN) (CONSISTENT)	NECESSARY	48.00	24.00
			48.00	24.00
	<u>LABOUR</u>			
	PANEL BEAT. INCLUSIVE OF THE REPAIR OF REAR END PANEL.		800.00	200.00
	SPRAY PAINT.		800.00	200.00
	CHECK WIRING.		100.00	30.00
	RUST PROOF.		100.00	30.00
	TO INSTALL REVERSE SENSOR. (NPA)	NOT NECESSARY		
			1,800.00	460.00
	GRAND TOTAL		4,045.00	1,394.40

RECOMMENDED COST OF LUMP SUM REPAIRS		1,100.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/ASM22001821/Vqy3e2



THEVAN THOMAS KARTHIKESAVAN

X.2.

**ADRIAN LING WAI PING** 

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

**Licensed Appraiser** 

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.