

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22001825/ANY3Q2**Date:** 16/01/2023**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00116792100

**Claimant Vehicle
No :** SMQ2183Z**Insured Vehicle
No :** GBF3781D

Date of Loss: 19/02/2022

Nature of Claim: TP

Claim
No: SNM22D201285/C02/CSC**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SMQ2183Z**

Make & Model: AUDI S5 SPORTBACK, 3.0 (A)

Engine No: CAK013043

Reg. Date: 22/09/2010 (Man. Year: 2010)

Chassis No: WAUZZZ8T0BA009985

Colour: Black

Odometer: 155756 km

Engine Capacity: 2995 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40 R19

Rear Tyre Size: 245/40 R19

Front Left Side: Continental 6 mm

Rear Left Side: Continental 6 mm

Front Right Side: Continental 6 mm

Rear Right Side: Continental 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,075.80	10,089.78	8,986.02	47.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,580.00	1,810.00	2,770.00	60.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,655.80	11,899.78	11,756.02	49.70
Approved Total (Overridden) (S\$)		9,500.00		
Nett Amount (S\$)	23,655.80	9,500.00	14,155.80	59.84

INSPECTION

Date of Assignment: 29/09/2022

Date Inspected: 24/02/2022 Inspected At:

T & C Automobile (HQ)
NO.1 KAKI BUKIT AVENUE 6 #01-71 AUTOBAY
Singapore 417883

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Jan 2023)
Parts:	M1-COUPE	AUDI S5 SPORTBACK 3.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMQ2183Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Repair	2,249.00 F	*- FL
2	1		*FRONT BONNET INSULATOR	Not Necessary	288.00 F	*- FL
3	1		*FRONT BONNET CATCH HOOK	Not Necessary	135.00 F	*- FL
4	2		*FRONT BONNET EDGE PROTECTION	Not Necessary	68.00 F	*- FL
5	1		*FRONT BONNET LID LOCK WITH MICRO SWITCH	Not Necessary	288.00 F	*- FL
6	1		*FRONT BUMPER	Distorted	2,138.00 F	*2,138.00 FL
7	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	880.00 F	*- FL
8	1		*FRONT BUMPER SUPPORT	O/S Cracked	88.00 F	*44.00 FL
9	1		*FRONT BUMPER FOG LAMP RHS	Cracked	299.80 F	*299.80 FL
10	1		*FRONT BUMPER FOG LAMP COVER RHS	Missing	168.50 F	*168.50 FL
11	1		*FRONT BUMPER NOZZLE COVER	Missing	120.00 F	*120.00 FL
12	1		*FRONT BUMPER TOW COVER	Not Necessary	48.00 F	*- FL
13	1		*FRONT BUMPER SENSOR	Damaged (1 PCS ONLY)	440.00 F	*220.00 FL
14	4		*FRONT BUMPER SENSOR HOLDER	Necessary	80.00 F	*80.00 FL
15	1		*FRONT GRILLE QUATTRO	Cracked	2,240.00 F	*1,680.00 FL
16	1		*FRONT GRILLE LOGO	Necessary	128.00 F	*128.00 FL
17	1		*FRONT GRILLE S5 EMBLEM	Necessary	118.00 F	*118.00 FL
18	1		*FRONT SUPPORT PANEL	Cracked	1,127.00 F	*1,127.00 FL
19	1		*OIL COOLER	Not Necessary	829.00 F	*- FL
20	1		*AIRCON CONDENSOR	Not Necessary	1,320.00 F	*- FL
21	1		*SECONDARY AIR PUMP	Cracked	1,047.90 F	*1,047.90 FL
22	1		*SECONDARY AIR PUMP UPPER HOSE	Not Necessary	199.80 F	*- FL
23	1		*SECONDARY AIR LOWER UPPER HOSE	Not Necessary	199.80 F	*- FL
24	1		*FRONT HEADLAMP RHS	Cracked	2,578.00 F	*2,578.00 FL
25	1		*FRONT HEADLAMP LOWER BRACKET RHS	Not Necessary	198.00 F	*- FL
26	1		*FRONT HEADLAMP LOWER NOZZLE	Cracked	220.00 F	*220.00 FL
27	1		*FRONT FENDER RHS	Dented	980.00 F	*980.00 FL
28	1		*FRONT FENDER INNER SHIELD	Torn	260.00 F	*195.00 FL
29	1		*SET BONNET INSULATOR CLIP	Not Necessary	60.00 FS	*- FS
30	1		*SET BUMPER CLIP	Necessary	60.00 FS	*30.00 FS
31	1		*FRONT NUMBER PLATE WIHT HOLDER	Not Necessary	60.00 FS	*- FS
32	1		*SET FENDER INNER SHIELD CLIP	Necessary	60.00 FS	*30.00 FS
33	1		*RADIATOR COOLANT	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	19,075.80	11,204.20
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	1,114.42
Total Parts (\$)	19,075.80	10,089.78

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING SERVICE	New	150.00	0.00
2	TO CHECK WIRING AND LIGHTING	New	80.00	30.00
3	TO REMOVE,REPLACE AND REFIX FRONT BUMPER SENSOR	New	100.00	50.00
4	TO REMOVE AND REFIX RADIATOR ASSY	New	150.00	0.00
5	TO REMOVE ,REFIX AND TOP UP AIRCON GAS	New	150.00	100.00
6	TO APPLY ANTI RUST PROOFING ON AFFECTED AREAS	New	100.00	30.00
7	TO PERFORM DIAGNOSTIC CHECK FOR FAULT CODES AND RESET FACTORY SETTINGS	New	250.00	100.00
8	TO PANEL BEAT AND REPLACE DAMAGED PARTS ON AFFECTED AREAS	New	1,800.00	900.00
9	TO PUTTY AND SPRAY PAINTINGS ON AFFECTED AREAS	New	1,800.00	600.00
Gross Labour Cost (S\$)			4,580.00	1,810.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >