

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22001826/KVY3N2**Date:** 10/03/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00134282101
<b>Claimant Vehicle No :</b>	SKB7819T	<b>Insured Vehicle No :</b>	GBJ22K
Date of Loss:	24/02/2022	Nature of Claim:	TP
		Claim No:	SNM22D201351/C02

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SKB7819T</b>	Engine No:	G4FCBH355435
Make & Model:	KIA CERATO, 1.6 (A)	Chassis No:	KNAFW411MB5451101
Reg. Date:	28/06/2011 (Man. Year: 2011)	Odometer:	191628 km
Colour:	White		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	235/45R17	Rear Tyre Size:	235/45R17
Front Left Side:	Continental 8 mm	Rear Left Side:	Continental 8 mm
Front Right Side:	Continental 8 mm	Rear Right Side:	Continental 8 mm

*The above values represent the remaining tyre tread depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,053.00	4,329.40	723.60	14.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,460.00	2,570.00	1,890.00	42.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>9,513.00</b>	<b>6,899.40</b>	<b>2,613.60</b>	<b>27.47</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>5,500.00</b>		
<b>Nett Amount (\$\$)</b>	<b>9,513.00</b>	<b>5,500.00</b>	<b>4,013.00</b>	<b>42.18</b>

**INSPECTION**

Date of Assignment:	25/02/2022	Guan Hin Motor Workshop (HQ) BLK 10 ANG MO KIO IND PARK 2A #02-03 AMK AUTOPOINT Singapore 568047
Date Inspected:	25/02/2022 Inspected At:	
Estimated Period of Repair:	9.0 days	

**Adjuster:** KENNETH KONG**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 09 Mar 2022)
<b>Parts:</b>	143	KIA CERATO 1.6 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKB7819T)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*GRILL	Mtg Cracked	225.00 F	*225.00 FL
2	1		*GRILL EMBLEM	Necessary	35.00 F	*35.00 FL
3	2		*HEAD LAMP	Mtg Cracked	860.00 F	*860.00 FL
4	1		*FRONT NO PLATE BASE	Cracked	28.00 F	*28.00 FL
5	1		*SUPPORT PANEL	Buckled	379.00 F	*379.00 FL
6	1		*FRONT BUMPER	Buckled	576.00 F	*576.00 FL
7	1		*FRONT BUMPER REINFORCEMENT	Repair	165.00 F	*- FL
8	1		*FRONT BUMPER SPONGE	Cracked	180.00 F	*162.00 FL
9	2		*FRONT BUMPER RETAINER	Serviceable	80.00 F	*- FL
10	1		*REAR BUMPER LOWER GARNISH	Dented	101.00 F	*101.00 FL
11	1		*REAR BUMPER REINFORCEMENT	Bent	302.00 F	*302.00 FL
12	1		*REAR END PANEL	Bent	262.00 F	*262.00 FL
13	1		*REAR BUMPER SPONGE	Cracked	180.00 F	*180.00 FL
14	1		*REAR BOOT	Buckled	948.00 F	*948.00 FL
15	1		*REAR BUMPER	Bent	548.00 F	*548.00 FL
16	1		*REVERSE SENSOR	Shorted	184.00 FS	*184.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>5,053.00</b>	<b>4,790.00</b>
<b>- List Item Discount on L Items 0.00/10.00% (\$)</b>	0.00	460.60
<b>Total Parts (\$)</b>	<b>5,053.00</b>	<b>4,329.40</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	CUTTING & WELDING REAR CENTRE PANEL AND STRAIGHTENING FLOOR BOARD AND REPLACEMENT REAR CENTRE PANEL,REPAIRING FLOORBOARD REPLACEMENT OF SUPPORT PANEL AND PARTS	New	1,800.00	1,200.00
2	SPRAY PAINTING	New	1,800.00	1,000.00
3	REMOVE & FIX BACK AIR CON & REFILL GAS	New	150.00	100.00
4	TO REMOVE AND INSTALL REAR REVERSE SENSOR	New	120.00	60.00
5	CHANGE REVERSE CAMER	New	100.00	0.00
6	FOCUS HEAD LAMP WIRING	New	50.00	40.00
7	TO REMOVE AND INSTALL REAR BOOT LOCK MECHANISM	New	60.00	50.00
8	REMOVE & INSTALL REAR INNER GARNISH AND TRIM TO FACILITATE THE REPAIR	New	180.00	60.00
9	ANTI RUST	New	200.00	60.00
<b>Gross Labour Cost (\$)</b>			<b>4,460.00</b>	<b>2,570.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >