

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: 22.29474 Date: 11th Apr 2022

Our Ref: CS3/ASM21008939/Gvy3e2-1

M/s Axa Insurance Pte Ltd

C/o: Seah Ong & Partners LLP 36 Robinson Road #12-03 City House Singapore 068877 (The Motor Claims Department)

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: XE 3058D INSURED VEHICLE: SHC 7034X ACCIDENT DATE: 21/08/2021

We thank you for your instruction on 25/02/2022.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of XE 3058D from M/s Carlink Consultancy.
- b) Singapore Accident Statement of Vehicle XE 3058D and SHC 7034X.
- c) Police Report of Vehicle XE 3058D.
- d) Colour damaged vehicle photographs of XE 3058D.

Pre-Repair Inspection Date: 26/08/2021 at M/s Eng Soon Huat Engineering Works, Blk 1003 Eunos Ave 8 #01-55 Eunos Ind Estates, Singapore 409498.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : XE 3058D

Make & Model : Hino FS1EKMD-KAS

Year of Registration : 2017

Chassis Number : FS1EKM10032 Engine Capacity : 12913 cc

- 2. We recommend that the repairs of the entire damage require about _____ 2 (Two) ____ working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.