

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG22001836/UTF3E2

Date: 29/03/2022

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 30001762924
Claimant Vehicle No : FBP3512L Insured Vehicle No : GX8823E
Date of Loss: 14/02/2022 Nature of Claim: TP Claim No: 269846

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBP3512L**
Make & Model: YAMAHA CZD300A / XMAX300, 292cc Engine No: H336E0047101
Reg. Date: 23/03/2019 (Man. Year: 2018) Chassis No: MH3SH0844KK005638
Colour: Grey Odometer: 83591 km
Engine Capacity: 292 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 120-70-15 Rear Tyre Size: 140-70-14
Front Left Side: Maxxis 5 mm Rear Left Side: Maxxis 5 mm
Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,034.40	2,600.70	4,433.70	63.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,810.00	300.00	1,510.00	83.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,844.40	2,900.70	5,943.70	67.20
Approved Total (Overridden) (S\$)		2,600.00		
Nett Amount (S\$)	8,844.40	2,600.00	6,244.40	70.60

INSPECTION

Date of Assignment: 25/02/2022
Date Inspected: 28/02/2022 Inspected At: Erofia Motor Trading Pte Ltd - (kaki Bukit) (HQ)
1 Kaki Bukit Avenue 6, #02-62 AutoBay @ Kaki Bukit
Singapore 417883
Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 09 Mar 2022)	
Parts:	N/A	YAMAHA CZD300A / XMAX300 292cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBP3512L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FORK ASSY	Not Necessary	980.00 FL	*- FL
2	1		*FORK UNDER BRACKET COVER	Not Necessary	190.00 FL	*- FL
3	1		*FRONT SPORT RIM	Not Necessary	550.00 FL	*- FL
4	1		*FRONT BRAKE DISC	Not Necessary	180.00 FL	*- FL
5	1		*FRONT RIM SHAFT	Not Necessary	52.00 FL	*- FL
6	1		*HEADLAMP - LED	Cracked	1,380.00 FL	*685.00 FL
7	1		*SIDE MIRROR N/S	Cut	180.00 FL	*98.00 FL
8	1		*HANDLE-BAR	Not Necessary	135.00 FL	*- FL
9	1		*SET HANDLE-BAR BALANCER	Not Necessary	125.00 FL	*- FL
10	1		*SET HAND GRIP	Not Necessary	60.00 FL	*- FL
11	1		*SET BRAKE LEVERS	Not Necessary	150.00 FL	*- FL
12	1		*SET FRONT COWLING INNER PANEL CARBON	Cut	300.00 FL	*260.00 FL
13	1		*FRONT INNER PANEL	Cut	160.00 FL	*142.00 FL
14	1		*FRONT COVER	Cracked	440.00 FL	*320.00 FL
15	1		*FRONT FENDER	Cut	150.00 FL	*145.00 FL
16	1		*FRONT SIGNALS	N/S Not Necessary /O/S Cracked	150.00 FL	*75.00 FL
17	2		*FOOTSTEP PANELS	Cut	310.00 FL	*250.00 FL
18	1		*MAIN STAND	Cut	148.00 FL	*148.00 FL
19	1		*AIR FILTER COVER	Serviceable	218.00 FL	*- FL
20	1		*BELT COVER	Serviceable	180.00 FL	*- FL
21	1		*SET FAIRING COVER	Cut / Cracked	1,320.00 FL	*700.00 FL
22	1		*SIDE STAND	Repair	98.00 FL	*- FL
23	2		*FORK OILS	Not Necessary	30.00 FS	*- FS
24	2		*FORK OIL SEALS	Not Necessary	56.00 FS	*- FS
25	1		*SET STEERING CONE	Not Necessary	120.00 FS	*- FS
26	1		*SET NUMBER PLATE	Not Necessary	38.00 FS	*- FS
27	1		*X MAX EMBLEM	Necessary	80.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,780.00	2,883.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	745.60	282.30
Total Parts (\$\$)	7,034.40	2,600.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING AND RESET HEADLAMP FOCUSING	New	80.00	0.00
2	TO PROVIDE LABOUR	New	480.00	300.00
3	TO REPAIR BODY FRAME	New	450.00	0.00
4	TO RE-SPRAY PAINTING	New	800.00	0.00
5	TO PROVIDE TOWING SERVICE (LOD) S\$100.00	New	0.00	0.00
			Gross Labour Cost (\$)	300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >