



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLT 5555K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT BUMPER	NOT NECESSARY	871.90	-
1	FRONT BUMPER-LOWER	NOT NECESSARY	228.00	-
1	O/S FRONT FENDER	DENTED / WARPED	667.35	667.35
1	O/S FRONT FENDER ARCH GARNISH	GRAZED	161.00	161.00
1	O/S FRONT FENDER INNER SHIELD	NOT NECESSARY	143.95	-
1	O/S FRONT DOOR	TO REPAIR SEE LABOUR	1,209.80	-
1	O/S FRONT DOOR PROTECTOR	CUT	92.35	92.35
1	O/S FRONT DOOR EMBLEM	NECESSARY	98.35	98.35
1	O/S ROCKER PANEL SKIRT	CUT	245.70	245.70
1	O/S FRONT RIM	CUT	1,117.40	1,117.40
1	O/S FRONT WHEEL BEARING	NOT NECESSARY	511.30	-
1	O/S FRONT KNUCKLE ARM	NOT NECESSARY	573.30	-
1	O/S FRONT LOWER ARM	NOT NECESSARY	475.10	-
1	O/S FRONT SHOCK ABSORBER	NOT NECESSARY	462.10	-
1	REAR BUMPER LOWER GARNISH (SCRATCHED)	NOT CONSISTENT WITH THE IMPACT	582.60	-
1	O/S FRONT DOOR RUBBER	NOT NECESSARY	179.65	-
	LESS 5% DISCOUNT		-380.99	-119.11
			7,238.86	2,263.04
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET O/S FRONT FENDER INNER SHIELD CLIP (SN)	NECESSARY	50.00	50.00
1	O/S FRONT TYRE (SN)	SERVICEABLE	300.00	-
1	SET FRONT BUMPER CLIP (SN)	NOT NECESSARY	50.00	-
1	SET REAR BUMPER CLIP (SN)	NOT NECESSARY	50.00	-
			450.00	50.00
	<b><u>LABOUR</u></b>			
	TO CHECK LIGHT AND WIRING.		50.00	20.00
	TRANSFER DOOR PARTS.	NOT NECESSARY	120.00	-
	TO DIAGNOSE AND REPROGRAM.		200.00	50.00
	COMPUTERIZED WHEEL ALIGNMENT.		120.00	60.00

Report Ref No. CS/SMO22001838/Uqf3n2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	INSTALL REVERSE SENSOR.	NOT NECESSARY	80.00	-
	LABOUR/PANEL BEATING.INCLUSIVE OF THE REPAIR OF O/S FRONT DOOR.		700.00	500.00
	SPRAY PAINTING.1 ) FRT BUMPER,2) BONNET,3) O/S FRT FENDER,4) O/S FRT DOOR,5) O/S RR DOOR,6) O/S RR FENDER,7) RR BUMPER.		1,500.00	900.00
	REPLACE FRONT UNDERCARRIAGE.	NOT NECESSARY	200.00	-
			2,970.00	1,530.00
<b>GRAND TOTAL</b>			<b>10,658.86</b>	<b>3,843.04</b>

<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>3,050.00</b>
---	--	--	--	-----------------

Report Ref No. CS/SMO22001838/Uqf3n2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.