

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22001839/EVY3Q2**Date:** 01/04/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00078912104		
<b>Claimant Vehicle No :</b>	GX5409M	<b>Insured Vehicle No :</b>	GW7073P		
Date of Loss:	23/02/2022	Nature of Claim:	TP	Claim No:	SNM22D201356/C02/TANCHC

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>GX5409M</b>	Engine No:	4M40GM9084
Make & Model:	mitsubishi FB511BOJSRDE, 2.8 D (M)	Chassis No:	FB511BA46048
Reg. Date:	30/06/2004 (Man. Year: 2004)	Odometer:	75430 km
Colour:	White		
Engine Capacity:	2835 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	195 R15C	Rear Tyre Size:	195 R15C
Front Left Side:	Dunlop 4 mm	Rear Left Side:	Dunlop 4 mm
Front Right Side:	Dunlop 4 mm	Rear Right Side:	Dunlop 4 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,299.00	2,803.50	495.50	15.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,180.00	990.00	1,190.00	54.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>5,479.00</b>	<b>3,793.50</b>	<b>1,685.50</b>	<b>30.76</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,050.00</b>		
<b>(S\$)</b>	5,479.00	3,050.00	2,429.00	44.33
<b>+ GST 7.00/7.00% (S\$)</b>	383.53	213.50	170.03	44.33
<b>Nett Amount (S\$)</b>	<b>5,862.53</b>	<b>3,263.50</b>	<b>2,599.03</b>	<b>44.33</b>

**INSPECTION**

Date of Assignment:	25/02/2022	
Date Inspected:	08/03/2022	Inspected At: Wah Hong Motors & Credit Pte Ltd (HQ) 38 Toh Guan Road East, #01-57, Enterprise Hub Singapore 608581
Estimated Period of Repair:	3.0 days	

**Adjuster:** CHEN TSUE YEE**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 01 Apr 2022)	
<b>Parts:</b>	N/A	mitsubishi FB511BOJSRDE 2.8 D (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for GX5409M)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT PANEL LOGO BADGE	Necessary	75.00 FL	*75.00 FL
2	1		*FRONT PANEL EMBLEM CANTER	Necessary	100.00 FL	*100.00 FL
3	1		*FRONT SIDE TOP PANEL LH	Dented	739.00 FL	*739.00 FL
4	1		*CENTER GRILLE	Cut	619.00 FL	*619.00 FL
5	1		*HEADLAMP LH	Broken	584.00 FL	*584.00 FL
6	1		*SIDE LAMP LH	Broken	223.00 FL	*223.00 FL
7	1		*SIGNAL LAMP LH	Cut	237.00 FL	*237.00 FL
8	1		*FRONT BUMPER	Crushed	444.00 FL	*444.00 FL
9	1		*FRONT DOOR OUTER LOWER GARNISH LH	Missing	209.00 FL	*209.00 FL
10	1		*FRONT DOOR LOWER SIGNAL LAMP LH	Cracked	248.00 FL	*248.00 FL
11	1		*FRONT DOOR RUBBER SEAL LH	Not Necessary	58.00 FL	*- FL
12	1		*FRONT DOOR WEATHERSTRIP LH	Not Necessary	416.00 FL	*- FL
13	1		*FRONT PANEL (REPAIR REFER TO LABOUR) (NPA)	Repair	0.00 FL	*- FL
14	1		*FRONT DOOR LH (REPAIR REFER TO LABOUR )(NPA)	Repair	0.00 FL	*- FL
15	1		*FRONT BUMPER CLIPS	Necessary	35.00 FS	*20.00 FS
16	1		*FRONT DOOR COMPANY DECAL LH	Necessary	25.00 FS	*25.00 FS
17	1		*FRONT DOOR COMPANY STICKER LH	Necessary	200.00 FS	*150.00 FS
18	2		*HEADLAMP LIGHT BULB LH	Not Necessary	50.00 FS	*- FS
19	1		*SIDE LAMP LIGHT BULB LH	Not Necessary	25.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>4,287.00</b>	<b>3,673.00</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	988.00	869.50
<b>Total Parts (\$\$)</b>	<b>3,299.00</b>	<b>2,803.50</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS ,PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACE THE DAMAGED PARTS AND COMPONENTS	New	1,000.00	400.00
2	TO SUPPLY PAINT MATERIALS EXPANDABLE ITEMS & PUTTY ,RESPRAY PAINT ON PARTS REPLACED & REPAIRED	New	1,000.00	500.00
3	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	New	60.00	30.00
4	TO REMOVE AND REPAIR /REFIT WIRING SYSTEM AT ACCIDENT DAMAGED AREA AND CHECK FOR ALL ELECTRICAL PROPER FUNCTION	New	60.00	30.00
5	TO REMOVE ,REPLACE AND FOCUS HEADLAMP BEAM	New	60.00	30.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,180.00</b>	<b>990.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >