LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.

Our File No: CC3/AIG22001843/AVY3E2

AIG Building, 78 Shenton Way, #09-16

Singapore 079120 **Date:** 20/09/2022

REFERENCE

Insured/Claimant: LOW SIEW TEE SERENE MRS SERENE SORENSEN Policy No: 2000002749-01

Date of Loss: 30/08/2021 Nature of Claim: OD Claim No: 4316552321SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKE688J

Make & Model: AUDI Q7, 2.0 TFSI QU (A) Engine No: CYR091811

Reg. Date: 20/01/2020 (Man. Year: 2019) Chassis No: WAUZZZ4M7KD034346

Colour: Blue Odometer: 33362 km

Engine Capacity: 1984 cc
Market Value/New Car Price: \$\$230,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 255/55R19 Rear Tyre Size: 255/55R19

Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		7,807.00	5,394.24	2,412.76	30.91
Miscellaneous Items		0.00	0.00	0.00	
Labour		5,942.00	2,892.00	3,050.00	51.33
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	13,749.00	8,286.24	5,462.76	39.73
	- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
	(S\$)	12,749.00	7,286.24	5,462.76	42.85
	+ GST 7.00/7.00% (S\$)	892.43	510.04	382.39	42.85
	Nett Amount (S\$)	13,641.43	7,796.28	5,845.15	42.85

INSPECTION

Date of Assignment: 28/02/2022

Date Inspected: Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1

Singapore 408699

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR-RH	Dented	5,311.00 FS	*4,248.80 FS
2	1		*REAR DOOR OUTER SEAL-RH	Necessary	250.00 FS	*200.00 FS
3	1		*BONDING AGENT	Not Necessary	49.00 FS	*- FS
4	1		*CLEANING SOLUTION	Not Necessary	68.00 FS	*- FS
5	1		*APPLICATOR	Not Necessary	8.00 FS	*- FS
6	1		*REAR DOOR ATTACHMENT PARTS	Not Necessary	99.00 FS	*- FS
7	1		*REAR DOOR CATCH-RH	Not Necessary	105.00 FS	*- FS
8	1		*REAR DOOR SEAL,OUTER-RH	Not Necessary	191.00 FS	*- FS
9	1		*SILL PANEL SEAL-RH	Not Necessary	253.00 FS	*- FS
10	1		*REAR DOOR COVER-RH	Necessary	600.00 FS	*479.60 FS
11	1		*REAR WHEEL ARCH COVER-RH	Necessary	196.00 FS	*156.80 FS
12	1		*REAR WHEEL ARCH COVER-RH	Necessary	377.00 FS	*301.20 FS
13	1		*SUNDRIES	Necessary	300.00 FS	*7.84 FS
F=Fra	anchise	part. S=SpcN	ett.	-		
				Total Parts (S\$)	7,807.00	5,394.24
			Report was unsubmitted	during this print out		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	TO REMOVE AND TRANSFER RHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES.INSPECT FOR DAMAGES	New	450.00	300.00
2	TO REMOVE AND RENEW RHS REAR DOOR.TO REPAIR RHS REAR FENDER.TO RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	1,800.00	600.00
3	TO RESPRAY RHS REAR DOOR,DOOR COVER,RHS REAR FENDER,RHS REAR DOOR ARCH TRIM AND RHS REAR WHEEL ARCH TRIM	New	3,500.00	1,800.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
	Gross Labour Cost (S\$)		5,942.00	2,892.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >