

CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD**  
**EUNOS LINK SERVICE CENTRE**

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

**ESTIMATE**

Invoice Name & Address	Owner Name & Vehicle Info
MS First Capital Insurance Limited 36 Robinson Road #16-01 City House Singapore 068877	Cust No/Name /Mr Koh Chen Kiat Reg No/Reg Date SMM3371L / 26/06/2019 Date In/Mileage 25/02/2022/ 0 Chassis No MMBSTA13AKH001531 Engine No 3A92UHS1225 Make/Model MIT/19MY ATTRAGE 1.2 CVT Colour/Trim P57 / BK
Contact No	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
F0000034	Credit	01/03/2022/ 12:46	Bod	303 / Renemer	27009
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M JJ5379A473	LH PANEL,AIR GUIDE	1.00	9.00	0.00	9.00
M JJ5379A474	RH PANEL,AIR GUIDE	1.00	9.00	0.00	9.00
M JJMU001623	CLIP,AIR GUIDE	6.00	4.00	0.00	24.00
M JJ1360A090	PANEL,AIR GUIDE	1.00	112.00	0.00	112.00
M JJ1350A670	RADIATOR ASSY	1.00	967.00	0.00	967.00
M JJ1355A280	FAN,COOLING	1.00	77.00	0.00	77.00
M JJ1355A278	SHROUD,COOLING FAN	1.00	131.00	0.00	131.00
M JJ1355A356	MOTOR,COOLING FAN	1.00	479.00	0.00	479.00
M JJ7812A339	CONDENSER ASSY,A/C R	1.00	758.00	0.00	758.00
Z	NOTES				

SUPPLEMENTARY ITEMS


Estimate

Confirm &amp; accepted by

Parts	2,566.00
Labour	0.00
Standard Menu	0.00
Specialist Job	0.00
Others(Lub,etc)	0.00
Sundry	0.00
Total(w/o GST)	2,566.00

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD  
EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



## ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info	
MS First Capital Insurance Limited 36 Robinson Road #16-01 City House Singapore 068877  Contact No	Cust No/Name	/Mr Koh Chen Kiat
	Reg No/Reg Date	SMM3371L / 26/06/2019
	Date In/Mileage	01/03/2022/ 39989
	Chassis No	MMBSTA13AKH001531
	Engine No	3A92UHS1225
	Make/Model	MIT/19MY ATTRAGE 1.2 CVT
	Colour/Trim	P57 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
F0000034	Credit	07/03/2022/ 11:49	DS	218 / Mars Ler	27009			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	JJ7415A603	MARK, THREE-DIA	ADD	NEE	1.00	70.00	0.00	70.00
Z	NOTES							
SUPPLEMENTARY ITEM								
Estimate								

Confirm &amp; accepted by

Parts	70.00
Labour	0.00
Standard Menu	0.00
Specialist Job	0.00
Others(Lub,etc)	0.00
Sundry	0.00
Total(w/o GST)	70.00

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.