



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLN 8476S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DEFORMED	1,128.60	1,028.00
2	REAR BUMPER SIDE HOLDER @\$38.00	NOT NECESSARY	76.00	-
2	REAR BUMPER REFLECTOR @\$53.60	NOT NECESSARY	107.20	-
1	REAR BUMPER REINFORCEMENT	DENTED	564.20	564.20
4	REVERSE SENSORS @\$205.00	DAMAGED (2 PCS ONLY)	820.00	410.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	530.40	-
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	214.20	-
	LESS 20% DISCOUNT		-	-400.44
			3,440.60	1,601.76
	<u>SPECIAL NETT ITEMS</u>			
1	REAR BUMPER CLIPS (SN)	NECESSARY	30.00	30.00
1	REAR END PANEL TOP GARNISH CLIPS (SN)	NOT NECESSARY	20.00	-
1	REAR END PANEL SEALANT (SN)	NOT NECESSARY	60.00	-
			110.00	30.00
	<u>LABOUR</u>			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR END PANEL.		800.00	250.00
	SPRAY PAINTING.		800.00	300.00
	WIRING.		50.00	30.00
	TO REMOVE REVERSE SENSOR.		100.00	60.00
	TO SPRAY TUFF COAT.	NOT NECESSARY	150.00	-
	TO REMOVE UPHOLSTERY.	NOT NECESSARY	150.00	-
			2,050.00	640.00
	GRAND TOTAL		5,600.60	2,271.76



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,800.00
---	--	--	-----------------

Report Ref No. CS/AGI22001856/Aqf3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.