

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGR 512L

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DEFORMED	704.16	704.16
1	REAR BUMPER LOWER	CUT	250.56	250.56
1	REAR BUMPER REFLECTOR RH	NOT NECESSARY	109.26	-
1	REAR BUMPER RETAINER RH	NOT NECESSARY	74.25	-
1	REAR TAILLAMP RH	NOT NECESSARY	804.60	-
	LESS 20% DISCOUNT		-388.57	-190.94
			1,554.26	763.78
	SPECIAL NETT ITEMS			
1	REAR BUMPER CLIPS (SN)		40.00	40.00
			40.00	40.00
	<u>LABOUR</u>			
	TO DISCONNECT AND RECONNECT, CHECK ELECTRICAL WIRING HARNESS WIRE, SOCKETS, REPLACE DAMAGED PARTS.		30.00	30.00
	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS. TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS.		350.00	200.00
	TO SPRAY PAINTING ON THE REPLACED AND REPAIR PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING AND SANDING OF SURFACES, FINAL POLISHING AND WAXING ARE ALSO AVAILABLE.		500.00	220.00
			880.00	450.00
	GRAND TOTAL		2,474.26	1,253.78

RECOMMENDED COST OF LUMP SUM REPAIRS		1,000.00
(TO ITS PRE-ACCIDENT CONDITION)		·

Report Ref No. CS/SMR22001858/Tny3m4

**MOHAMAD TAUFIKH** 

M.MATAI, AMSAE-A

**ANG BRYAN TANI** 

**Automotive Assessor / Investigator** 

**Automotive Assessor** 

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.