S. REC. BY: Taylor REF: CS / 17G122	IGNMENT
Date: Date: DiffP WS TP RES OD RES EVA INV MV Dispect Vehicle No: Workshop m/s financed:	Veh No: GRL 2964T Yr Regn: 2021 14pml, Type: M.Carl M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or Make: Nisan NV2001-64 c.c / 592. Colour / Make: A/C: Insured / Std / NI / NA Sp.Reading 12585 T/Radio: Insured / Std / NI / NA Eng/No: C/No: TWISHAM 20* 2000 / 356
Claims No. Sum Insured: Excess:	Gen. Cond: Good / Fair / Poor / Burnt Steering: Inorder / Jammed / Leaked / Burnt or Brake: Inorder / Jammed / Leaked / Burnt or
(Client's Record) Make of Veh: (Policy Condition) Remark: The veh had commenced its repair at the time of inspection. Bal. or Market Value: IDAC Accident Rport: GIA / PR Seen: Est. Repairs: Lum Sum: CA / REV / REP. / 24 HRS Date: Date / Time Action / Instruction Consistent?: Vehicle: IN	Front R/Bal. L/Bal. D.O.A. Survey held at Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Date/Time, File Pass to? 1) Date/Time, File Return to? 2) Representation: Learner Steam / L.B.J.: (**)	Days Of Repair: Resurvey No. of Trip: Survey Fee: Transportation: S + RS_SI Photos Total

Estimate Report

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Mega@Woodlands, 39 Woodlands Close #01-12

Singapore 737856 Tel: Fax: Email:

INSURER:

PARTICULARS OF CLAIM

Claim Type:

Policy No:

Vehicle Reg. No.:

Driver Age: Any Injuries?

Insured/Claimant:

DMCVSNW00050182100

GBL2964T

GPM BUILDERS PTE LTD

Ref. No:

Date of Loss:

Driveable?

Third Party Vehicle No.:

Contact No:

Driver:

SML4411D

21/02/2022

ves

BADRI ADHIESWARA GANGADURGA **NETHIKONDA**

YTMG/TP/2202/004

PARTS MODEL

Make/Model:

Vehicle Colour:

Chassis No:

Total Loss?

Nissan, NV200 -

JN1YBAM20U

Engine Number:

Vehicle Reg. Date:

Odometer

Est. Duration of Repair(Day)

DESCRIPTION OF ACCIDENT/LOSS

Description of Accident/loss REFER TO ATTACHED

Remarks:

Present Location:

Yew Tee Automobile Tech Pte Ltd (Mega)-YTMG

Amount **COST OF CLAIMS** 7,100.17 Parts 810.00 Miscellaneous Items 1,390.00 Labour 1,000.00 Paintwork Labour 0.00 Towing

Gross Total(S\$): GST 7.00%(S\$): Nett Amount(S\$): 10,300.17 721.01 11.021.18

This claim is handled by: Tee Shu yi

Estima	ites On Pai	rts		ROD B		
No.	Qty	Particulars	Amount	%Disc	After Disc	
1	1	REAR BUMPER	878.40	-30.00	614.88	
2	1	REAR BUMPER SIDE RETAINER RH	88.90	-30.00	62.23 ×	
3	1	REAR BUMPER SIDE RETAINER LH	88.90	-30.00	62.23	
4	1	REAR BUMPER INNER SPONGE	121.50	-30.00	85.05 7	
5	1	REAR TAILGATE	1,895.60	-30.00	1,326.92 bt-	
6	1	REAR TAILGATE INNER BOARD	337.50	-30.00	236.25 ×	
7	1	REAR TAILGATE LOGO	103.10	-30.00	72.17 Mer	
88	1	REAR TAILGATE OUTER GARNISH	243.60	-30.00	170.52 ×	
9	1	REAR OUTER GARNISH LAMP RH	378.10	-30.00	264.67 ×	
10	1	REAR OUTER GARNISH LAMP LH	378.10	-30.00	264.67 ≈	
11	1	REAR WINDSCREEN SEALANT	108.90	-30.00	76.23	
12	1	REAR END PANEL	877.50	-30.00	614.25 7	
13	1	REAR END PANEL REINFORCEMENT	1,334.60	-30.00	934.22	
14	1	REAR FLOOR PANEL	2,025.90	-30.00	1,418.13 RY	
15	1	REAR FENDER LH	1,282.50	-30.00	897.75 X	
		Т	otal Parts (S\$)		7,100.17	
Estima	ates of Mis	cellaneous Items				
No.	Qty	Particulars	Amount	%Disc	After Disc	
1	1	REAR BUMPER SENSOR	200.00	0.00	200.00 MM	
2	1	REAR TAILGATE 70KM/H STICKER	60.00	0.00	60.00 nej-	
3	1	REAR TAILGATE NV200 EMBLEM	60.00	0.00	60.00 nes	
4	1	REAR TAILGATE VANETTE EMBLEM	80.00	0.00	80.00 NO	
5	1	REAR TAILGATE 6PAX STICKER	60.00	0.00	60.00 ne	
6	1	REAR CAMERA	350.00	0.00	350.00 ⋉	
			Sub Total (S\$)		810.00	
Estim	ates On La	abour	24 × 1012 man	16.680		
	ates On La Qty	Particulars	Amount	%Disc	After Disc	
No.			The 100.00	%Disc	100.00 Go	
No. 1	Qty	Particulars To Remove And Refit Carpet And Trims On TRear Section To Give Way To The Repair on The Rear Section. To Remove and Refit Rear Bumper Sensor.	The 100.00		Disc	
No. 1	Qty 1	Particulars To Remove And Refit Carpet And Trims On TRear Section To Give Way To The Repair on The Rear Section.	The 100.00	0.00	100.00 Go	
No. 1 2 3	Qty 1	Particulars To Remove And Refit Carpet And Trims On TRear Section To Give Way To The Repair on The Rear Section. To Remove and Refit Rear Bumper Sensor.	The 100.00 80.00 80.00	0.00	100.00 Go	
No. 1 2 3 4	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Particulars To Remove And Refit Carpet And Trims On TRear Section To Give Way To The Repair on The Rear Section. To Remove and Refit Rear Bumper Sensor. To Transfer Rear Tailgate.	80.00 80.00 80.00 100.00	0.00	100.00 Go 80.00 70 80.00 60	
No.	1 1 1 1 1	Particulars To Remove And Refit Carpet And Trims On TRear Section To Give Way To The Repair on The Rear Section. To Remove and Refit Rear Bumper Sensor. To Transfer Rear Tailgate. To Dismantle and Refit Rear Windscreen Gla To Disconnect and Reconnect, Check Electric wiring Harness Wire, Sockets, Replace	80.00 80.00 80.00 100.00 cal 30.00 d 1,000.00	0.00 0.00 0.00 0.00	80.00 20 80.00 60 100.00 60	

lo.	Qty	Particulars		Amount	%Disc	After	
1	1	To Spray painting on the Re Parts, Prepare Spray Such the unaffected areas with p Sanding of Surfaces, Final Waxing are also available.	as Masking Tape aper, Cleaning and	1,000.00	0.00	1,000.00	700
			Gross Labou	r Cost (S\$)		1,000.00	
		< EN	S >				
		7	Tauphi 97	495749	16256	3561	
			wp 4/3/2	1 6 1115			
			taufikh @ /M	antion			
		45	Tauphi 97 N° 4/3/2 to 4 fikh @ 1 M Today Resum spec	repair			
				LKK Auto Con the Repairer o • To resurvey befo • To display dama • Parts prices are • Third party survo • No illegal modifi • Supplementary is subject to fina	f the following ore/after spray pa- sped part(s) during subject to confirm ey is on a "Withon cation(s) is allow item(s) must be re-	g: ainting ng resurvey mation ut Prejudice" basi red	
				Acknowledged by Signature: Date:	Repairer		