

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG22001860/RQF3N2**Date:** 10/06/2022REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 1000909271

Claimant Vehicle No : PA8051E**Insured Vehicle No :** SJD1673L

Date of Loss: 24/02/2022

Nature of Claim: TP Claim No: 270475

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **PA8051E**

Make & Model: TOYOTA HIACE, 3.0 D X (M)

Engine No: 1KD1793118

Reg. Date: 06/08/2008 (Man. Year: 2008)

Chassis No: KDH2010019651

Colour: Grey

Odometer: 665391 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195R15C

Rear Tyre Size: 195R15C

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,486.76	2,277.45	1,209.31	34.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,020.00	1,110.00	910.00	45.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,506.76	3,387.45	2,119.31	38.49
Approved Total (Overridden) (S\$)		2,700.00		
(S\$)	5,506.76	2,700.00	2,806.76	50.97
+ GST 7.00/7.00% (S\$)	385.47	189.00	196.47	50.97
Nett Amount (S\$)	5,892.23	2,889.00	3,003.23	50.97

INSPECTION

Date of Assignment: 28/02/2022

Date Inspected: 01/03/2022

Inspected At:

Connect3 (HQ)
566 Woodlands Road
Singapore 728697

Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 Jun 2022)
Parts:	213	TOYOTA HIACE 3.0 D X (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PA8051E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Scratched	735.10 F	*735.10 FL
2	1		*FRONT BUMPER BRACKET LH	Not Necessary	112.36 F	*- FL
3	10		*FRONT BUMPER CLIPS	Necessary	25.00 F	*25.00 FL
4	1		*FRONT BUMPER INNER DUCT	Not Necessary	337.80 F	*- FL
5	1		*LH HEADLAMP	Cracked	389.40 F	*389.40 FL
6	1		*LH PASSENGER DOOR	Bent	1,887.10 F	*1,887.10 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	3,486.76	3,036.60
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	759.15
Total Parts (\$\$)	3,486.76	2,277.45

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SPRAY PAINTING	New	800.00	500.00
2	APPLY ANTI RUST	New	50.00	30.00
3	CHECK WIRING	New	20.00	20.00
4	TRANSFER DOOR FITTING	New	150.00	60.00
5	LABOUR CHARGES	New	1,000.00	500.00
Gross Labour Cost (\$)			2,020.00	1,110.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >