Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte.

Ltd.

4 Shenton Way

#21-01 SGX Centre 2 Singapore 068807

From: LKK Auto Consultants Pte Ltd

: 24/02/2022

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park

Assignment Date: 28/02/2022

• 4

Singapore 408933

Accident Date

Est. Duration of

Repair

Attn: Douglas Ong Chu Chong Date: 16 Mar 2022

Preliminary Advice

Insured : SJD1673L

Vehicle No

TP Vehicle : PA8051E No

Make : TOYOTA HIACE

Date of Inspection

: 01/03/2022

Inspection At: CONNECT3 (HQ)

566 WOODLANDS ROAD

SINGAPORE 728697

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross) :S\$ 5,506.76 **Revised Amount** :S\$ 2,717.55 Check Items (Estimated) :S\$ 0.00

Total :S\$ 2,717.55

Lump Sum Repair :S\$ 2,150.00

Total Loss Consideration

New for Old Value :S\$ Pre-Accident Value :S\$ COE / PARF Rebate :S\$ Salvage Value :S\$
Margin for Repair :S\$

Remarks	Re	ma	rks
---------	----	----	-----

)	The vehicle is economical for repair
)	The vehicle is not economical for repair
)	Part-by-Part repair
Χ)	Lump Sum repair

(X) The above survey was conducted on a 'without prejudice' basis. Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.