

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22001861/ATY3Q2**Date:** 30/05/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00149882100
Claimant Vehicle No :	SLE1983M	Insured Vehicle No :	SJF6454J
Date of Loss:	25/02/2022	Nature of Claim:	TP
		Claim No:	SNM22D201411/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLE1983M	Engine No:	LEB5079510
Make & Model:	HONDA VEZEL, 1.5 X HYBRID CVT (A)	Chassis No:	RU31129490
Reg. Date:	12/07/2016 (Man. Year: 2016)	Odometer:	97807 km
Colour:	Grey		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,245.86	5,851.43	3,394.43	36.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,230.00	1,890.00	2,340.00	55.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	13,475.86	7,741.43	5,734.43	42.55
Approved Total (Overridden) (\$\$)		6,200.00		
(\$\$)	13,475.86	6,200.00	7,275.86	53.99
+ GST 7.00/7.00% (\$\$)	943.31	434.00	509.31	53.99
Nett Amount (\$\$)	14,419.17	6,634.00	7,785.17	53.99

INSPECTION

Date of Assignment:	28/02/2022	
Date Inspected:	28/02/2022	Inspected At: Success United Pte Ltd (HQ) 2 Kaki Bukit Ave 2 #01-33, Kaki Bukit AutoHub Singapore 417921
Estimated Period of Repair:	6.0 days	

Adjuster: ADRIAN LING**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 May 2022)
Parts:	M1-SUV	HONDA VEZEL 1.5 X HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLE1983M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Distorted	1,286.70 FL	*1,100.00 FL
2	2		*REAR BOOT HINGE L/R	Not Necessary	127.40 FL	*- FL
3	1		*REAR BOOT LID VEZEL EMBLEM	Necessary	65.00 FL	*65.00 FL
4	1		*REAR BOOT LID HYBRID EMBLEM	Necessary	86.20 FL	*86.20 FL
5	1		*REAR WINDSCREEN MOULDING	Necessary	110.00 FL	*110.00 FL
6	1		*REAR WIPER MOTOR	Not Necessary	392.50 FL	*- FL
7	2		*REAR BOOT DAMPER L/R	Not Necessary	330.00 FL	*- FL
8	1		*REAR BOOT LID WEATHERSTRIP	Cut	154.82 FL	*154.82 FL
9	1		*REAR BOOT LID MECHANISM LOCK	Damaged	225.00 FL	*225.00 FL
10	1		*REAR BOOT LID HONDA LOGO	Not Necessary	64.20 FL	*- FL
11	1		*REAR BOOT LID INNER HANDLE COVER	Deformed	71.50 FL	*71.50 FL
12	1		*REAR BOOT LID INNER TRIM BOARD	Cracked	345.71 FL	*345.71 FL
13	2		*REAR BOOT LAMP L/R	O/S Cut / N/S Cracked	756.40 FL	*756.40 FL
14	2		*REAR LAMP L/R	Cut	1,167.90 FL	*990.00 FL
15	2		*REAR SIDE BUMPER L/R	Not Necessary	503.56 FL	*- FL
16	1		*REAR FENDER WHEEL ARC GUARD GARNISH LH	Deformed	283.80 FL	*185.00 FL
17	1		*REAR BUMPER ASSY	Distorted	892.60 FL	*765.00 FL
18	10		*REAR BUMPER CLIPS	Necessary	38.00 FL	*38.00 FL
19	2		*REAR BUMPER SIDE HOLDER L/R	Necessary	65.00 FL	*65.00 FL
20	2		*REAR BUMPER BRACKET L/R	Not Necessary	50.00 FL	*- FL
21	2		*REAR BUMPER REFLECTOR LAMP L/R	Not Necessary	77.80 FL	*- FL
22	1		*REAR END PANEL	Dented	642.50 FL	*585.00 FL
23	1		*REAR END PANEL INNER TOP GARNISH	Deformed	98.70 FL	*98.70 FL
24	1		*REAR TYRE PANEL FLOOR PANEL	Repair	918.60 FL	*- FL
25	1		*REAR TOOLS TRAY GARNISH	Cracked	283.00 FL	*283.00 FL
26	1		*REAR TYRE PANEL COVER TRIM BOARD	Not Necessary	329.18 FL	*- FL
27	2		*REAR FENDER INNER TRIM GARNISH L/R	Cracked	625.00 FL	*625.00 FL
28	1		*REAR TYRE PANEL LOWER UNDER SHIELD	Deformed	275.91 FL	*275.91 FL
29	6		*REAR TYRE PANEL LOWER UNDER SHIELD CLIPS	Necessary	22.80 FL	*22.80 FL
30	1		*REAR EXHAUST SILENCER BOX ASSY	Not Necessary	613.80 FL	*- FL
31	1		*WINDSCREEN SEALANT	Necessary	40.00 FS	*40.00 FS
32	1		*REAR NO PLATE W/FRAME	Bent	45.00 FS	*45.00 FS
33	1		*SET REVERSE SENSOR	Damaged	350.00 FS	*200.00 FS
34	1		*BUZZER	Cracked	110.00 FL	*110.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,448.58	7,243.04
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,202.72	1,391.61
Total Parts (\$\$)	9,245.86	5,851.43

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,REARRANGE ELECTRICAL WIRINGS ,CHECK LIGHTING	New	100.00	30.00
2	TO REMOVE ,REINSTAL UPHOLSTERY INNER TRIM GARNISHES	New	200.00	60.00
3	TO REMOVE REINSTAL EXHAUST & ALIGN PIPE	New	180.00	0.00
4	TO REMOVE ,REPLACE & TRANSFER REAR BOOT LID COMPONENTS	New	150.00	80.00
5	TO REMOVE ,REPLACE REAR WINDSCREEN	New	200.00	120.00
6	TO REMOVE ,REPAIR AND REPLACED DAMAGED BODYPARTS ,REALIGN BODYWORKS & WHERE CONSISTENT TO THE ACCIDENT	New	1,800.00	800.00
7	TO PUTTY AND RESPRAY PAINTING ON AFFECTED AREA	New	1,600.00	800.00
Gross Labour Cost (\$\$)			4,230.00	1,890.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >