

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22001862/UPA3Q2**Date:** 20/04/2023REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SLC5361S**Insured Vehicle No :** SKV6190Z

Date of Loss: 25/02/2022

Nature of Claim: TP

Claim No: 1662499804SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLC5361S**

Make & Model: HONDA VEZEL, 1.5 X CVT (A)

Engine No: L15B4033967

Reg. Date: 18/08/2016 (Man. Year: 2016)

Chassis No: RU11113938

Colour: Silver

Odometer: 138742 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R17

Rear Tyre Size: 215/55 R17

Front Left Side: Continental 6 mm

Rear Left Side: Continental 6 mm

Front Right Side: Continental 6 mm

Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,760.00	2,132.64	3,627.36	62.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,340.00	1,340.00	1,000.00	42.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,100.00	3,472.64	4,627.36	57.13
Approved Total (Overridden) (S\$)		2,750.00		
(S\$)	8,100.00	2,750.00	5,350.00	66.05
+ GST 7.00/7.00% (S\$)	567.00	192.50	374.50	66.05
Nett Amount (S\$)	8,667.00	2,942.50	5,724.50	66.05
+ Car Rental (5.0 x S\$100.00/day + 7.00% GST) (S\$)		535.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		3,484.95		

INSPECTION

Date of Assignment: 28/02/2022

Date Inspected: 28/02/2022

Inspected At:

Tan Lim Motor Pte Ltd (Defu)

1 Defu Lane 6

Singapore 539365

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE LID	Badly Dented	1,050.00 F	*953.00 FL
2	1		*TAILGATE LID VEZEL BADGE	Necessary	43.00 F	*43.00 FL
3	1		*TAILGATE LID INNER LOCK STRICKET	Not Necessary	27.50 F	*- FL
4	1		*TAILGATE LID WEATHERSTRIP	Twisted	135.00 F	*135.00 FL
5	1		*TAILGATE LID INNER BOARD	Cracked	225.00 F	*225.00 FL
6	1		*TAILGATE LID INNER LOCK	Twisted / Shorted	157.00 F	*157.00 FL
7	2		*TAILGATE LID LAMP	Not Necessary	450.00 F	*- FL
8	2		*REAR LAMP	Not Necessary	949.20 F	*- FL
9	1		*REAR BUMPER	Dented	777.90 F	*492.50 FL
10	2		*REAR BUMPER REFLECTOR	Not Necessary	282.20 F	*- FL
11	2		*REAR BUMPER SIDE	Not Necessary	306.00 F	*- FL
12	2		*REAR BUMPER SIDE RETAINER	Not Necessary	35.00 F	*- FL
13	1		*REAR BUMPER LOWER SPLASHIELD COVER	Deformed	190.00 F	*190.00 FL
14	8		*REAR BUMPER LOWER SPLASHIELD COVER CLIPS	Necessary	28.00 F	*28.00 FL
15	1		*REAR END PANEL	Repair	411.90 F	*- FL
16	1		*REAR END PANEL INNER TRIM	Twisted	92.30 F	*92.30 FL
17	1		*SET REAR BUMPER PARKING SENSOR	Shorted	450.00 FS	*200.00 FS
18	1		*REAR WINDSCREEN SEAL	Necessary	50.00 FS	*40.00 FS
19	1		*REAR WINDSCREEN INNER SEAL SPONGE	Necessary	50.00 FS	*40.00 FS
20	1		*REAR NUMBER PLATE	Serviceable	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	5,760.00	2,595.80
- List Item Discount on L Items 0.00/20.00% (\$)	0.00	463.16
Total Parts (\$)	5,760.00	2,132.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE REAR OF NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	900.00	550.00
2	PUTTY AND SPRAY PAINTING REAR OF THE AFFECTED PORTION	New	900.00	500.00
3	TO REINSTALL OF REAR BUMPER PARKING SENSOR	New	80.00	50.00
4	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	140.00	120.00
5	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	80.00	20.00
6	TO RUST-PROOFING OF THE AFFECTED AREAS	New	120.00	40.00
7	TO TRANSFER OF TAILGATE FITTINGS ,FIXTURE AND PERFORM WATERSEEPAGE TEST	New	120.00	60.00
Gross Labour Cost (\$\$)			2,340.00	1,340.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >