

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22001868/VNY3E2

Date: 07/07/2022

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMB1SNW00002082100
Claimant Vehicle No : SMC6634L Insured Vehicle No : PA8049M
Date of Loss: 24/02/2022 Nature of Claim: TP Claim No: SNM22D201363/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMC6634L**
Make & Model: MERCEDES-BENZ C180, 1.8 (A) Engine No: 27182030079441
Reg. Date: 16/09/2010 (Man. Year: 2010) Chassis No: WDD2040492A403588
Colour: Silver Odometer: 125795 km
Engine Capacity: 1796 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17
Front Left Side: Michelin 5 mm Rear Left Side: Michelin 5 mm
Front Right Side: Michelin 5 mm Rear Right Side: Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	24,244.00	10,990.50	13,253.50	54.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,660.00	2,240.00	5,420.00	70.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	31,904.00	13,230.50	18,673.50	58.53
+ GST 7.00/7.00% (S\$)	2,233.28	926.14	1,307.14	58.53
Nett Amount (S\$)	34,137.28	14,156.64	19,980.64	58.53

INSPECTION

Date of Assignment: 28/02/2022
Date Inspected: 28/02/2022 Inspected At: Dickson Auto Care Centre Pte Ltd (HQ)
29 Ubi Road 4, Dickson Auto Centre
Singapore 408619
Estimated Period of Repair: 7.0 days

Adjuster: Thevan Thomas Karthikesavan

Manager: HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$11,591.50 NETT)

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Jul 2022)
Parts:	143	MERCEDES-BENZ C180 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMC6634L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	1,672.00 F	*1,672.00 F
2	10		*REAR BUMPER CLIPS	Necessary	55.00 F	*55.00 F
3	1		*REAR BUMPER CHROME MOULDING CENTRE	Necessary	129.20 F	*129.20 F
4	2		*REAR BUMPER CHROME MOULDING SIDE	Necessary	235.60 F	*235.60 F
5	1		*REAR BUMPER LH SIDE RETAINER	Necessary	57.00 F	*57.00 F
6	1		*REAR TRUNK	Repair	1,862.00 F	*- F
7	2		*REAR TRUNK HINGES LH & RH	* Check	1,292.00 F	*- F
8	1		*REAR TRUNK C180 LOGO	Necessary	95.00 F	*95.00 F
9	1		*REAR LH TAIL LAMP	Cracked	532.00 F	*532.00 F
10	1		*REAR LH FENDER	Dented	2,432.00 F	*2,432.00 F
11	1		*REAR LH FENDER INNER SEAL	Necessary	129.20 F	*129.20 F
12	10		*REAR LH FENDER INNER SEAL CLIPS	Necessary	55.00 F	*55.00 F
13	1		*REAR LH FENDER INNER HOUSING	* Check	2,565.00 F	*- F
14	1		*REAR LH DOOR	Dented	2,280.00 F	*2,280.00 F
15	1		*REAR LH DOOR UPPER HINGE	Shifted	171.00 F	*171.00 F
16	1		*REAR LH DOOR LOWER HINGE	Shifted	190.00 F	*190.00 F
17	1		*REAR LH DOOR CHROME PROTECTOR UPPER	Necessary	209.00 F	*209.00 F
18	1		*REAR LH DOOR CHROME PROTECTOR LOWER	Necessary	110.00 F	*110.00 F
19	1		*REAR LH DOOR INNER LOCK	Jammed	332.50 F	*332.50 F
20	1		*REAR LH DOOR INNER BOARD	* Check	2,565.00 F	*- F
21	1		*REAR LH DOOR GLASS OUTER UPPER MOULDING	Necessary	209.00 F	*209.00 F
22	1		*REAR LH DOOR SIDE SILVER PROTECTOR	Necessary	110.00 F	*110.00 F
23	1		*REAR LH DOOR POWER WINDOW MOTOR	* Check	722.00 F	*- F
24	1		*REAR LH DOOR POWER WINDOW MOTOR REGULATOR	* Check	799.00 F	*- F
25	1		*REAR LH SPORT RIM	Scratched	1,235.00 F	*1,235.00 F
26	1		*REAR LH WHEEL HUB BEARING	* Check	522.50 F	*- F
27	1		*REAR LH LOWER ARM	* Check	237.50 F	*- F
28	1		*REAR LH UPPER ARM	* Check	237.50 F	*- F
29	1		*REAR LH NUCKER ARM BEARING	* Check	1,900.00 F	*- F
30	1		*REAR LH SHOCK ABSORBER	* Check	551.00 F	*- F
31	1		*REAR WINDSCREEN INNER SEAL	Necessary	250.00 F	*250.00 F
32	1		*SEALANT	Necessary	45.00 F	*45.00 F
33	1		*REAR LH TYRE	Cut	400.00 F	*400.00 F
34	1		*REAR TRUNK LOGO	Necessary	57.00 F	*57.00 F

F=Franchise part.

Total Parts (\$\$) **24,244.00** **10,990.50**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIT BEAM WIRING, DAMAGED LAMP AND TEST FOR PROPER FUNCTIONING	New	80.00	30.00
2	TO REMOVE & REFIT REVERSE SENSORS	New	200.00	30.00
3	TO DO DIAGNOSTIC CHECKING & REPROGRAM SYSTEM	New	280.00	60.00
4	TO REMOVE & REFIT REAR WINDSCREEN	New	200.00	120.00
5	TO REMOVE & REFIT REAR DASHBOARD, SPEAKERS, TRIM COVER AND REAR SEATS	New	300.00	70.00
6	TO REMOVE & REFIT REAR LH SUSPENSION TO ASSIST FOR REPAIR (* Check)	New	200.00	0.00
7	TO DO ELECTRICAL 4 WHEEL ALIGNMENT	New	200.00	60.00
8	TO REMOVE & REFIT REAR LH POWER WINDOW WIRING, MOTOR & REGULATOR	New	200.00	70.00
9	TO PROVIDE SKILL LABOUR TO REMOVE ALL DAMAGED PARTS & PANELS. PANEL BEAT, CUT & WELD IN PLACE NEW	New	3,000.00	1,000.00
10	TO PROVIDE SKILL LABOUR & MATERIAL TO PREPARE AND PAINT ALL NEW PARTS & PANELS	New	3,000.00	800.00
Gross Labour Cost (\$\$)			7,660.00	2,240.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >