

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBF 996X

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DEFORMED	745.00	589.00
1	SET REAR BUMPER CLIPS	NECESSARY	65.00	50.00
1	REAR BUMPER REINFORCEMENT	BENT	475.30	461.00
1	REAR RH TAILGATE	DENTED	1,895.90	1,895.90
1	REAR RH TAILGATE OUTER GARNISH	CRACKED	321.80	321.80
1	REAR RH TAIL LAMP	CRACKED	462.70	422.10
1	REAR RH TAILGATE "FIAT" EMBLEM	SCRATCHED	87.80	87.80
1	REAR RH TAILGATE "PROFESSIONAL" EMBLEM	NECESSARY	163.50	145.00
	LESS 10% DISCOUNT		-	-397.26
			4,217.00	3,575.34
	SPECIAL NETT ITEMS			
1	SET REAR BUMPER REVERSE SENSOR (SN)	SHORTED	220.00	200.00
1	REAR RH TAILGATE "6 PAX" STICKER (SN)	NECESSARY	15.00	10.00
			235.00	210.00
	<u>LABOUR</u>			
	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION.		40.00	20.00
	REMOVE AND REFIX REAR TAILGATE COMPONENTS & WIPER MECHANISM.		60.00	60.00
	REMOVE AND REFIX REAR BUMPER REVERSE SENSOR.		120.00	50.00
	REMOVE & REINSTALL TAILGATE GLASS TO FACILITATE REPAIRS.		120.00	100.00
	LABOR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS ETCS.		800.00	300.00
	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED AREAS.		700.00	500.00
			1,840.00	1,030.00
	GRAND TOTAL		6,292.00	4,815.34

Report Ref No. CS/SMO22001871/Uqf3e2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		3,850.00
(TO ITS PRE-ACCIDENT CONDITION)		·

Report Ref No. CS/SMO22001871/Uqf3e2

CHUA KANG SENG

Licensed Appraiser