

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG22001872/KPA3Q2**Date:** 28/10/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210104089
<b>Claimant Vehicle No :</b>	SJQ7558D	<b>Insured Vehicle No :</b>	SGG3934R
Date of Loss:	30/01/2022	Nature of Claim:	TP
		Claim No:	1906349788SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SJQ7558D</b>	Engine No:	2NRX437841
Make & Model:	TOYOTA VIOS, 1.5 E (A)	Chassis No:	MR2B23F3701174916
Reg. Date:	30/04/2019 (Man. Year: 2019)	Odometer:	29722 km
Colour:	Metallic Grey		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Yokohama 8 mm	Rear Left Side:	Yokohama 8 mm
Front Right Side:	Yokohama 8 mm	Rear Right Side:	Yokohama 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	735.98	735.98	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	800.00	650.00	150.00	18.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>1,535.98</b>	<b>1,385.98</b>	<b>150.00</b>	<b>9.77</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	107.52	97.02	10.50	9.77
<b>Nett Amount (\$\$)</b>	<b>1,643.50</b>	<b>1,483.00</b>	<b>160.50</b>	<b>9.77</b>
<b>+ Loss of Use (3.0 x S\$90.00/day) (\$\$)</b>		270.00		
<b>Nett Liability (\$\$)</b>		<b>1,753.00</b>		
<b>Global Sum Settlement (\$\$)</b>		<b>1,750.00</b>		

INSPECTION

Date of Assignment:	08/03/2022	
Date Inspected:	08/03/2022	Inspected At: Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A Singapore 768761
Estimated Period of Repair:	3.0 days	

**Adjuster:** KENNETH KONG**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled / Dented	497.11 FL	*497.11 FL
2	6		*REAR BUMPER CLIPS	Necessary	21.00 FL	*21.00 FL
3	2		*REVERSE SENSORS	Shorted	386.00 FN	*386.00 FN
F=Franchise part. L=ListItemDisc. N=NettItemDisc.						
Sub Total (S\$)					904.11	904.11
- List Item Discount on L Items 25.00/25.00% (S\$)					129.53	129.53
- Nett Item Discount on N Items 10.00/10.00% (S\$)					38.60	38.60
Total Parts (S\$)					735.98	735.98

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REMOVE & REFIX REAR BUMPER ASSY ,REVERSE SENSORS TO KNOCK & REPAIR REAR BUMPER REINFORCEMENT AND REALIGN THE SAME	New	300.00	250.00
2	PUTTY & RESPRAY BOOT ,REAR BUMPER ,REAR PANEL ,REINFORCEMENT	New	500.00	400.00
<b>Gross Labour Cost (\$\$)</b>			<b>800.00</b>	<b>650.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >