

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22001875/DNY3Q2**Date:** 19/09/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00112672100	
Claimant Vehicle No :	SLV3224T	Insured Vehicle No :	SLF6593S	
Date of Loss:	25/02/2022	Nature of Claim:	TP	Claim No: SNM22D201412/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLV3224T		Engine No:	2ZR8236955
Make & Model:	TOYOTA VOXY HYBRID, 1.8 X CVT (A)		Chassis No:	ZWR800281802
Reg. Date:	27/12/2017 (Man. Year: 2017)		Odometer:	213892 km
Colour:	Black			
Engine Capacity:	1797 cc			
Market Value/New Car Price:	N/A			
Sum Insured (\$\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Dunlop 5 mm	Rear Left Side:	Dunlop 5 mm
Front Right Side:	Dunlop 5 mm	Rear Right Side:	Dunlop 5 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	27,346.55	7,389.16	19,957.39	72.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,320.00	2,460.00	3,860.00	61.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	33,666.55	9,849.16	23,817.39	70.74
Approved Total (Overridden) (\$\$)		7,800.00		
(\$\$)	33,666.55	7,800.00	25,866.55	76.83
+ GST 7.00/7.00% (\$\$)	2,356.66	546.00	1,810.66	76.83
Nett Amount (\$\$)	36,023.21	8,346.00	27,677.21	76.83

INSPECTION

Date of Assignment:	07/03/2022	
Date Inspected:	01/03/2022 Inspected At:	JWG International Pte Ltd (HQ) Blk 10, Ang Mo Kio Ind Park 2A,, #03-08 AMK AutoPoint Singapore 568047
Estimated Period of Repair:	6.0 days	

Adjuster: BRYAN TANI**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Sep 2022)
Parts:	M1-MPV	TOYOTA VOXY HYBRID 1.8 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLV3224T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Buckled	2,406.10 FL	*1,812.00 FL
2	1		*TAILGATE WINDSCREEN MOULDING	Necessary	407.20 FL	*135.00 FL
3	1		*TAILGATE CHROME MOULDING	Cracked	988.20 FL	*581.00 FL
4	1		*TAILGATE TOYOTA LOGO	Necessary	58.80 FL	*58.80 FL
5	1		*TAILGATE VOXY EMBLEM	Necessary	103.90 FL	*103.90 FL
6	2		*TAILGATE NO PLATE LAMP L+R	Not Necessary	215.36 FL	*- FL
7	1		*TAILGATE INNER TRIM BOARD	Mtg Cracked	1,093.70 FL	*425.00 FL
8	1		*TAILGATE WEATHERSTRIP	Deformed	725.50 FL	*371.75 FL
9	1		*TAILGATE LOCK	Damaged	461.50 FL	*461.50 FL
10	1		*TAILGATE HYBRID EMBLEM	Necessary	62.15 FL	*62.15 FL
11	2		*TAILGATE HINGE LH/RH	Not Necessary	208.40 FL	*- FL
12	2		*TAILGATE DAMPER LH/RH	Not Necessary	1,218.20 FL	*- FL
13	1		*REAR BUMPER	Buckled	1,491.90 FL	*798.20 FL
14	2		*REAR BUMPER SIDE RETAINER L+R	Not Necessary	259.80 FL	*- FL
15	2		*REAR BUMPER BRACKET L+R	Not Necessary	316.78 FL	*- FL
16	2		*REAR BUMPER REFLECTOR L+R	Not Necessary	291.60 FL	*- FL
17	1		*REAR BUMPER TOW HOOK COVER	Dislodged	91.80 FL	*42.10 FL
18	1		*REAR END PANEL INNER	Not Necessary	1,205.90 FL	*- FL
19	1		*REAR END PANEL OUTER	Dented / Buckled	1,420.85 FL	*685.10 FL
20	1		*REAR END PANEL TOP GARNISH	Deformed	383.82 FL	*204.50 FL
21	1		*SPARE WHEEL PANEL	Dented	2,876.20 FL	*855.00 FL
22	1		*SPARE WHEEL PANEL TOP BOARD	Bent	1,409.20 FL	*830.00 FL
23	2		*REAR FENDER LH/RH	Not Necessary	5,971.40 FL	*- FL
24	2		*REAR FENDER INNER TRIM BOARD L+R	Deformed / Mtg Cracked	1,736.96 FL	*1,362.20 FL
25	2		*REAR FENDER QUARTER GLASS MOULDING	Not Necessary	999.60 FL	*- FL
26	2		*TAIL LAMP L+R	Not Necessary	2,779.70 FL	*- FL
27	2		*TAIL LAMP LOWER BRACKET L+R	Not Necessary	348.50 FL	*- FL
28	2		*TAIL LAMP PANEL L+R	Repair	1,796.00 FL	*- FL
29	2		*TAIL LAMP LOWER GARNISH LH/RH	Cut / Mtg Cracked	997.50 FL	*743.70 FL
30	1		*REAR EXHAUST PIPE	Not Necessary	1,573.90 FL	*- FL
31	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	288.80 FL	*- FL
32	1		*REAR EXHAUST MOUNTING	Not Necessary	98.00 FL	*- FL
33	1		*REAR EXHAUST DIFFUSER COVER	Not Necessary	355.00 FL	*- FL
34	1		*REAR KEYLESS SENSOR	Mtg Cracked	301.27 FL	*72.00 FL
35	1		*REAR FENDER INNER TRIM BOARD BRACKET RH	Bent	211.91 FL	*68.31 FL
36	1		*SET REAR REVERSE SENSOR	Not fitted	300.00 FS	*- FS
37	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*20.00 FS
38	1		*REAR FENDER SEALANT	Not Necessary	80.00 FS	*- FS
39	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
40	1		*REAR WINDSCREEN DAMPING SEAL	Not Necessary	30.00 FS	*- FS
41	1		*REAR FLOOR PANEL SEALANT	Necessary	80.00 FS	*20.00 FS
42	1		*TAIL LAMP PANEL SEALANT	Not Necessary	80.00 FS	*- FS
43	1		*TAIL LAMP CLIPS	Not Necessary	50.00 FS	*- FS
44	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*15.00 FS
45	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	50.00 FS	*10.00 FS
46	1		*REAR FENDER INNER TRIM CLIPS	Necessary	50.00 FS	*20.00 FS

Report was unsubmitted during this print-out.

9/19/22, 3:33 PM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*10.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					36,135.40	9,807.21
- List Item Discount on L Items 25.00/25.00% (S\$)					8,788.85	2,418.05
Total Parts (S\$)					27,346.55	7,389.16
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ALL INTERIOR UPHOLSTERY ITEMS TO FACILITATE REPAIRS	New	300.00	80.00
2	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	2,000.00	1,200.00
3	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	2,000.00	900.00
4	TO TUFF COAT DAMAGED AREAS	New	300.00	40.00
5	TO RNR REAR FENDER QUARTER GLASS TO FACILITATE REPAIRS	New	300.00	0.00
6	TO RNR REVERSE CAMERA	New	100.00	30.00
7	TO RNR REAR WINDSCREEN TO FACILITATE REPAIRS	New	250.00	120.00
8	TO RNR TAILGATE MECHANISM TO FACILITATE REPAIRS	New	200.00	60.00
9	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS	New	250.00	0.00
10	TO CHECK & REFIX ALL ELECTRICAL WIRINGS	New	200.00	30.00
11	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	0.00
12	TO RNR REVERSE SENSOR TO ASSIST WORK LOAD	New	120.00	0.00
Gross Labour Cost (\$\$)			6,320.00	2,460.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >