

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22001876/UVY3N2**Date:** 22/03/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00195562100

**Claimant Vehicle No :** SDR148R **Insured Vehicle No :** SME4977A

Date of Loss: 25/02/2022 Nature of Claim: TP Claim No: SNM22D201402/C02/TANKW

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SDR148R**

Make & Model: MITSUBISHI ATTRAGE, 1.2 CVT (A) Engine No: 3A92UHT2565

Reg. Date: 24/10/2019 (Man. Year: 2019) Chassis No: MMBSTA13AKH001933

Colour: Blue Odometer: 27219 km

Engine Capacity: 1193 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 185/55R16 Rear Tyre Size: 185/55R16

Front Left Side: Bridgestone 7 mm Rear Left Side: Bridgestone 7 mm

Front Right Side: Bridgestone 7 mm Rear Right Side: Bridgestone 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	5,952.00	4,497.00	1,455.00	24.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,150.00	6,750.00	4,400.00	39.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>17,102.00</b>	<b>11,247.00</b>	<b>5,855.00</b>	<b>34.24</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,197.14</b>	<b>787.29</b>	<b>409.85</b>	<b>34.24</b>
<b>Nett Amount (S\$)</b>	<b>18,299.14</b>	<b>12,034.29</b>	<b>6,264.85</b>	<b>34.24</b>

**INSPECTION**

Date of Assignment: 28/02/2022

Date Inspected: 01/03/2022 Inspected At: Cycle & Carriage Fulco Motor Dealer Pte Ltd (HQ)  
330 Ubi Road 3  
Singapore 408650

Estimated Period of Repair: 7.0 days

**Adjuster:** MARCUS CHUA**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 22 Mar 2022)	
<b>Parts:</b>	N/A	mitsubishi attrage 1.2 CVT (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SDR148R)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*MARK,THREE-DIA	Necessary	70.00 FS	*70.00 FS
2	1		*MARK,ATTRAGE	Necessary	21.00 FS	*21.00 FS
3	1		*PANEL,TRUNK LID	Dented/Bent	795.00 FS	*795.00 FS
4	1		*LATCH,TRUNK LID	Not Necessary	218.00 FS	*- FS
5	1		*STRIKER,TRUNK LID LA	Not Necessary	20.00 FS	*- FS
6	1		*W/STRIP,TRUNK LID	Twisted	157.00 FS	*157.00 FS
7	1		*LH LAMP ASSY,COMB,RR	Not Necessary	337.00 FS	*- FS
8	1		*RH LAMP ASSY,COMB,RR	Not Necessary	337.00 FS	*- FS
9	1		*FACE,RR BUMPER	Dented	751.00 FS	*751.00 FS
10	10		*CLIP,BUMPER	Necessary	40.00 FS	*40.00 FS
11	1		*LH BRACKET,RR BUMPER	Bent	28.00 FS	*28.00 FS
12	1		*RH BRACKET,RR BUMPER	Bent	28.00 FS	*28.00 FS
13	1		*LH SHIELD,RR WHEELHO	Not Necessary	35.00 FS	*- FS
14	1		*RH SHIELD,RR WHEELHO	Not Necessary	35.00 FS	*- FS
15	10		*CLIP,WHEELHOUSE SHIE	Not Necessary	40.00 FS	*- FS
16	1		*COVER,RR VENTILATOR	Not Necessary	40.00 FS	*- FS
17	1		*LH INR RR,MUD GUARD	Not Necessary	36.00 FS	*- FS
18	1		*RH INR RR,MUD GUARD	Not Necessary	36.00 FS	*- FS
19	1		*BUZZER,KEYLESS OPERA	Cracked	91.00 FS	*91.00 FS
20	1		*ANTENNA,KEYLESS OPER	Not Necessary	96.00 FS	*- FS
21	1		*PANEL,RR END	Dented	427.00 FS	*427.00 FS
22	1		*TRIM,RR END	Twisted	66.00 FS	*66.00 FS
23	1		*BOARD,TRUNK ROOM FLO	Not Necessary	195.00 FS	*- FS
24	1		*BODY KIT,ATTRAGE	Cracked	1,643.00 FS	*1,643.00 FS
25	1		*C&C LOGO	Necessary	50.00 FS	*50.00 FS
26	1		*MIVEC EMBLEM	Necessary	50.00 FS	*50.00 FS
27	1		*REVERSE SENSOR (ITEMS & INSTALLATION INCLUDED)	Shorted	280.00 FS	*280.00 FS
28	1		*DUCT RR VENTILATOR	Not Necessary	30.00 FS	*- FS

F=Franchise part. S=SpcNett.

**Total Parts (\$\$)**      **5,952.00**      **4,497.00**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	DIAGNOSTIC/SCANNING	New	250.00	250.00
2	TO CHECK ALL LIGHTING/WIRING SYSTEM ON REAR ACCIDENT AFFECTED AREAS	New	100.00	80.00
3	TO REMOVE & RE-INSTALL ALL CARPETS/TRIMMING TO FACILITATE REPAIR ON REAR ACCIDENT AFFECTED AREAS	New	640.00	320.00
4	TO APPLY SEALANT KIT ON NEW & REPAIR PANELS	New	300.00	100.00
5	TO TRANSFER REAR BOOT COMPONENTS & MECHANISM PARTS	New	640.00	320.00
6	TO REPLACE EMBLEM, LOGO, REAR BOOT, TAIL LAMPS, REAR BUMPER, CLIPS, BRACKETS, WHEELHOUSE SHIELD, COVER & DUCT VENTILATOR, BUZZER, ANTENNA, ETC-TO CUT & WELD REAR END PANEL-TO REPAIR RHR FENDER & REAR FLOORING STRAIGHTEN, REFORM, ALIGN ON REAR ACCIDENT AFFECTED AREAS	New	5,120.00	2,880.00
7	SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS	New	3,300.00	2,200.00
8	TO REPLACE & RESPRAY BODY KIT	New	800.00	600.00
<b>Gross Labour Cost (S\$)</b>			<b>11,150.00</b>	<b>6,750.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >