



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBP 94X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	ENGINE BLOCK COVER BRACKET CHROME-LH	SERVICEABLE	225.00	-
1	EXHAUST	BENT	2,300.00	2,300.00
1	FRONT BRAKE CALIPER	SERVICEABLE	450.50	-
1	FRONT BRAKE MOTOR	WARPED	195.00	195.00
1	FRONT FENDER	BROKEN	195.15	195.15
1	FRONT FORK-LH }	BENT	1,396.80	1,900.00
1	FRONT FORK-RH }	BENT	1,396.80	-
1	FRONT FORK BRACKET TOP	DISTORTED	385.00	385.00
1	FRONT FORK TUBE-LH	SERVICEABLE	520.15	-
1	FRONT FORK TUBE-RH	DENTED	520.15	325.00
1	FRONT HANDLE BAR	DISTORTED	450.00	180.00
1	FRONT HANDLE BAR BALANCER-LH	DENTED	115.20	115.20
1	FRONT HANDLE BAR BALANCER-RH	SERVICEABLE	115.20	-
1	FRONT HANDLE CLUTCH LEVER	SERVICEABLE	144.00	-
1	FRONT HEADLAMP WING COVER	BROKEN	245.10	245.10
1	FRONT LOWER FORK BEARING (LOWER)	NECESSARY	85.15	85.15
1	FRONT LOWER FORK BEARING (TOP)	NECESSARY	85.15	85.15
1	FRONT LOWER FORK BRACKET	DISTORTED	385.00	385.00
1	FRONT SIGNAL LAMP-RH	CRACKED	95.00	95.00
1	FRONT SIGNAL LAMP-LH	SERVICEABLE	95.00	-
1	HEAD LAMP	DENTED	380.15	380.15
1	HEAD LAMP CHROME	DENTED	185.05	185.05
1	RPM METER	SERVICEABLE	1,520.00	-
1	WING MIRROR-LH	DENTED	90.05	90.05
1	WING MIRROR-RH	SERVICEABLE	90.05	-
1	RADIATOR (ADDITIONAL)	BENT	1,050.50	850.00
1	RADIATOR FAN MOTOR (ADDITIONAL)	CRACKED	365.00	330.00
1	RADIATOR COWLING (ADDITIONAL)	CRACKED	145.00	85.00
	LESS 10% DISCOUNT		-	-841.10
			13,225.15	7,569.90

Report Ref No. CS/AIS22001877/Ktf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT NUMBER PLATE (SN)	DENTED	50.00	15.00
1	FRONT WHEEL RIM (SN)	SERVICEABLE	850.90	-
1	REAR NUMBER PLATE (SN)	DENTED	50.00	15.00
1	BRAKE OIL (SN)	NECESSARY	20.00	20.00
1	WATER COOLANT (SN)(ADDITIONAL)	NECESSARY	50.00	20.00
			1,020.90	70.00
	<u>LABOUR</u>			
	TO DISMANTLE & REPLACE DAMAGED PARTS,PANEL BEAT WHERE NECESSARY.		800.00	180.00
	TO PUTTY,APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.	NOT NECESSARY	700.00	-
	TO ALIGN MAIN BODY FRAME.		400.00	120.00
	TO TOW VEHICLE TO WORKSHOP.		120.00	30.00
			2,020.00	330.00
GRAND TOTAL			16,266.05	7,969.90

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			6,350.00
---	--	--	-----------------

Report Ref No. CS/AIS22001877/Ktf3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.