

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	AXA INSURANCE	PTE LTD		Ref:	CS3/ASM22001878/Vvy3e2
	8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811			Date:	16/03/2022
	ATTN: OH VALE			Code:	ASM
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	FBN 6754X	Veh. Inspected	l	SKJ 6889E
	Policy No.	P2467513	Coverage (\$)		0.00
	Claim No.	S2M03UFP	Excess (\$)		0.00
	Assign From	OH VALE	Assign Date		28/02/2022
2. Vehicle Particulars & Condition					
	Make & Model	VOLKSWAGEN TOURAN	c.c		1390
	Engine No.	HIDDEN	Year of Reg.		2009
	Chassis No.	WVGZZZ1TZ9W112259	Colour		BLACK
	Odometer	195760 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM
	General	GOOD			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	225/40 R18	MICHELIN		5 mm
	L/H Front Tyre	225/40 R18	MICHELIN		5 mm
	R/H Rear Tyre	225/40 R18	MICHELIN		5 mm
	L/H Rear Tyre	225/40 R18	MICHELIN		5 mm
4. Description of Damages					
	THE VEHICLE SUS	HE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.			
5.	General Information				
	Accident Date	26/02/2022	Inspect Date /	Time	28/02/2022 (03:00 PM)
	Survey held at GARAGE 13 PTE LTD				
	8 KAKI BUKIT AVE 4 #03-46 PREMIER SINGAPORE 415875				
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. ITHE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000-\$5,000				
5b. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				

Report Ref No. CS3/ASM22001878/Vvy3e2

Inspected By

THEVAN THOMAS KARTHIKESAVAN

The

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser