

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

| PRE-REPAIR INSPECTION REPORT | | | | | | |
|------------------------------|---|--|----------------|-------|-------------------------|--|
| | STRIDES AUTOMO | OTIVE SERVICES PTE LTD | | Ref: | CS3/SMR22001881/Vtf3e2 | |
| | 60 WOODLANDS I E4SINGAPORE 75 | NDUSTRIAL PARK 7705 | | Date: | 16/03/2022 | |
| | | | | Code: | SMR | |
| 1. | Policy Particulars :- (THIRD PARTY CLAIM) | | | | | |
| | Insured Veh. | SHB 5301T | Veh. Inspected | k | SKB 9462A | |
| | Policy No. | | Coverage (\$) | | 0.00 | |
| | Claim No. | TAX/02/22/2072 | Excess (\$) | | 0.00 | |
| | Assign From | HUA YEN | Assign Date | | 28/02/2022 | |
| 2. | Vehicle Particulars & Condition | | | | | |
| | Make & Model | HYUNDAI 145 2.4 | c.c | | 2359 | |
| | Engine No. | HIDDEN | Year of Reg. | | 2011 | |
| | Chassis No. | KMHEC41CMBA259304 | Colour | | WHITE | |
| | Odometer | 255049 KM | Steering | | IN ORDER | |
| | Brakes | IN ORDER | Modification | | STANDARD ALLOY RIM | |
| | General | GOOD | | | | |
| 3. Conditions of Tyres | | | | | | |
| | | Size | Make | | Balance | |
| | R/H Front Tyre | 215/55 R17 | YOKOHAMA | | 6 mm | |
| | L/H Front Tyre | 215/55 R17 | YOKOHAMA | | 6 mm | |
| | R/H Rear Tyre | 215/55 R17 | YOKOHAMA | | 6 mm | |
| | L/H Rear Tyre | 215/55 R17 | YOKOHAMA | | 6 mm | |
| 4. | Description of Damages | | | | | |
| | THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. | | | | | |
| 5. | General Information | | | | | |
| | Accident Date | 25/02/2022 | Inspect Date / | Time | 01/03/2022 (12:47 PM) | |
| | Survey held at | LENG WANG MOTOR | • | | | |
| | BLK 3007 UBI ROAD #01-414 SINGAPORE 408701 | | | | | |
| 5a. | Remarks | | | | | |
| | A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000 | | | | | |
| 5b. | | Estimate Days of Repair | | | | |
| | ESTIMATED NORM | ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days | | | | |

Report Ref No. CS3/SMR22001881/Vtf3e2

Inspected By

THEVAN THOMAS KARTHIKESAVAN

The

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser