

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 4254S**

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRT BUMPER COVER	CUT	430.90	430.90
10	FRT BUMPER CLIPS	NECESSARY	22.00	22.00
1	FRT BUMPER SIDE BRACKET RH	NECESSARY	28.00	28.00
1	FRT BUMPER MOULDING CENTRE UPPER	SCRATCHED	368.50	368.50
1	HEADLAMP RH	SCRATCHED	1,993.65	1,993.65
1	DAY LIGHT RH	CUT	642.50	642.50
1	FRT BUMPER SIDE GRILLE RH	DISTORTED	93.45	93.45
1	HEAD LAMP SUPPORT PANEL	SERVICEABLE	949.30	-
1	FRT BUMPER AIR DUCT RH	SERVICEABLE	153.80	-
1	FRT FENDER RH	TO REPAIR SEE LABOUR	588.80	-
1	FRT FENDER RETAINER BRACKET RH	NECESSARY	41.40	41.40
1	EMBLEM-BLUE DRIVE RH	NECESSARY	26.60	26.60
	LESS 20% DISCOUNT		-1,067.78	-729.40
			<b>4,271.12</b>	<b>2,917.60</b>
<b><u>LABOUR</u></b>				
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRT FENDER RH.		1,050.00	700.00
	SPRAY PAINTING CHARGE.		600.00	500.00
	CHECK ALL LIGHTING.		60.00	20.00
			<b>1,710.00</b>	<b>1,220.00</b>
<b>GRAND TOTAL</b>			<b>5,981.12</b>	<b>4,137.60</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>				<b>3,300.00</b>

Report Ref No. NS/INC22001896/Vty3n2



**THEVAN THOMAS KARTHIKESAVAN**



**K.K.LAU CPT(RET)**

**BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE**

**REGD Auto Consultant-SAE, Licensed Appraiser**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.**

**No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.**