

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22001898/AQY3E2

Date: 24/06/2022

REFERENCE

Insured/Claimant:	CHAUDHARI AJAY ASHOK	Policy No:	7210004265	
Date of Loss:	24/02/2022	Nature of Claim:	OD	Claim No: 6011294778SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMX8267P	Engine No:	DEM025744
Make & Model:	AUDI A5, 2.0 SPORTBACK (A)	Chassis No:	WAUZZZF53MA004285
Reg. Date:	30/01/2021 (Man. Year: 2020)	Odometer:	20787 km
Colour:	Grey		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$178,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,304.00	10,854.48	10,449.52	49.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,992.00	3,542.00	3,450.00	49.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	28,296.00	14,396.48	13,899.52	49.12
- Excess (S\$)	800.00	800.00	0.00	0.00
(S\$)	27,496.00	13,596.48	13,899.52	50.55
+ GST 7.00/7.00% (S\$)	1,924.72	951.75	972.97	50.55
Nett Amount (S\$)	29,420.72	14,548.23	14,872.49	50.55

INSPECTION

Date of Assignment:	01/03/2022		
Date Inspected:	28/02/2022	Inspected At:	24 Benoi Sector Repairer: Premium Automobiles Pte Ltd
Estimated Period of Repair:	5.0 days		

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,493.00 FS	*1,994.40 FS
2	2		*FRONT BUMPER SECURING STRIP	Not Necessary	79.00 FS	*- FS
3	1		*FRONT BUMPER GRILLE - CENTER	Not Necessary	219.00 FS	*- FS
4	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	Torn	293.00 FS	*234.00 FS
5	1		*FRONT BUMPER AIR GUIDE - RH	Not Necessary	72.00 FS	*- FS
6	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	293.00 FS	*- FS
7	1		*FRONT BUMPER AIR GUIDE GRILLE - RH	Cut	151.00 FS	*120.40 FS
8	1		*FRONT BUMPER TRIM - RH	Not Necessary	54.00 FS	*- FS
9	1		*FRONT BUMPER TRIM - CENTER	Not Necessary	127.00 FS	*- FS
10	1		*RADIATOR GRILLE	Not Necessary	1,881.00 FS	*- FS
11	1		*FRONT BUMPER GUIDE SECTION - RH	Damaged	41.00 FS	*32.24 FS
12	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	163.00 FS	*- FS
13	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	899.00 FS	*- FS
14	1		*FRONT BUMPER TOP COVER	Not Necessary	143.00 FS	*- FS
15	1		*CAUTION STICKER	Not Necessary	16.00 FS	*- FS
16	1		*AIR CON STICKER	Not Necessary	9.00 FS	*- FS
17	1		*FRONT BUMPER LOCK CARRIER BRACKET	Not Necessary	154.00 FS	*- FS
18	2		*FRONT BUMPER SUPPORT - LH / RH	Not Necessary	64.00 FS	*- FS
19	4		*POP RIVET	Not Necessary	4.00 FS	*- FS
20	1		*FRONT PARKING AID SENSOR - OUTER	Not Necessary	244.00 FS	*- FS
21	4		*FRONT PARKING AID SENSOR SEAL RING	Not Necessary	13.00 FS	*- FS
22	1		*FRONT PARKING AID SENSOR SIDE	Not Necessary	244.00 FS	*- FS
23	1		*FRONT FENDER - RH	Distorted	1,189.00 FS	*951.20 FS
24	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	55.00 FS	*- FS
25	1		*FRONT FENDER CLOSING ELEMENT - RH	Distorted	83.00 FS	*65.84 FS
26	1		*FRONT FENDER BRACKET - RH	Not Necessary	41.00 FS	*- FS
27	5		*POP RIVET	Not Necessary	19.00 FS	*- FS
28	1		*FRONT FENDER BRACKET - CENTER RH	Not Necessary	55.00 FS	*- FS
29	1		*FRONT FENDER BRACKET - END RH	Not Necessary	40.00 FS	*- FS
30	1		*FRONT FENDER BRACE - RH	Bent	132.00 FS	*105.20 FS
31	1		*FRONT FENDER TRIM - RH	Necessary	171.00 FS	*136.40 FS
32	1		*FRONT WHEEL HOUSING LINER - RH	Deformed	299.00 FS	*238.80 FS
33	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	176.00 FS	*- FS
34	1		*FRONT WHEEL SPOILER - RH	Torn	82.00 FS	*65.12 FS
35	1		*FRONT WHEEL SPOILER LOWER - RH	Not Necessary	40.00 FS	*- FS
36	1		*HEADLIGHT MATRIX BEAM - RH	Cut	8,172.00 FS	*6,537.60 FS
37	1		*HEADLIGHT HOSE	Not Necessary	42.00 FS	*- FS
38	1		*LIFT CYLINDER - RH	Not Necessary	217.00 FS	*- FS
39	1		*LIFT CYLINDER BRACKET - RH	Not Necessary	17.00 FS	*- FS
40	1		*LIFT CYLINDER CORRUGATED PIPE	Not Necessary	107.00 FS	*- FS
41	1		*FRONT FENDER LEDGE COVER LONG - RH	Not Necessary	40.00 FS	*- FS
42	1		*FRONT FENDER LEDGE COVER SHORT - RH	Not Necessary	18.00 FS	*- FS
43	1		*HEADLAMPS COVER - RH	Not Necessary	49.00 FS	*- FS
44	1		*ALUMINIUM RIM	Not Necessary	1,889.00 FS	*- FS
45	4		*RUBBER VALVE	Not Necessary	15.00 FS	*- FS
46	1		*FRONT NO PLATE	Not Necessary	60.00 FS	*- FS
47	1		*RHS FRONT TYRE	Cut	340.00 FS	*340.00 FS
48	1		*SUNDRIES	Necessary	300.00 FS	*33.28 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **21,304.00** **10,854.48**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	400.00	250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,400.00	1,000.00
4	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER AND BONNET	New	3,000.00	1,100.00
5	TO RENEW RHS FRONT RIM WITH TYRE. TO CARRY OUT PRE/POST WHEEL ALIGNMENT	New	520.00	520.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			6,992.00	3,542.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >