

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22001905/AQCE2

Date: 27/06/2022

REFERENCE

Insured/Claimant:	TAN KOK KIONG ANDREW	Policy No:	2100390817	
Date of Loss:	25/02/2022	Nature of Claim:	OD	Claim No: 4552035347SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDS6826Y		
Make & Model:	AUDI A6, 2.0 TFSI MU (A)	Engine No:	CDN410156
Reg. Date:	31/10/2014 (Man. Year: 2014)	Chassis No:	WAUZZZ4G5EN154896
Colour:	Black	Odometer:	70081 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$61,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R17	Rear Tyre Size:	225/55 R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	34,034.00	10,336.40	23,697.60	69.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,472.00	2,772.00	7,700.00	73.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	44,506.00	13,108.40	31,397.60	70.55
- Excess (S\$)	400.00	400.00	0.00	0.00
(S\$)	44,106.00	12,708.40	31,397.60	71.19
+ GST 7.00/7.00% (S\$)	3,087.42	889.59	2,197.83	71.19
Nett Amount (S\$)	47,193.42	13,597.99	33,595.43	71.19

INSPECTION

Date of Assignment:	01/03/2022		
Date Inspected:	28/02/2022	Inspected At:	24 Benoi Sector Repairer: Premium Automobiles Pte Ltd
Estimated Period of Repair:	4.0 days		

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	3,012.00 FS	*2,409.60 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	287.00 FS	*- FS
3	1		*FRONT BUMPER CLOSING ELEMENT	Not Necessary	212.00 FS	*- FS
4	1		*FRONT BUMPER SPOILER	Not Necessary	276.00 FS	*- FS
5	1		*FRONT BUMPER TRIM COVER	Not Necessary	111.00 FS	*- FS
6	1		*SET FRONT BUMPER END CAP	Not Necessary	160.00 FS	*- FS
7	1		*RADIATOR GRILLE	Smashed	1,478.00 FS	*1,182.40 FS
8	1		*RADIATOR GRILLE CENTER COVER	Distorted	41.00 FS	*32.24 FS
9	2		*FRONT BUMPER AIR GUIDE GRILLE - LH / RH	Not Necessary	342.00 FS	*- FS
10	1		*FRONT BUMPER END CAP - LH	Not Necessary	44.00 FS	*- FS
11	1		*FRONT BUMPER FOAM FILLER PIECE	Cracked	111.00 FS	*88.80 FS
12	1		*FRONT BUMPER REINFORCEMENT BEAM	Bent	927.00 FS	*741.20 FS
13	2		*FRONT BUMPER BRACKET HOLDER - LH / RH	Not Necessary	582.00 FS	*- FS
14	2		*FRONT BUMPER BRACE - LH / RH	Not Necessary	68.00 FS	*- FS
15	4		*POP RIVET	Not Necessary	4.00 FS	*- FS
16	2		*FRONT BUMPER SUPPORT - LH / RH	Not Necessary	29.00 FS	*- FS
17	2		*FRONT BUMPER GUIDE PIECE - LH / RH	Not Necessary	84.00 FS	*- FS
18	1		*FRONT BUMPER TOP COVER	Cracked	137.00 FS	*109.60 FS
19	1		*CAUTION STICKER	Necessary	16.00 FS	*12.40 FS
20	1		*AIR COND STICKER	Necessary	34.00 FS	*26.96 FS
21	2		*FRONT PARKING AID SENSOR	Not Necessary	488.00 FS	*- FS
22	4		*FRONT PARKING AID SENSOR SEAL RING - INNER / OUTER	Not Necessary	6.00 FS	*- FS
23	1		*SET FRONT BUMPER WIRING	Not Necessary	642.00 FS	*- FS
24	2		*HORN - LH / RH	Not Necessary	502.00 FS	*- FS
25	2		*HORN BRACKET - LH / RH	Not Necessary	102.00 FS	*- FS
26	1		*BONNET	Not Necessary	5,736.00 FS	*- FS
27	1		*BONNET ATTACHMENT PARTS	Not Necessary	150.00 FS	*- FS
28	1		*BONNET LOCK BAR	Not Necessary	56.00 FS	*- FS
29	1		*BONNET LOCK MICRO - SWITCH	Not Necessary	228.00 FS	*- FS
30	1		*BONNET BOWDEN CABLE COVER	Not Necessary	4.00 FS	*- FS
31	1		*BONNET BOWDEN CABLE - CENTER	Not Necessary	64.00 FS	*- FS
32	1		*BONNET RELEASE CABLE COVER	Not Necessary	11.00 FS	*- FS
33	1		*BONNET CATCH HOOK - LOWER	Not Necessary	20.00 FS	*- FS
34	1		*BONNET CATCH HOOK - UPPER	Not Necessary	155.00 FS	*- FS
35	1		*BONNET LOCK CABLE	Not Necessary	82.00 FS	*- FS
36	2		*FRONT WHEEL HOUSING LINER - LH / RH	Not Necessary	620.00 FS	*- FS
37	2		*FRONT WHEEL SPOILER - LH / RH	Not Necessary	588.00 FS	*- FS
38	2		*HEADLIGHT MOUNTING - LH / RH	Not Necessary	264.00 FS	*- FS
39	2		*HEADLIGHT - LH / RH	N/S Cut / O/S Cracked	7,066.00 FS	*5,652.80 FS
40	2		*LIFT CYLINDER - LH / RH	Not Necessary	518.00 FS	*- FS
41	2		*HEADLIGHT WASHER ASSY COVER CAP - LH / RH	Not Necessary	128.00 FS	*- FS
42	1		*HEADLIGHT HOSE	Not Necessary	43.00 FS	*- FS
43	1		*LOCK CARRIER	Not Necessary	1,385.00 FS	*- FS
44	2		*LOCK CARRIER BRACKET - LH / RH	Not Necessary	83.00 FS	*- FS
45	1		*A/C CONDENSER	Not Necessary	829.00 FS	*- FS
46	1		*REFRIGERANT HOSE	Not Necessary	286.00 FS	*- FS
47	1		*REFRIGERANT HOSE	Not Necessary	286.00 FS	*- FS
48	1		*PRESSURE SENDER	Not Necessary	206.00 FS	*- FS
49	2		*HIGH PRESSURE SWITCH	Not Necessary	104.00 FS	*- FS
50	1		*OUTSIDE TEMPERATURE SENSOR BRACKET	Necessary	26.00 FS	*20.40 FS
51	1		*CHARGE AIR COOLER	Not Necessary	628.00 FS	*- FS
52	1		*PULSATION DAMPER	Not Necessary	88.00 FS	*- FS
53	1		*PRESSURE HOSE	Not Necessary	76.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
54	1		*RADIATOR	Not Necessary	804.00 FS	*- FS
55	1		*RADIATOR TWIN FAN RING	Not Necessary	288.00 FS	*- FS
56	1		*RADIATOR FAN - LH	Not Necessary	880.00 FS	*- FS
57	1		*RADIATOR FAN - RH	Not Necessary	781.00 FS	*- FS
58	1		*RADIATOR FAN CONTROL UNIT	Not Necessary	842.00 FS	*- FS
59	6		*RADIATOR COOLANT	Not Necessary	282.00 FS	*- FS
60	2		*RADIATOR AIR GUIDE - LH / RH	Not Necessary	194.00 FS	*- FS
61	1		*RADIATOR GRILLE AIR GUIDE - UPPER	Not Necessary	32.00 FS	*- FS
62	1		*RADIATOR GRILLE AIR GUIDE - LOWER	Not Necessary	25.00 FS	*- FS
63	1		*AIR INTAKE HOSE	Not Necessary	31.00 FS	*- FS
64	1		*INTAKE AIR GUIDE	Not Necessary	90.00 FS	*- FS
65	1		*FRONT NO PLATE	Dented	60.00 FS	*60.00 FS
66	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 34,034.00 10,336.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER BOTH HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	800.00	500.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND BOTH HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	4,800.00	500.00
4	TO RESPRAY FRONT BUMPER AND BONNET	New	2,500.00	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
6	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT PRESSURISE, VACUUM AND REGAS	New	1,700.00	0.00
Gross Labour Cost (\$\$)			10,472.00	2,772.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >