

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC3/AIG22001906/RPA3Q2**Date:** 18/10/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210004265
<b>Claimant Vehicle No :</b>	SHB1138A	<b>Insured Vehicle No :</b>	SMX8267P
Date of Loss:	24/02/2022	Nature of Claim:	TP
		Claim No:	6011294778SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SHB1138A</b>	Engine No:	HIDDEN
Make & Model:	M.G. MG5, EV EXCLUSIVE (M)	Chassis No:	LSJE24037MG051332
Reg. Date:	30/08/2021 (Man. Year: 2021)	Odometer:	28758 km
Colour:	Green		
Engine Capacity:	0 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	8,416.33	4,153.02	4,263.31	50.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,144.00	1,920.00	4,224.00	68.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>14,560.33</b>	<b>6,073.02</b>	<b>8,487.31</b>	<b>58.29</b>
<b>+ Loss of Use (9.0 x S\$50.00/day) (S\$)</b>		450.00		
<b>+ Car Rental (9.0 x S\$105.93/day) (S\$)</b>		953.37		
<b>+ Doc/Search Fee (S\$)</b>		7.00		
<b>Nett Liability (S\$)</b>		<b>7,483.39</b>		
<b>Global Sum Settlement (S\$)</b>		<b>7,480.00</b>		

INSPECTION

Date of Assignment:	28/02/2022	
Date Inspected:	28/02/2022 Inspected At:	Strides Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705
Estimated Period of Repair:	6.0 days	

**Adjuster:** MOHD RASUL**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*DOOR ASM -FRT SI-L (DISC 10%)	Necessary	2,338.76 F	*2,104.88 F
2	1		*DOOR ASM-RR SI-L (DISC 10%)	Bent	2,185.04 F	*1,966.54 F
3	1		*STICKER ELECTRIC (LOGO) (SN)	Necessary	21.60 F	*21.60 F
4	1		*STICKER STRIDES TAXI (DOOR) (SN)	Necessary	60.00 F	*60.00 F
5	1		*REGULATOR ASM-RR S/D WDO-L	Not Necessary	265.30 F	*- F
6	1		*REGULATOR ASM -FRT S/D WDO-L	Not Necessary	324.06 F	*- F
7	1		*MOTOR ASM-FRT S/D WDO REG-L	Not Necessary	169.00 F	*- F
8	1		*HINGE ASM-RR S/D LWR/L	Not Necessary	47.22 F	*- F
9	1		*HINGE ASM-RR S/D UPR/L	Not Necessary	46.90 F	*- F
10	1		*MOTOR ASM -RR S/D WDO REG-L	Not Necessary	169.00 F	*- F
11	1		*LATCH ASM-FRT S/D -L	Not Necessary	156.84 F	*- F
12	1		*LATCH ASM-RR S/D -L	Not Necessary	139.98 F	*- F
13	1		*TYRE	Not Necessary	126.74 F	*- F
14	1		*WHEEL	Repair	618.07 F	*- F
15	1		*PANEL -BODY SI OTR-L	Repair	1,747.82 F	*- F
F=Franchise part.						
Total Parts (\$\$)					8,416.33	4,153.02

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING & BODY WORK	New	3,600.00	750.00
2	SPRAY PAINT	New	1,284.00	660.00
3	TO DO WHEEL ALIGNMENT /TYRE BALANCING	New	120.00	50.00
4	TO WASH AND VACUUM	New	60.00	0.00
5	TO APPLY RUST-PROOFING ON AFFECTED AREA	New	120.00	40.00
6	TO REPLACE SUNDRY PARTS	New	100.00	0.00
7	TO CHECK WIRING AND SYSTEM FUNCTION	New	120.00	0.00
8	TO TRANSFER DOOR MECHANISM	New	120.00	120.00
9	TO REMOVE & REFIT REAR QUARTER GLASS LH	New	120.00	0.00
10	TO CHECK & RESET SYSTEM FUNCTION	New	350.00	150.00
11	ISOLATED OF (EV)	New	150.00	150.00
<b>Gross Labour Cost (\$\$)</b>			<b>6,144.00</b>	<b>1,920.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >