

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22001909/UVY3N2**Date:** 23/03/2022**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNA00130842103

**Claimant Vehicle
No :** SGF9190K**Insured Vehicle
No :** GBG8017P

Date of Loss: 28/02/2022

Nature of Claim: TP

Claim
No: SNM22D201452/C02/LEEPG**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SGF9190K**

Make & Model: MERCEDES-BENZ C180, 1.6 (A)

Engine No: 27491030129153

Reg. Date: 27/02/2014 (Man. Year: 2013)

Chassis No: WDD2040312A926112

Colour: White

Odometer: 57585 km

Engine Capacity: 1595 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45ZR17

Rear Tyre Size: 225/45ZR17

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,176.50	7,318.50	3,858.00	34.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,420.00	2,540.00	880.00	25.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,596.50	9,858.50	4,738.00	32.46
Approved Total (Overridden) (S\$)		7,850.00		
(S\$)	14,596.50	7,850.00	6,746.50	46.22
+ GST 7.00/7.00% (S\$)	1,021.76	549.50	472.26	46.22
Nett Amount (S\$)	15,618.26	8,399.50	7,218.76	46.22

INSPECTION

Date of Assignment: 02/03/2022

Date Inspected: 01/03/2022

Inspected At:

Progressive Car Care Pte Ltd (HQ)
Blk 3022A Ubi Road 1, #01-45/46
Singapore 408716

Estimated Period of Repair: 6.0 days

Adjuster: MARCUS CHUA**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Mar 2022)
Parts:	143	MERCEDES-BENZ C180 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGF9190K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	1,485.00 FL	*1,485.00 FL
2	1		*SET REAR BUMPER CLIPS	Necessary	70.00 FL	*70.00 FL
3	1		*REAR BUMPER LOWER GARNISH	Not fitted	215.00 FL	*- FL
4	1		*REAR BUMPER FOAM	Not fitted	165.00 FL	*- FL
5	1		*REAR BUMPER REINFORCEMENT	Distorted	720.00 FL	*720.00 FL
6	2		*REAR BUMPER INNER FRAME-LH/RH	Not Necessary	172.00 FL	*- FL
7	2		*REAR BUMPER SIDE HOLDER-LH/RH	Bent	92.00 FL	*92.00 FL
8	2		*REAR BUMPER CHROME-LH/RH	Cracked	310.00 FL	*310.00 FL
9	1		*REAR PANEL	Badly Dented	1,478.00 FL	*1,478.00 FL
10	1		*REAR PANEL TOP GARNISH	Not Necessary	172.00 FL	*- FL
11	1		*REAR SPARE TYRE FLOOR PANEL	Not Necessary	322.00 FL	*- FL
12	1		*REAR BOOT	Buckled	1,898.00 FL	*1,898.00 FL
13	1		*REAR BOOT TOP LOCK	Bent	305.00 FL	*305.00 FL
14	1		*REAR BOOT BOTTOM LOCK	Not Necessary	26.00 FL	*- FL
15	1		*REAR BOOT RUBBER	Twisted	198.00 FL	*198.00 FL
16	1		*REAR BOOT MER LOGO	Necessary	57.00 FL	*57.00 FL
17	1		*REAR BOOT C180 LOGO	Necessary	96.00 FL	*96.00 FL
18	1		*REAR BOOT TRONIC LOGO	Necessary	80.00 FL	*80.00 FL
19	2		*REAR BOOT HINGES-LH/RH	Repair	1,268.00 FL	*- FL
20	2		*FRONT HEAD REST-LH/RH	Serviceable	1,060.00 FL	*- FL
21	1		*TAIL LAMP ASSY-LH/RH	O/s Broken/N/s Not Necessary	1,440.00 FL	*720.00 FL
22	2		*TAIL LAMP SIDE GARNISH-LH/RH	Torn	70.00 FL	*70.00 FL
23	1		*REAR BOOT OUTER CHROME	Cracked	236.00 FL	*236.00 FL
24	1		*SET REAR NUMBER PLATE WITH CASING	Bent	35.00 FS	*35.00 FS
25	1		*SET REAR BUMPER SENSOR (4 PCS)	Shorted	400.00 FS	*250.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,370.00	8,100.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,193.50	781.50
Total Parts (\$\$)	11,176.50	7,318.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK OUT DENTS,REAR BOOT,REAR PANEL,REAR SPARE TYRE FLOOR PANEL,REMOVE,REPLACE ACCIDENT PARTS	New	1,200.00	900.00
2	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	1,200.00	1,080.00
3	TO CHECK WIRING	New	50.00	20.00
4	TO REMOVE,REPLACE REAR BUMPER SENSOR	New	100.00	50.00
5	TO TUFF-KOTE	New	120.00	60.00
6	TO REMOVE,REFIX REAR GARNISH	New	150.00	80.00
7	TO REMOVE,REPLACE HEAD REST AND REFIT RELATED PARTS	New	400.00	250.00
8	TO RESET AIRBAG LIGHT	New	200.00	100.00
Gross Labour Cost (\$\$)			3,420.00	2,540.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >