



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 3379C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRT RH FENDER	BENT	588.80	588.80
1	FRT RH FENDER EMBLEM	NECESSARY	26.60	26.60
1	FRT BUMPER ASSY	DEFORMED	430.90	430.90
10	FRT BUMPER ASSY CLIPS	NECESSARY	22.00	2.20
1	HEADLAMP ASSY RH	NOT NECESSARY	1,993.65	-
1	FRT RH DAY LIGHT ASSY	NOT NECESSARY	642.50	-
1	FRT RH DAY LIGHT GRILLE	CRACKED	93.45	93.45
1	FRT RH FENDER RETAINER	NOT NECESSARY	41.40	-
1	FRT BUMPER BRACKET RH	NOT NECESSARY	35.00	-
1	FRT RH WHEEL CAP	CUT	346.40	346.40
	LESS 20% DISCOUNT		-844.14	-297.67
			3,376.56	1,190.68
	<u>LABOUR</u>			
	OD/TP CASE (INSURER) .		11.00	11.00
	PANEL BEATING.		800.00	525.00
	SPRAYPAINT.		600.00	500.00
	CHECK WIRING.		50.00	30.00
	TUFF KOTE.		50.00	30.00
	TOWING FEE.		60.00	60.00
			1,571.00	1,156.00
	GRAND TOTAL		4,947.56	2,346.68
	RECOMMENDED COST OF REPAIRS			2,346.68

Report Ref No. CS/QW22001912/Tvce2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.